Office	State of New Me	exico		Form C-103	
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources			Revised August 1, 2011	
1625 N French Dr , Hobbs, NM 88240			WELL API NO.		
<u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION		30-015-27946		
811 S First St , Artesia, NM 88210 District III – (505) 334-6178			5. Indicate Type	of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE	FEE	
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & G	as Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM					
87505					
	CES AND REPORTS ON WELLS			or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			East Shugart Unit		
PROPOSALS.)					
1. Type of Well: Oil Well Gas Well X Other		8. Well Number	# 52		
2. Name of Operator			9. OGRID Number		
Americo Energy Resources, LLC.			J. OGRID Rumi	oe:	
3. Address of Operator			10. Pool name or Wildcat		
7575 San Felipe STE 200 Houston TX 77063					
4. Well Location					
Unit Letter: B: 330'	feet from the FNL line	and 2230' feet fro	m the FEL 1	ine	
Section 35	Township 18S	Range	31E NMPM	County EDDY	
	11. Elevation (Show whether DR			1	
	GL 3646'	i, 1111), 111, O11, cic	·/		
	32 30 10				
40 01 1 4			~	_	
12. Check A	ppropriate Box to Indicate N	Nature of Notice,	, Report or Other	· Data	
NOTICE OF IN	TENTION TO	0.115	NOTOLIENT DE	COOT OF	
			BSEQUENT <u>R</u> E		
PERFORM REMEDIAL WORK X_				ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	ILLING OPNS.	P AND A		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN			IT JOB 🔲		
DOWNHOLE COMMINGLE					
OTHER:		OTHER:		<u>. </u>	
	eted operations. (Clearly state all				
	rk). SEE RULE 19.15.7.14 NMA	C. For Multiple Co	mpletions: Attach	wellbore diagram of	
proposed completion or reco	mpletion.				
Move in equipment on 4/22/2012. Rig	g up and perform a flow back of 3	00 to 400 bbls prod	luced water to clean	up casing, perforations and	
near well bore. Then treat the current	set of perforations with 1500 gall	ons of 15% NEFE a	ncid. Leave well shu	it in for 24 hours. Return	
well to active injection after clean up			***		
				RECEIVED	
			1	IECEIVED	
			1	ADD	
				APR 20 2012	
Spud Date:	Rig Release D	ate:	1		
			INN	OCD ARTESIA	
				- OIA	
I hereby certify that the information a	have is true and complete to the h	est of my knowledg	re and halief		
Thereby certify that the information a	To ve is true and complete to the b	cst of my knowledg	ge and belief.		
SIGNATURE ()	TITLE: Open	ations Manager	DA	TE 4/19/2012	
SIGNATURE C	TITLE. Opera	mons Manager	D.P.	ATE 4/18/2012	
Type or print name: E-mail address:	glann hartrand@amariaaanara	com DUONE, 712	084 0700	•	
For State Use Only	A A	COIII FRONE: /13	-70 4- 7/UU		
For State Ose Only	\ \	11)		1 1	
APPROVED BY:	\mathcal{M} TITLE \mathcal{N}_{15}	THE)CA	ewison DA	TE 14/24 DAIS	
Conditions of Approval (if any):	IIILE (O.)	7	DF	TID O LO LOUID	
Conditions of Approval (It ally).				* /	