Submit I Copy To Appropriate District Office	Office District I – (575) 393-6161 Energy, Minerals and Natural Resources District II – (575) 748-1283 BITS First St., Artesia, NM 88210 DISTRICT OF TWO MACKETS AND STATE OF THE MINERAL OF THE MACKETS AND STATE OF THE MA		Form C-103	
<u>District I</u> – (575) 393-6161 1625 N. French Dr. Hobbs, NM 88240			Revised August 1, 2011 WELL API NO.	
District II ~ (575) 748-1283			30-015-39842	
District III - (505) 334-6178			5. Indicate Type of STATE	Lease ☐
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas I	
1220 S. St Francis Dr , Santa Fe, NM				
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			PATTON 5 FEE	
PROPOSALS)			8. Well Number	4H
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator			9. OGRID Number	
COG Operating, LLC			229137	
3. Address of Operator 550 W. Texas Ave., Suite 100, Midland, TX 79701			10. Pool name or Wildcat Atoka;Glorieta-Yeso	
4. Well Location				
Unit Letter <u>E</u> :	2310 feet from the North	line and235	feet from theW	<u>Vest</u> line
Section 5	Township 19S	Range 26E	NMPM	County Eddy
	11. Elevation (Show whether D.	<i>R, RKB, RT, GR, etc.</i> 8' GR)	
	330	o UK		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				LTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL			ILLING OPNS. P	AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB				
DOWNHOLE COMMINGLE	l			
OTHER: CHANGE CASING PRO		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
COG proposes to drill a 12 ¼" hole to 1200' w/ fresh water, run 9 5/8" 36# J-55 and cement to surface. Drill a 8 ¾" hole to 2273' MD				
and kick off and drill curve to 3023' MD. Drill a 7 7/8" lateral to new BHL @ 2750' TVD 7258' MD. Run a tapered string with 7" 26#				
L-80 from surface to 2273' & 5 1/2" 17# L-80 casing to TD with DV/ECP Combo Tool at 2273' and isolation packers in the open hole. Set isolation packers and ECP. Open DV Tool and cement from 2273' to surface.				
oct isolation packers and Ecr. Op	CH DV 1001 and coment from 2273	to surface.	RECEIV	/ED
			ILCEIV	
			MAY 07 2	012
			NMOCD AR	TECIA
			MINIOOD AR	ILOIA
C1D.4	D: D			7
Spud Date:	Rig Release I	Jate:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
The state of the s				
SIGNATURE TITLE Permitting Tech DATE 5/2/2012				
Type or print name Kelly J. Holly / E-mail address: kholly@concho.com PHONE: 432-685-4384				
For State Use Only				
APPROVED BY: / C. STURING TITLE GOODO(15T DATE 5/8/2012				
Conditions of Approval (if any):	11100		DATI	11