

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3480
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-00895
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Alamo Permian Resources, LLC		6. State Oil & Gas Lease No. B-7690
3. Address of Operator 415 W. Wall Street, Suite 500, Midland, TX 79701		7. Lease Name or Unit Agreement Name ARTESIA STATE UNIT
4. Well Location Unit Letter H : 1650 feet from the N line and 330 feet from the E line Section 14 Township 18S Range 27E NMPM County EDDY		8. Well Number 301
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 274841
		10. Pool name or Wildcat Artesia; Queen-Grayburg-San Andres

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: RETURN TO PRODUCTION ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

05/17/12

MIRU. POOH w/(20) 3/4" rods, (5) 5/8" rods & pump. ND WH, NU BOP. POOH w/(56) 2 3/8" jts, SN, 4' perf sub, 1jt, mud anchor & bull plug. Tag @ 1873.17'. SDFD.

05/18/12

RIH w/3/4" bit & 5 1/2" scraper, tag btm @ 1873', POOH. Test tbg. RIH w/2 3/8" bull plug, 1 mud jt, (1) 4' slotted sub, 1 SN, 1 endurance jt, & 55 jts 2 3/8" tbg. Test tbg 5000# below slips. Had 3 bad jts. ND BOP, NU WH. SN @ 1781'. SDFN.

05/21/12

RIH w/(50) 5/8" rods, (20) 3/4" rods & new pump. Checked pump action, good. HWO. RD.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tam Fulvi TITLE Regulatory Affairs Coordinator DATE 05/25/2012

Type or print name TOM FULVI E-mail address: tfulvi@alamoresources.com PHONE: 432.897.0673

APPROVED BY: [Signature] TITLE Dist. Representative DATE 05/30/2012

Conditions of Approval (if any):