Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No. NMLC-0029395A

SUNDRY NOTICES AND REPORTS ON WELLS

It use this form for proposals to drill or to re-enter and

Do not use this form for proposals to drill or to re-enter and Abandoned well. Use Form 3160-3 (APD) for such proposals

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.					7. If Unit of CA/Agr	eement, Name and/or No.	
1. Type of Well ☐ Gas Well ☐ Other			AUG 03		8. Well Name and No. TONY FEDERAL #39 <308738>		
2. Name of Operator APACHE CORPORATION <873>					9. API Well No. 30-015-40172		
303 VETERANS AIRRADE IN #3000		NMOCD AL No. (include al 18-1117 / 432-81	,	10. Field and Pool or Exploratory Area CEDAR LAKE; GLORIETA-YESO <96831>			
4. Location of Well (Footage, Sec., T., R., M., or Survey Descript 1115' FNL & 1455' FWL, UL: C, SEC 19, T17S, R31E			tion)		11. County or Parish, State EDDY COUNTY, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA						R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Comple	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Fa N Pi Pi	eepen acture Treat ew Construction lug and Abandon lug Back	Reclam Recomp Tempor Water I	olete rarily Abandon Disposal	Water Shut-Off Well Integrity Other DRILLING OPS: INTERMEDIATE CSG JOB	

13. Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directional or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attached the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Bond No: BLM-CO-1463

While drilling Apache Corporation's Tony Federal #39 (API no. 30-015-40172), lost circulation was encountered at 337' (9' below the 13-3/8" surface casing shoe set at 328'). LCM pills have not succeeded in restoring circulation, and the well is being dry drilled to the intermediate casing point at 3500'. Apache plans to run 8-5/8" casing at 3500' and cement it per the approved APD (with an increase of the lead slurry volume from 710 sx to 1370 sx and an increase of the tail slurry volume from 225 sx to 280 sx), but we believe it is likely that cement will not be raised (in the 8-5/8" casing x 11" hole annulus) past the lost circulation zone at 337'. We therefore propose and seek your approval to conduct a remedial cement job as follows:

REPORT CONTINUED ON PAGE 2.	Accepted for record				
14. I hereby certify that the foregoing is true and correct.			NMOCD		
Name (Printed/Typed) VICKI BROWN	Title	DRILLING TECH			
Signature Wickildrown 1	Date	7/26/2012	APPROVED		
THIS SPACE FOR FEDERA					
Approved by	Title		JUL 2 6 2012 Date/s/ Chris Walls		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon		е	BUREAU OF LAND MANAGEMEN CARLSBAD FIELD OFFICE		

Title 18 U>S.C. Section 1001 and Title 43 U S C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Tony Federal #39 – Inter Csg Job – pg. 2

- Wait on cement for six hours (after plug down time on the primary cement job).
 Establish injection through the bradenhead valve using the cement pump truck (if injection we will know the annulus is uncemented above the lost circulation and the statement of the statemen

- 5. Pump up to 300 sx Class C cement with 1% calcium chloride (weight 14.8 ppg, yield 1.34 cuft/sk) through the bradenhead valve (continue pumping until a low pressure squeeze is obtained; if a squeeze is not obtained, pump the entire 300 sx cement).
- 6. Close the bradenhead valve.
- 7. Wait on cement for six hours before cutting the 8-5/8" casing and nippling up BOPE.