
Submit 1 Copy To Appropriate District State of New Mo	exico	Form C-103	
Office Energy, Minerals and Natural District 1 - (575) 393-6161	ITAL RECEIVE	Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 OIL CONSEDIVATION	DIVISION 1 9 2012	ELL API NO. 30-015-20351	
811 S. First St., Artesia, NM 88210	DIVISION 13 2012	Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87	505 NMOCD ARTES		
<u>District IV</u> - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM		State Oil & Gas Lease No.	
87505	, , , , , , , , , , , , , , , , , , ,	B-1266	
SUNDRY NOTICES AND REPORTS ON WEL		Lease Name or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR F DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) I PROPOSALS.)		J. WEST COOP UNIT	
1. Type of Well: Oil Well X Gas Well Other	8.	Well Number #123	
2. Name of Operator	9.	OGRID Number	
COG OPERATING LLC	1.0	229137	
		. Pool name or Wildcat 1; 7RVS-QN-GB-GLORIETA-YESO 97558	
600 W. ILLINOIS AVE., MIDLAND, TEXAS 79701 4. Well Location	<u> </u>	7; /RVS-UN-GB-GLORIE:IA-IESU 9/536	
Unit Letter P : 660 feet from the SO	JIH line and 66	60 feet from the EAST line	
Section 21 Township 178	Range 29E N	MPM County EDDY	
11. Elevation (Show whether 3,55	DR, RKB, RT, GR, etc.) 2' - GR		
12. Check Appropriate Box to Indicate		ort, or Other Data	
The choose appropriate Bon to marcine	rature of rection, resp	ori, or onior batta	
NOTICE OF INTENTION TO:	SUBSE	QUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON X	REMEDIAL WORK	☐ ALTERING CASING ☐	
TEMPORARILY ABANDON	COMMENCE DRILLING	OPNS. P AND A	
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB		
DOWNHOLE COMMINGLE		Notify OCD 24 hrs. prior	
50VIII 1022 00IIIIII 1022		To any work done.	
OTHER:	OTHER:	io driy work done.	
13. Describe proposed or completed operations. (Clearly state all pe	<u> </u>	ertinent dates including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.			
1) SET 5-1/2" CIBP @ 5,700' (DRINKARD PERFS.); DUMP	BAIL 35' CMT. @ 5,700	'-5.665'.	
2) SET 5-1/2" CIBP @ 4,600' (BLINEBRY PERFS.); DUMP BAIL 35' CMT. @ 4,600'-4,565'.			
3) SET 5-1/2" CIBP @ 3,900' (PADDOCK PERFS.); PUMP A 60 SX. OMT. PLUG @ 3,900'-3,420' (T/GLOR. @ 3,864',			
5-1/2" DV TOOL @ 3,790' X 8-5/8" CSG.SHOE @ 3,500'). WOL T65 4) PUMP A 35 SX. CMT. PLUG @ 856'-595'(11-3/4" CSG.SHOE X B/SALT); WOC X TAG CMT. PLUG.			
4) Fump A 33 SA. CMI. Plous & 636 -395 (11-3/4" CSG. 5) PERF. X CIRC. TO SURF., FILLING ALL ANNULI, A 35			
6) DIG OUT X OUT OFF WELLHEAD 3' B.G.L.; WELD ON ST			
Spud Date: Rig Relea	ise Date:		
I hereby certify that the information above is true and complete to the	best of my knowledge an	d belief.	
SIGNATURE TIT	LEAGENT	DATE09/12/12	
	deyler@milagro-re	es.com	
~ 11	an address,	FRUNE 432.007.3033	
For State Use Only		9/. 10	
	TLE	DATE 7/12/201	
Conditions of Approval (if any):	Approval Granted providing is complete by 13/1	7/24/	
			

COG Operating LLC

Lease & Well # GJ West COOP Unit #123


SPUD - 11/20/70



COG Operating LLC

Lease & Well # GJ West COOP Unit #123

SPUD - 11/20/70



NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator:_	COG Operating LLC	
Well Name	& Number: G. J. Wost Coop Unit "	43
API #:	30-015-20351	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.

8. Cement Retainers may not be used.

- 9. Squeeze pressures not to exceed 500 psi., unless approval is given by NMOCD Plugging Supervisor.
- 10. Plugs may be combined after consulting with NMOCD P & A Supervisor.

11. Minimum WOC time for tag plugs will be 4 hrs.

DG

Date: 9/11/2012