Submit 1 Copy To Appropriate District Office District I - (575) 393-6161

Conditions of Approval (if any):

State of New Mexico Energy, Minerals and Natural Resources

Revised August 1, 2011 WELL API NO

Approval Cranted providing work DATE 10/9/2011
is complete by 1/9/2013

Form C-103

District II - (575) 748-1283	OIL CONSERVATION DIVISION	30-015-37135-25508					
811 S. First St., Artesia, NM 88210	1220 South St. Francis Dr.	5. Indicate Type of Lease					
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE 🛣 FEE 🗌					
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, INIVI 6/303	6. State Oil & Gas Lease No. E-7832					
SUNDRY NOTION	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:					
(DO NOT USE THIS FORM FOR PROPOSA	AMOCO STATE A						
PROPOSALS.)	TION FOR PERMIT" (FORM C-101) FOR SUCH						
_		8. Well Number					
1. Type of Well: Oil Well 🔀	Gas Well U Other	#002					
2. Name of Operator		9. OGRID Number					
COG OPERATING, LLC	ATTN: BRIAN MAJORINO	229137					
3. Address of Operator		10. Pool name or Wildcat					
600 W. ILLINOIS AVE., MII	IAND, TEXAS 79701	ARTESIA; QN. CRBG. S.A.					
4. Well Location							
Unit Letter A:	feet from the NORTH line and	1 978 feet from the EAST line					
Section 34	Township 178 Range 28E	NMPM County EDDY					
	11. Elevation (Show whether DR, RKB, RT, G 3,671.9' - GR	iR, etc.)					
and the second of the second o	3,011.3 GR	P 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK		PLUG AND ABANDON	X V	REMED!	AL WORK] .	ALTERIN	G CASING	; 🗀
TEMPORARILY ABANDON		CHANGE PLANS		СОММЕ	NCE DRILLING	OPNS.]	P AND A		
PULL OR ALTER CASING		MULTIPLE COMPL		CASING	CEMENT JOB]			
DOWNHOLE COMMINGLE					,	Notify (CD	24 hrs	. prior	
						To a	ny wo	ork do	ne.	
OTHER:				OTHER:	····			·		
13. Describe proposed or composed of starting any proposed opposed completion or re	work).	SEE RULE 19.15.7.14								
1) SET 5-1/2" CIBP @ 2) PUMP A 35 SX. CMT 3) MIX X CIRC. TO SUI 4) DIG OUT X CUT OFF	. PLUG RF. A	6 690'-455' (T/ANHY	7. X 8-1 100'-3	5/8" CSG '.	.SHOE); WOC X	TAG OMT.	PLUG.			
								RE	ECEI	VED
								C	OCT 04	2012
Spud Date:		R	ig Relea	se Date:		**************************************		NMC	OCD AF	TESIA
I hereby certify that the inform	ation a	bove is true and comple	te to the	best of m	y knowledge and	d belief.				
SIGNATURE		A. Zo	TIT	LE	ACENT	···	D.	ATE	09/28/12	<u>}</u>
Type or print name DAVID A.	EYLEF	· \	E-m		er@milagro-re		PI	HONE 43	32.687.30)33
1 . L										

	Location:]		235	€ 5	Well ID Info:	^
Footage.	C 24 T4TO DOOF				3 3	API No.	30-015-25508 UIL A
Section. Block:	S-34 T17S, R28E	{		333		Spud Date	12/12/1985
Survey				用	\$, S	443' FNL × 978' FEL
County	Eddy County, NM	}			S \$	Surf Csg:	12" HOLE; 8 5/8" 24# CSG
Unit:				333	2 5	Set @	505', CMTD
Pump Speed. KB.					X 24	Cement wi	350 sxs
KB Calc				2		Scirc.	
TQ Calc				图 制			
				學事			
History							
					の開発業を		
				The state of the s			
	•			E L			
					る。最後		
Directions						lm4-n @	
Directions					\$ 5	Inter Csg: Set @	
				4	は一番	Cement w/	
	Current			Z	7	circ.	
	Tubing Detail (top to bottom)				181	1	ζ,
Joints	Description	Footage	Depth	1 [8]	Žį.		
	KB		12	<u> </u>	12		
91	2-7/8"	2821 0	2,833 00	为	J.		
0			2,833 00 2,833 00		の変に組みると		
ö			2,833 00		<u> </u>		
0			2,833 00	[[]			
0			2,833.00	15	82		
0			2,833 00	44	12 (A) 12		
0	* · · · · · · · · · · · · · · · · ·		2,833.00 2,833.00	i i			
			2,000.00	劉	šń		
				io io	75.3 18.3		•
	Rod Detail (top to bottom)			رَيِّ ا	<i>*</i>		
Pumping Unit Rods	Weatherford 456-305-144 Description	Footage	Depth		ķ)		
0	Description	0.0	26		a,		
0		0	26		9		
0		0	26		3		
0		0	26	100	34		
			26	- P	龙		
					3		
				i ši	A.		
	"IF" NEW Tubing Detail (top to bottom)				不要である。 野人の海人の治を書から、朝の西田の間、		
Joints	Description	Footage	Depth) E	Ü		
105	КВ	12.0	12 12.00	#S	32		
1			12.00	Ğ			
2			12.00			San Andres ⁻ Perfs	, 2319-2820,
1			12.00				
36	<u> </u>		12.00 12.00				
			12.00		F		
1			12 00		E		
5			12.00	हरू गाउँ सामित्र सामित्र इ.स.च्या १ वर्षा	<u>_</u>		
	<u> </u>					Prod Csg:	5-1/2"CSG,15 5#/ft
	Rod Detail (top to bottom)			3	1	Set @	3082
oumping Unit	Weatherford 640-365-144 in 124" stroke					Cement wi	1000sxs
Rods 1	Description	Footage 26 0	Depth 26	[[]	jad ost	circ.	
- 1			26.00		1		
58			26.00	PBTD: 3068			
86			26.00	TD: 3090			
12			26.00	}			
			26.00	}			
- 1			26.00 26.00				
	L	L	40,00	1			

R. Crawford 9/18/2012

odated:

minutu siale A #2

Reservoir Artesia On Grog SA

Updated: R. Crawford 9/18/2012

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: <u>C.O. G. Operating</u>, <u>LLC</u>

Well Name & Number: <u>A moco 51ate A ** 002</u>

API #: 30.015-25508

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.

8. Cement Retainers may not be used.

- 9. Squeeze pressures not to exceed 500 psi., unless approval is given by NMOCD Plugging Supervisor.
- 10. Plugs may be combined after consulting with NMOCD P & A Supervisor.

11. Minimum WOC time for tag plugs will be 4 hrs.

DG

Date: 10/9/2012