Submit 1 Copy To Appropriate District Form C-103 State of New Mexico Revised August 1, 2011 Energy, Minerals and Natural Resources District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 30-015-32705 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 1220 South St. Francis Dr. STATE FEE X 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Juneau 31 Fee Com DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number 1. Type of Well: Oil Well X Gas Well Other RECEIVED 2. Name of Operator 9. OGRID Number BOPCO, L.P. 260737 3. Address of Operator P O Box 2760 Midland, Tx 79702 OCT **0 4** 2012 10. Pool name or Wildcat WildcatG-02 S212831L; Delaware NMOCD ARTESIA 4. Well Location Unit Letter P : 1980 feet from the South line and 660 feet from the West line Section 31 Township 21S **NMPM** Range 28E County Eddy 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERING CASING PERFORM REMEDIAL WORK □ PLUG AND ABANDON X REMEDIAL WORK **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. P AND A XPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. BOPCO, L.P. respectfully wishes to report the plugging of this well. 9-17-12: Notify Phil Hawkins, NMOCD and informed him of MIRU to plug well. 9-18-12: Tag cmt on BP @ 7780; drill out cmt. & CIBP @ 7790'. RIH and tag TOC @ 10,511 (139' above CIBP @ 10,650'). Circulate hole clean. 9-19-12: Run in hole w/5-1/2" Alpha CIBP @ 9306; CIBP sheared off. Did not set. Prepare to set CIBP in A.M. 9-20-12: RIH w/5-1/2" Alpha CIBP and set @ 9306'. Dump bail 111' "CL" H cmt. WOC and tag cmt @ 9195'. RIH w/5-1/2" Alpha CIBP and set @ 7774'; dump bail 35' "CL" H cmt. RIH w/5-1/2" Alpha CIBP and set @ 5528'; dump bail 35' CL H cmt on top. (Phil Hawkins on location - did not stay to witness). Prepare to tag cmt in A.M. 9-21-12: Tag PBTD @ 5490'. Obtain "Hot Work Permit" to weld Bell Nipples on 5-1/2" csg. Csg. Stuck @ 1725' - free @ 1700'; cut csg. @ 1700'. 9-23 thru 9-24-12: Shut down. Approved for plugging of well bore only. CONTINUED ON ATTACHED SHEET Liability under bond is retained pending receipt of Calda (Subsequent Report of Well Plugging) which may be found at OCD Web Hage under Spud Date: Rig Release Date: Forms, www.cmnrd.state.nm.us/ocd I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Sandia TITLE Sr. Regulatory Clerk DATE 10/04/2012 Type or print name Sandra J. Belt ext. 7379 PHONE: (432)683-22 E-mail address: sjbelt@basspet.com For State Use Only

APPROVED BY:
Conditions of Approval (if any):

TIT Approved for plugging of well hore only.

Liability under bend is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms, www.cmnrd.state.nm.us/ocd.

DATE 10/5/2012

Juneau 31 Fee Com #1 30-015-32705 Form C-103 Attachment Plugging Report 10.4.12

9-25-12: Spot 135 sx CL C w/2% CaCl2 from 2819-1625'. Circulate hole clean. Spot tbg @ 1450'. Tag PBTD @ 1640'. NMOCD representative Phil Hawkins on location. Land EOT @ 897'. Spot balance plug 135 sx CL C w/2% Ca Cl2 cmt plug 897-500'. EOT 473' circulate hole clean. WOC & tag plug in A.M.

9-26-12: Tag PBTD 495'. Spot 35 sx CL C from 113' to Surf. Dig out cellar and weld on cap w/P&A hole marker. Final report.

PLUG AND ABANDON

	: JUNEAU 31 FEE		lo.: <u>1</u>
	: EAST CARLSBAD (I		
		VL, SEC 31, T21S, R28E	
County	: EDDY	St: <u>NM</u>	API : <u>30-015-32705</u>
			KB: 3133'
			GL: 3116'
			Spud Date: 8/31/2003
			Compl. Date: 11/5/2003
Surface Csg.	,		Surface Plug 0' - 113' - 35 sxs Cl C cmt
Size:	13 3/8"		X : 562218.44
Wt	48#		Y : 521930.3
Grd.	J-55		Lat : 32.434738
Set @:	560'		Long : 104.131668
Sxs cmt:	500		
Circ:	Υ		Shoe/Salt Plug 495' - 897' - 135 sxs Cl C cmt, woc & TAG
TOC:	Surface		560' 13 3/8" Csg
Hole Size:	17 1/2"		Salt Section 615' - 840' (Mud Log)
Intermediate	e Csa.		
Size:	9 5/8"		Cut & Pull 5 1/2" csg @ 1700'
Wt	40#		T/Delaware 1740' (Mud log)
Grd	J-55		(Totalialo (Tito (Mar 183)
Set @:	2746'		Shoe/Del Plug 1640' - 2819' - 135 sxs Cl C cmt, WOC & TAG
Sxs Cmt:	650 sx		
Circ:	Y		2621' EST. TOC (CBL)
TOC:	Surface		202.
Hole Size:	12 1/4"	=	
. 1010 0120.			2746' 9 5/8" Csg
Production	Csg.		G
Size:	5 1/2"	_	
Wt	17#		
Grd	P110 & N80		LBC "Y" Plug-CIPB @ 5528' with 35' CI C cmt cap (tag @ 5490')
Set @:	12,232'		5578-5608 LBC "Y" 17 holes(8/19/2010)
Stage 1:	1000 sx		
Circ:	Y 80 sx	_	
Stage 2:	2100 sx		
Circ:	N		Bone Springs Plug - CIBP @ 7774' with 35' CI C cmt dump bailed
TOC:	2621 (CBL) 8 3/4"	_	7824-34' B Sprgs 30 holes (5/29/09)
Hole Size:	0 3/4		9256' DV Tool
			DV Tool Plug - CIBP @ 9306', w 111' CI H cmt cap (tag @ 9195
			10,511' Tagged Fill from DO of CIBP & cmt
			10650' CIBP w/ 35' cmt (5/28/2009))
		= =	10680-98 Strawn 37 Holes
		*	10792-98' 14 Holes
			11,713' Arrow ser Pkr (w/ 31' sd on top) & Blanking Plug 11858-68' Morrow 'B' 11/22/03 6 SPF (36 holes)
			12237' TD
			11. 1 . 1 . 401/2010
		DDTD:	Updated: 10/1/2012
		PBTD: 42.227	Author: crm
		TD: <u>12,237'</u>	Engr: CCC