	Submit 3 Copies To Appropriate District Office, District I	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 May 27, 2004		
,	1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
	<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-005-63689 5. Indicate Type of Lease		
	District III	1220 South St. Francis Dr.			FEE 🗍	
	1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, N	M 87505		6. State Oil & Gas Lease No.	
	1220 S. St. Francis Dr., Santa Fe, NM 87505			VO-5686		
	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Datil BFD State Com		
	PROPOSALS.) 1. Time of Well, Oil Well			8. Well Number	ile Com	
	1. Type of Well: Oil Well Gas Well Other		RECEIVED	1		
	2. Name of Operator	ut		9. OGRID Number	-	
ŀ	Yates Petroleum Corporation 3. Address of Operator		MAY 2 3 2005	025575 10. Pool name or Wildcat		
	105 S. 4 th Street, Artesia,	NM 88210	OOD-ARTESH	Undes. Foor Ranch		
+	4. Well Location					
	Unit Letter N:	660 feet from the	South line and	1980 feet from the	West line	
	Section 2	Township 9S	Range 26E	NMPM Chaves	County	
Print State	11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
3850'GR Pit or Below-grade Tank Application or Closure						
ı			inach water wall Di	stanas fuam nasmat sumface west		
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material						
L						
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ PLUG AND ABANDON PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT JOB ☐					RING CASING	
	TOLE ON ALTEN CASING	MOLTIFEE COMFE	CASING/CEWEN	11 JOB		
OTHER: OTHER: Add perfs and stimulate						
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.						
1/20/05 Squagge Silveion 6222' 6226' with 150 ov Class "II" with EL Squagged and to 2000#						
4/20/05 – Squeeze Silurian 6222'-6236' with 150 sx Class "H" with FL. Squeezed perfs to 2000#. 4/21/05 – Perforate Mississippian 6146'-6152' and 6198'-6206' with 56 holes.						
4/22/05 – Acidize Mississippian with 1500g 15% IC acid and 84 balls.						
	4/26/05 - Squeeze Mississippian with 150 sx Class "H" with FL. Squeezed formation to 2500#.					
	4/27/05 – Perforate Strawn 6072'-6092' (80) and 6096'-6122' (104).					
	4/28/05 – Acidize Strawn with 2300g 7-1/2% IC acid and 200 balls. 5/11/05 – Frac Strawn with 85,500g 55Q CO2 foam and 125K# of 20/40. ASI packer with 2.25" on/off tool at 6022'. Cement retainers					
	at 6140' and 6216'.					
7	hereby certify that the information	a shove is true and complete to	the heat of my Imagelade	and haliaf year are		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed pr closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.						
	SIGNATURE Liva L	· ·		rvisor DATE May 1		
]	Type or print name Tina Hue		ress: <u>tinah@ypcnm.c</u>	om Telephone No	Y 2 4 2000	
7	For State Use Only APPROVED BY: Conditions of Approval (if any):	R RECORDS ONLY	LE	DATE	B	
	- III					