Submit 3 Copies To Appropriate District	State	of New Mexico	Form C-103
Office District I	Energy, Miner	als and Natural Resource	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II	OIL CONSE	ERVATION DIVISION	30-015-26290
1301 W. Grand Ave., Artesia, NM 88210 District III		outh St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE 🖂
District IV	Santa	a Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			
87505			
	TCES AND REPORTS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			
PROPOSALS.)	CATION FOR PERMIT (I	FORM C-101) FOR SUCH	John AGU
1. Type of Well: Oil Well	Gas Well	Other	8. Well Number
		RECEIVEL	1
2. Name of Operator		TIEGETVEE	9. OGRID Number
Yates Petroleum Corporat	ion	MAY 1 7 2005	025575
3. Address of Operator			10. Pool name or Wildcat
105 S. 4 th Street, Artesia,	NM 88210	OCU-ARTERI	Wildcat Bone Spring
4. Well Location			
Unit Letter C:	660 feet from the	North line and	1980 feet from the West line
Section 14	Township	20S Range 24H	E NMPM Eddy County
Section 14			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3617'GR			
Pit or Below-grade Tank Application or Closure			
			District the second second
			Distance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank:	Volumebbls	s; Construction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
,	Trr		, F
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☑ REMEDIAL WORK ☐ ALTERING CASING ☐			
TEMPORARILY ABANDON	CHANGE PLANS	☐ COMMENCE	E DRILLING OPNS. PLUG AND ABANDON
PULL OR ALTER CASING	MULTIPLE COMPL	☐ CASING/CE	MENT JOB
OTHER:	·	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
Yates Petroleum Corporation plans	to plug and abandon th	is well as follows: Rig up s	afety equipment as needed. POOH with tubing.
Set a 7" CIBP at 2170' with 35' cement on top. Circulate plugging mud on top of CIBP. Pull tubing up to 1260' and spot 35 sx cement			
surface shoe plug. Tag plug. Pull tubing up to 60' and circulate cement to surface. Tag plug. Install dry hole marker and clean up			
location as per regulated.			
NOTE: Yates Petroleum Corporation	on will use steel pits an	id no earth pits	
		-	
			Notify OCD 24 hrs. prior to any work done
			Nothly GGD 27 !
I hereby certify that the information	above is true and com	plete to the best of my know	ledge and belief. I further certify that any pit or below-
grade tank has been/will be constructed or	closed according to NMO	CD guidelines 🔲, a general pern	nit or an (attached) alternative OCD-approved plan .
A ` \	1 1		
SIGNATURE TITLE Regulatory Compliance Supervisor DATE May 16, 2005			
_			
Type or print name Tina Huer	ta E-m	nail address: <u>tinah@ypcr</u>	<u>m.com</u> Telephone No. <u>505-748-1471</u>
\mathcal{N} . \mathcal{N} .			
For State Use Only	i. b.	_ TITLE Field du	· *
APPROVED BY:	wilins	_TITLE There gr	specter DATE 5/20/05
Conditions of Approval (if any):			