Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office District I	Energy, Minerals and Natural Resources		Revised May 08, 2003
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-33719 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE X FEE
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			VO-6442
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			TONKED ON THE
PROPOSALS.)			ZONKED STATE 8. Well Number
1. Type of Well: Oil Well Gas Well X		RECEIVED	o. Well Malliot
		JUN 0 9 2005	9. OGRID Number
2. Name of Operator MARBOB ENERGY CORPORA		DEAD+EOM	9. OGRID Number
3. Address of Operator	11011		10. Pool name or Wildcat
PO BOX 227, ARTESIA,	NM 88211-0227		CEMETERY; MORROW, SE (GAS)
4. Well Location			
Unit Letter J:_	1500 feet from the SOU	TH line and	1650 feet from the EAST line
J. J			
Section 2		Range 24E	NMPM County EDDY
	11. Elevation (Show whether D. 3780 GL	R, RKB, RT, GR, etc.,	
12 Check A	ppropriate Box to Indicate	Vature of Notice	Report or Other Data
NOTICE OF IN			SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	ILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AN	
	_		- 1966 - 1966 - 1966 - 1966 - 1966 - 1966 - 1966 - 1966 - 1966 - 1966 - 1966 - 1966 - 1966 - 1966 - 1966 - 196
OTHER: ADD ADDITION		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
MARBOB ENERGY CORPORATION PROPOSES TO ADD MIDDLE MORROW SAND PAY AS FOLLOWS:			
SET 10K COMPOSITE FRAC PLUG @ 10075'. PERF THE MIDDLE MORROW @			
9918' - 10015' (180 SHOTS). FLOW/SWAB TEST. ACIDIZE W/ 1500 GAL			
CLAY SAFE H ACID. SWAB/FLOW TEST.			
\sim			
I hereby certify that the information al	bove is true and complete to the l	est of my knowledge	e and belief.
SIGNATURE	Druggy_title_	PRODUCTION AN	NALYST DATE 6/8/05
Type or print napped DIANA	. BRIGGS	·	Telephone No. (505) 748-3303
(This space for State use)	W. Grem		JUN 1 3 2005
APPPROVED BY	TITLE_	<u> </u>	DATE
Conditions of approximate	7-4- Seglevi	esc .	