Form 3160-5 (April 2004)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

5. Lease Serial No.

## SUNDRY NOTICES AND REPORTS ON WELLS

OMB No. 1004-0135 Expires March 31, 2007

Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals.		INM-31099
		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instr	uctions on reverse side	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well	RECEIVED	
Oil Well X Gas Well Other	AUG 2 5 2005	8. Well Name and No.
2. Name of Operator	OCD-AFITEDIA	Horn Y.G Federal #4
Yates Petroleum Corporation		9. API Well No.
3a. Address 105 S. 4th Str., Artesia, NM 88210	3b. Phone No. (include area code) 505-748-1471	30-005-63680 10. Field and Pool, or Exploratory Area
103 3. 4th 3th, Artesia, NFF 00210	303 / 10 11/1	To. Meld and Pool, of Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)		Pecos Slope Abo
AZERIECL & CORPEL of Continue Z TOC DOCE (Unit L NECE)		11. County or Parish, State
1750'FSL & 660'FEL of Section 7-T8S-R26E (Unit		Chaves County, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OF SUBMISSION  TYPE OF ACTION		
TIPE OF SUBMISSION		
Acidize	Deepen Production	(Start/Resume) Water Shut-Off
Notice of Intent Alter Casing	Fracture Treat Reclamation	Well Integrity
X Casing Repair	New Construction X Recomplete	Other
Subsequent Report Change Plans	Plug and Abandon Temporarily	Abandon
Final Abandonment Notice Convert to Injection	X Plug Back Water Dispe	osal
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filled once testing has been completed. Final Abandonment Notices shall be filled only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  7/29/05 Set CIBP at 5650' and 5350' and cap with cement. Perforate Wolfcamp 5116'-5126' (60).  8/1/05 Acidize Wolfcamp with 1000g 7-1/2% IC acid and 90 balls.  8/3/05 Perforate Wolfcamp 4618'-4628' (40), 4658'-4666' (32) and 4704'-4714' (40). Set CIBP at 5100' with 35' cement.  8/4/05 Acidize Wolfcamp with 2800g 20% IC acid and 168 balls.  8/9/05 Set composite BP at 4600'. Perforate Abo 3962'-3970', 3998'-4004', 4092'-4100', 4118'-4126', 4160'-4172', 4198'-4200', 4203'-4208', 4234'-4242', 4258'-4262' and 4320'-4328' with a total of 79 holes.  8/10/05 Spotted 2500g 7-1/2% IC acid.  8/11/05 Frac Abo with 125,000g 33Q CO2 foam and 250K 20/40 Brown. ASI 10K packer with 2.25" on/off tool at 3914'.		
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Tina Huerta  Signature THIS SPACE	Title Regulatory Complia  Date August 24, 2005  FOR FEDERAL OR STATE OFFICE USE	ance Supervisor
Approved by	Title	Date ::
Conditions of approval, if any, are attached. Approval of this notice docertify that the applicant holds legal or equitable title to those rights in which would entitle the applicant to conduct operations thereon.	es not warrant or	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willbully to make to any department or agency of the United

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction