Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RECEIVED NOV 2 1 2012

FORM APPROVED OMB NO. 1004-0135

	xpires:		
Lease Serial	No.		

BUREAU OF LAND MANAGEMENT	10000	ARTESIA
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON	MENIZOD	Alticago.
Do not use this form for proposals to drill or to abandoned well. Use form 3160-3 (APD) for suc	re-enter an	
abandoned well. Ose lonii 3160-3 (APD) loi suc	n proposais.	

Do not use this form for proposals to drill or to re							
abandoned well. Use form 3160-3 (APD) for such p	oroposals. 6. If Indian, Allottee or Tribe Name						
SUBMIT IN TRIPLICATE - Other instructions on rev	7. If Unit or CA/Agreement, Name and/or No.						
1. Type of Well ☐ Gas Well ☐ Other	8. Well Name and No. WHITE STAR FEDERAL 25						
2. Name of Operator Contact: BRIAN MAIC COG OPERATING LLC E-Mail: bmaiorino@concho.com	9. API Well No. 30-015-32509						
3a. Address ONE CONCHO CENTER 600 W ILLINOIS AVENUE MIDLAND, TX 79701 3b. Phone No Ph: 432-22	. (include area code) 10. Field and Pool, or Exploratory EMPIRE;GLORIETA-YESO,EAST						
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish, and State						
Sec 29 T17S R29E NENW 890FNL 1650FWL	EDDY COUNTY, NM						
000 20 1170 11202 1121117 0007 112 10001 172							
12. CHECK APPROPRIATE BOX(ES) TO INDICATE	NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	pen Production (Start/Resume) Water Shut-Off						
Alter Casing	ture Treat Reclamation Well Integrity						
Subsequent Report Casing Repair New	Construction Recomplete Other						
☐ Final Abandonment Notice ☐ Change Plans ☐ Plug	and Abandon Temporarily Abandon						
Convert to Injection Plus	Back Water Disposal						
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) COG Opperating LLC respectfully request to deepen the White Star Federal 25. ACCEPTED for TECOTO Deepening Procedure 1. MIRU rig. 2. LD production equipment 3. Sqz upper Yeso w/ +/-400sx of Class C neat. 4. Drill out squeeze. Test squeeze to 300 psi for 20 minutes partitled FOR APPROVAL chart recorder 5. PU 4-3/4? bit and drill 4-3/4? from 4364? to 5760? NDITIONS OF APPROVAL 6. POOH w/ bit and drillstring. 7. RIH w/ logs and log from TD to 4300?. 8. RIH w/ 4?, 11.3# casing. See next attachment for general centralizer							
14. Thereby certify that the foregoing is true and correct. Electronic Submission #149436 verifie	d by the RLM Well Information System						
For COG OPERATING LI Committed to AFMSS for processing	.C, sent to the Carlsbad						
Name(Printed/Typed) BRIAN MAIORINO	Title AUTHORIZED REPRESENTATIVE						
Signature (Electronic Submission) Date 09/10/2012							
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By	Title Date						
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office						

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #149436 that would not fit on the form

32. Additional remarks, continued

program.

9. Cement casing from TD to 4289? w/ 115 sxs Class C cmt. Drop plug and open DV tool. Circ cmt off DV tool. Drop plug to close DV tool. 10. PU workstring and RIH and drill out DV tool. POOH and LD workstring. 11. RDMO rig.

Completion Procedure 1. MIRU rig.

2. RIH/ w/ perforating guns and perforate Yeso from 5150 ? 5350w/1spf, 28 holes.

plug at 5100'
4. RIH w/ perforating guns and perforate Yeso from 4850? ? 5050?.
5. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 179,800 # of sanglest ATTACHED FOR APPROVAL plug at 4800'
6. RIH w/ perforating guns and perforate Yeso from 4550? ? 4750?.
7. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 179,800 # of sand.
8. RIH and drill out plug at 4800? and 5100?.
9. RIH and cut or back off 43 area.

8. RIH and drill out plug at 4800? and 5100?.
9. RIH and cut or back off 4? casing at 4289?. POOH w/ 4? casing. Leave 4? liner from 4289? to 5750? (TD).
10. RIH w/ tog and locate end of tbg at 4200?.

11. RIH w/ rods and pump.

12. RDMO rig.

CONDITIONS OF APPROVAL

COG Operating LLC NMNM14840 White Star Federal 25 30-015-32509 Section 29, T. 17 S., R 29 E., NMPM Eddy County, New Mexico

- 1. Surface disturbance beyond the existing pad must have prior approval.
- 2. Closed loop system required.
- 3. H2S monitoring equipment should be onsite for personnel protection from surrounding oil operations. Operator should not encounter H2S while deepening.
- 4. 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 5. BOP to be tested to 1000 psi based on expected BHP
- 6. Variance for stand-off of less than 0.422" is approved due to NMOCD classifying the formations in this area as the Yeso group Pool 96610.
- 7. Variance for not testing seal also approved based on NMOCD classification of formations in this area as the Yeso group Pool 96610.
- 8. Variance approved for a minimum tie back of 100'. When plugged, cement plug will be required across this tie back and across squeezed perforations.
- 9. If cement does not circulate to DV tool, the appropriate BLM office is to be notified.
- 10. Test casing as per Onshore Order 2.III.B.1.h
- 11. Steel tanks to be used.
- 12. Work to be completed in 90 days
- 13. Subsequent sundry and completion report required when work is complete.

EGF 111912

1. Estimated Tops of Important Geologic Markers

+/- 4250' Yeso Group

2. Estimated Depths of Anticipated Fresh Water, Oil, and Gas

Yeso Group +/- 4250'

This deepening originates in the Yeso and will finish at the base of the Yeso. The entire Yeso group is an oil and gas bearing interval.

3. Casing Program

Hole Size	Interval	OD Casing	Weight	Grade**	Jt./Condition	Burst/collapse/tension	
4-3/4"	4405' – 6000'	4"	11.3#	L-80 or	ULT-FJ/New	3.98/4.09/3.21 (L80)	
				P-110		5.47/5.23/4.25 (P110)	

^{**} Due to casing shortages, either L-80 or P-110 will be run. The exact grade is unknown at time of requesting permit.

NOTE: COG OPERATING LLC REQUESTS A VARIANCE TO THE 0.422" STAND OFF RULE BETWEEN CASING AND WELLBORE.

4. Cement Program

Class C, 115 sxs, yield 1.37. 100' minimum tie back to production casing.

NOTE: COG OPERATING LLC REQUESTS A VARIANCE TO THE LINER TOP FLUID ENTRY OR PRESSURE TEST BECAUSE THE DEEPENED WELL WILL BE COMPLETED IN THE SAME ZONE AS THE CURRENT PERFS AND THE ENTIRE INTERVAL IS RECOGNIZED BY THE OCD AS ONE INTERVAL (YESO). AS PER ONSHORE ORDER NO. 2 SECT III: REQUIREMENTS, PART B. CASING AND CEMENTING REQUIREMENTS, SUBPART b. "NO TEST SHALL BE REQUIRED FOR LINERS THAT DO NOT INCORPORATE OR NEED A SEAL MECHANISM." COG BELIEVES WE MEET THE CRITERIA TO NOT BE REQUIRED TESTING THE LINER TOP BECAUSE THERE IS NO NEED FOR A SEAL MECHANISM.

NOTE: COG OPERATING LLC REQUESTS A VARIANCE TO THE 200' MINIMUM TIE BACK TO THE PRODUCTION CASING BECAUSE THE LOWEST PERFORATION IS AT 4557'. THE 100' WILL ALLOW US TO NOT COVER EXISTING PERFORATIONS. SEE ATTACHED FOR

CONDITIONS OF APPROVAL

5. Minimum Specifications for Pressure Control

The BOP equipment will be a 3000 psi double ram type manually operated preventer. This equipment will be nipple up to a 7-1/16" 3K flange. The pipe rams are located above blind rams. There is no choke or kill manifold. The BOP is tested to see psi prior to drilling new formation. Access to the annulus will be through the valves on the 5-1/2" casing head.

6. Types and Characteristics of the Proposed Mud System

This well will drilled from end of the existing 5-1/2" casing to TD with 2% KCl.

7. Auxillary Well Control and Monitoring Equipment

- A. A full opening drill pipe-stabbing valve with proper drill pipe connections will be on the rig floor at all times.
- 8. Logging, Testing, and Coring Program

.....

- B. No drill stem tests.
- C. No conventional coring anticipated.
- D. Further testing procedures will be determined after the 4" liner has been cemented at TD, based on drill shows and log evaluation.

9. Abnormal Conditions, Pressure, Temperatures, and Potential Hazards

No abnormal pressures or temperatures are anticipated. The estimated bottomhole temperature at TD is 110 degrees and the estimated maximum bottomhole pressure is 2300 psig. The drilling starts in the Yeso and ends in the Yeso. The section of Yeso being drilled has very low permeability (less than 1 md).

10. Anticipated Starting Date and Duration of Operations

There will be no road or location work required as this is an existing well location. Once commenced, drilling operations should be finished in approximately 14 days. If the well is productive, an additional 30 days will be required for completion and testing before a decision is made.

11. Centralizer Program

Fixed blade stabilizer subs will be utilized in the casing string to insure adequate isolation and seal throughout the wellbore. These stabilizer subs are positive fixed blade type. These subs will actually be screwed into the casing string. A diagram of the fixed blade stabilizer sub is located at the end of this program.

The standard location of the stabilizers will be the following:

Shoe Location

Guide shoe, 1 jt casing, stabilizer sub, float collar, 1 jt casing, stabilizer sub

Perf Interval Location – between perf intervals Stabilizer sub, 1 jt casing, stabilizer sub

Top of Liner Location

DV tool, 1 jt casing, stabilizer sub, 1 jt casing, stabilizer sub

12. Summary Drilling and Completion Program


Deepening Procedure

- 1. MIRU rig.
- 2. LD production equipment
- 3. Sqz upper Yeso w/ +/-400sx of Class C neat.
- 4. Drill out squeeze. Test squeeze to 500 psi for 20 minutes using chart recorder.
- 5. PU 4-3/4" bit and drill 4-3/4" from 4436' to 5750'.
- 6. POOH w/ bit and drillstring.
- 7. RIH w/ logs and log from TD to 4400'.
- 8. RIH w/ 4", 11.3# casing. See next attachment for general centralizer program.
- 9. Cement casing from TD to 4361' w/ 115 sxs Class C cmt. Drop plug and open DV tool. Circ cmt off DV tool. Drop plug to close DV tool.

- 10. PU workstring and RIH and drill out DV tool. POOH and LD workstring.
- 11. RDMO rig.

Completion Procedure

- 1. MIRU rig.
- 2. RIH/ w/ perforating guns and perforate Yeso from 5150 5350 w/ 1 spf, 28 holes.
- 3. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 179,800 # of sand. Set plug at 5100'.
- 4. RIH w/ perforating guns and perforate Yeso from 4850' 5050'.
- 5. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 179,800 # of sand. Set plug at 4800'.
- 6. RIH w/ perforating guns and perforate Yeso from 4550' 4750'.
- 7. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 179,800 # of sand.
- 8. RIH and drill out plug at 4800' and 5100'.
- 9. RIH and cut or back off 4" casing at 4361'. POOH w/ 4" casing. Leave 4" liner from 4361' to 5750' (TD).
- 10. RIH w/tbg and locate end of tbg at 4200'.
- 11. RIH w/ rods and pump.
- 12. RDMO rig.



CONDITIONS OF APPROVAL

COG Operating LLC NMNM14840 White Star Federal 25 30-015-32509 Section 29, T. 17 S., R 29 E., NMPM Eddy County, New Mexico

- 1. Surface disturbance beyond the existing pad must have prior approval.
- 2. Closed loop system required.
- 3. H2S monitoring equipment should be onsite for personnel protection from surrounding oil operations. Operator should not encounter H2S while deepening.
- 4. 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 5. BOP to be tested to 1000 psi based on expected BHP
- 6. Variance for stand-off of less than 0.422" is approved due to NMOCD classifying the formations in this area as the Yeso group Pool 96610.
- 7. Variance for not testing seal also approved based on NMOCD classification of formations in this area as the Yeso group Pool 96610.
- 8. Variance approved for a minimum tie back of 100'. When plugged, cement plug will be required across this tie back and across squeezed perforations.
- 9. If cement does not circulate to DV tool, the appropriate BLM office is to be notified.
- 10. Test casing as per Onshore Order 2.III.B.1.h
- 11. Steel tanks to be used.
- 12. Work to be completed in 90 days
- 13. Subsequent sundry and completion report required when work is complete.

EGF 111912