Approved By

## UNITED STATES DEPARTMENT OF THE INTERIOR.

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

B	UREAU OF LAND MANA	GEMENT	i	OCD Ari	tesi <b>a</b>		<u> </u>	uly 31, 2010		_
SUNDRY NOTICES AND REPORTS ON WI Do not use this form for proposals to drill or to re abandoned well. Use form 3160-3 (APD) for such p				ELLS e-enter an			5. Lease Serial No. NMNM82845			
							6. If Indian, Allottee or Tribe Name			_
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.				_	
1: Type of Well  Gas Well ☐ Other					<del></del>	8. Well Name and No. POLO AOP FEDERAL 6				_
2. Name of Operator Contact: TINA HUERTA YATES PETROLEUM CORPORATIONE-Mail: tinah@yatespetroleum.com						9. API Well No. 30-015-28871				
3a. Address 105 SOUTH FOURTH STREE ARTESIA, NM 88210	3b. Phone No. (include area code) Ph: 575-748-4168 Fx: 575-748-4585				10. Field and Pool, or Exploratory PENASCO; WOLFCAMP					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						11. County	or Parish, a	nd State		_
Sec 10 T19S R25E SWSE 660FSL 1980FEL						EDDY	COUNTY,	NM		
		····								_
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE	NATURI	E OF N	OTICE, RE	EPORT, OI	R OTHER	DATA		
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE O							•		
Notice of Intent	☐ Acidize	□ Dee	pen	,	□ Producti	on (Start/Re	esume)	□ Water Sh	ut-Off	
	☐ Alter Casing	□ Frac	ture Treat		□ Reclama	ition		□ Well Inte	grity	
□ Subsequent Report	☐ Casing Repair	□ New	Construct	ion	Recomp	lete	Other			
Final Abandonment Notice	Change Plans	ge Plans Plug and Abandon Temporarily Abandon								
	☐ Convert to Injection									
3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation have been dompleted and the operated has determined that the site is ready for final inspection.)  Yates Petroleum Corporation plans to plugback and recomplete this well as follows:  1. MIRU all safety equipment as needed. NU BOP.  2. Make a GR/JB run down to 7710'; then set a 7" CIBP at 7700' with 35' cement on top.  3. Perforate Wolfcamp 6006'-6408'(80).  4. Acidize 6338'-6408' with 1500g 20% HCL with 2g/M gelling agent, cationic surfactant, corrosion inhibitor and iron control additives. Drop 20 1.3 sg ball sealers spaced out evenly throughout the acid. Flush to bottom perf and over flush by 25 bbls.  5. Acidize 6190'-6252' with 2800g 20% HCL with 2g/M gelling agent, cationic surfactant, corrosion inhibitor and iron control additives. Drop 40 1.3 sg ball sealers spaced out evenly throughout the acid. Flush to bottom perf and over flush by 25 bbls.  6. Acidize 6006'-6130' with 3700g 20% HCL with 2g/M gelling agent, cationic surfactant, corrosion inhibitor and iron control additives. Drop 50 1.3 sg ball sealers spaced out evenly throughout the acid. Flush to bottom perf and over flush by 25 bbls.  6. Acidize 6006'-6130' with 3700g 20% HCL with 2g/M gelling agent, cationic surfactant, corrosion inhibitor and iron control additives. Drop										
4. Thereby certify that the foregoing is	true and correct. Electronic Submission #10	60640 verifie	by the Bl	M Well	Information	System	NMOC	D ARTE	SIA	=
•	For YATES PETROI Committed to AFMSS fo									
Name(Printed/Typed) TINA HUERTA					PORTING		OR			
Signature (Electronic Submission)				1/19/20	12		, 100 page			ı
	THIS SPACE FO	R FEDERA	L OR ST	ATE O	FFICE US	ŧ /	<b>IPPR</b>	OVED		Ī
	<del></del>								7	F

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title


Office


## Additional data for EC transaction #160640 that would not fit on the form

## 32. Additional remarks, continued

acid. Flush to bottom perf and over flush by 25 bbls. Move tools to straddle all perfs and swab test and evaluate and consider turning well over to production or pumping a 20,000g acid frac.
7. TIH with tubing. RIH with pump and rods and hang well off. Turn well over to production.

Wellbore schematics attached





## Polo AOP Federal Com 6 30-015-28871 Yates Petroleum Corporation December 07, 2012 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by March 07, 2012.

- 1. Surface disturbance beyond the originally approved pad must have prior approval.
- 2. Closed loop system required.
- 3. Operator to have H2S monitoring equipment on location.
- 4. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above precharge. The pre-charge test shall follow requirements in Onshore Order #2.
- 5. CIBP at 7,700' okay. Operator shall tag CIBP and place a 25 neat Class H cement plug on CIBP. No tag required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Subsequent sundry required detailing work done and completion report for new zone. Operator to include well bore schematic of current well condition when work is complete.

**JAM 120712**