Form 3160-5 (August 2007) - DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010 5. Lease Serial No. NMLC 0064756 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or C	A/Agreement, Name and/or No
1. Type of Well Gas Well X Other SWD 2. Name of Operator E0G Resources Inc. 3a. Address 3b. Phone No. (include area code) P.O. Box 2267 Midland. Texas 79702 432-686-3689 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980 FSL & 660 FEL, U/L I Sec 24, T26S, R31E Sec 24, T26S, R31E				8. Well Name and No. R. T. Wilson 1 <u>Federal</u> 9. API Well No. <u>30-015-05864</u> 10. Field and Pool, or Exploratory Area Mason; Delaware, North 11. County or Parish, State Eddy NM	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REF					
TYPE OF SUBMISSION Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Operation (clearly If the proposal is to deepen directionally or recomp	lete horizontally, give subsurfa	Deepen Fracture Treat New Construction Plug and Abandon Plug Back uding estimated startin ce locations and measu	Production Reclamation Recomplete Temporarily Water Disp g date of any pro- ured and true ver	e y Abandon osal posed work and tical depths of a	II pertinent markers and zones.
Attach the Bond under which the work will be per following completion of the involved operations. I testing has been completed. Final Abandonment h determined that the final site is ready for final inspe EOG Resources accepts all applica operations conducted on the lease	f the operation results in a mult Notices shall be filed only after ection.) ble terms, condition	tiple completion or rec all requirements, incl s, stipulations	completion in a n uding reclamations and restr	ew interval, a F on, have been c ictions co	form 3160-4 shall be filed once ompleted, and the operator has
Lease # NMLC0064756 R.T. Wilson Federal Number 1 1980 FSL & 660 FEL U/L I, Sec 24, T26S, R31E	RECEIVED	7		ACCAPIE ACCAPIE NB	k = 12/13/12 of for record NOCD
Effective 10/31/12. NM Bond Number 2308	DEC 11,2012		EE ATTA ONDITIC		FOR APPROVAL
14. I hereby certify that the foregoing is true and correct Name (Printed Typed) Stan Wagner Signature How Way	I	Date 11/5/2012		st	
	SPACE FOR FEDERAL				
Approved by /s/ JD Whitle Conditions of approval, if any, are attached. Approval of this not the applicant holds legal or equitable title to those rights in the sul entitle the applicant to conduct operations thereon.	ice does not warrant or certify that	Title SPE Office (F=2			nate 12/7/12

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval

EOG Resources Inc. R. T. Wilson #1, 2, 3 and 4 Lease NMLC064756

- 1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
- Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
 Subject to like approval by NMOCD.
- 8. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.

43 CFR 3162.3-4 (C) requires that wells incapable of production in paying quantities be promptly plugged and abandoned....

Wells may not be producing in paying quantities.

9. If a well is not capable of production in paying quantities submit Notice of Intent to P&A or submit documentation proving that well is capable of production in paying quantities within 30 of approval of change of operator.