

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB No. 1004-0137
Expires: October 31, 2014

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NM-07716

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
LIME ROCK RESOURCES II A, L.P.

3a. Address
1111 BAGBY STREET, SUITE 4600
HOUSTON, TX. 77002

3b. Phone No. (include area code)
713-292-9526 (SID ASHWORTH)

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.
VANDAGRIFF 8 D FEDERAL #4

9. API Well No.
30-015-40805

10. Field and Pool or Exploratory Area
RED LAKE; GLORIETA-YESO

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
330 FNL & 990 FWL, SECTION 08, T. 18 S., R. 27 E.

11. County or Parish, State
EDDY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA


TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input checked="" type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

LIME ROCK RESOURCES PROPOSES TO CHANGE THE APD PLANS TO ADD A BATTERY ON THE WEST SIDE OF THE PAD OF THE VANDAGRIFF 8 D FEDERAL #4 WELL LOCATION. SEE ATTACHED SCHEMATIC DRAWING OF THE FACILITY.

Approval Subject to Amending IR plan (Attached)

Accepted for record
NMOCD 105
11/18/2013



14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

BARRY W. HUNT

Title PERMIT AGENT FOR LIME ROCK RESOURCES II A, L.P.

Signature

Barry W. Hunt

Date

12/26/12

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

James G. Arns

Title

SEAS


Date

1-13-13

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

WEST



oil Flow line

P/W line

-X-X-X-X-X-

Gas line


-o-o-o-o-o-

Vent line

-.-.-.-.-

Vandagriff 80 #4 BHH

Interim Reclamation & Production Facilities




LIME ROCK RESOURCES II-A, L.P
VANDAGRIFF 8 D FEDERAL #4

Well Bore



Interim Reclamation

Production Facilities



Flowline

North

