

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

SUBMIT IN TRIPLICATE

N.M. Oil Cons. Div-Dist. 2  
1301 W. Grand Avenue  
Artesia, NM 88210

FORM APPROVED  
OMB NO. 1004-0135  
EXPIRES: NOVEMBER 30, 2000

1a. Type of Well ☒ Oil Well ☐ Gas Well ☐ Other \_\_\_\_\_

2. Name of Operator  
Devon Energy Production Co., LP

3. Address and Telephone No.  
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-7802

4. Location of Well (Report location clearly and in accordance with Federal requirements)\*  
Lot A, Sec 26 T-23S-R31E  
660' FNL & 990' FEL

RECEIVED

SEP 29 2005

OCD-AMC

5. Lease Serial No.  
NM 0405444-A

6. If Indian, Allottee or Tribe Name

7. Unit or CA Agreement Name and No.

8. Well Name and No.  
Todd 26A Federal 6

9. API Well No.  
30-015-21224

10. Field and Pool, or Exploratory  
Sand Dunes (Cherry Canyon)

12. County or Parish 13. State  
Eddy NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other Drilling Operations
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepens directionally or recompletes horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)

Devon Energy Production Company, L.P. respectfully requests approval to run a MIT on the referenced well as follows: MURU pump track. Pressure up on casing to 500 psi for 30 minutes, using a chart type pressure recorder. RDMO pump truck.

CIBP will be set @ 6,020' with 35' cmt on top of CIBP.

TA'ing well to bring well into OCD compliance, until well can be evaluated as future injection well for Cherry Canyon flood. Evaluation to be done within the next year.

SEE ATTACHED FOR  
CONDITIONS OF APPROVAL

Accepted for record  
NMOC

14. I hereby certify that the foregoing is true and correct

Signed \_\_\_\_\_

Name Stephanie A. Ysasaga  
Title Senior Engineering Technician

Date 9/26/2005

(This space for Federal or State Office use)

Approved by (ORIG. SGD.) ALEXIS C. SWOBODA  
Conditions of approval, if any \_\_\_\_\_

Title PETROLEUM ENGINEER

Date SEP 28 2005

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations to any matter within its jurisdiction.

\*See Instruction on Reverse Side