

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised May 08, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-34156
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 34884
7. Lease Name or Unit Agreement Name: 1625 Werner
8. Well Number 231
9. OGRID Number 218885
10. Pool name or Wildcat Cottonwood Creek-Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>	RECEIVED OCT 03 2005 OCCIDENTAL
2. Name of Operator LCX Energy, LLC	
3. Address of Operator 110 N. Marienfeld, Ste. 200, Midland, TX 79701	
4. Well Location Unit Letter <u>A</u> : <u>760</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line Section <u>23</u> Township <u>16S</u> Range <u>25E</u> NMPM <u>Eddy</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3436' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☒

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/15/05 Set a 750-850' 17# kick off cement plug from depth 5060 - 4240'. Pressure test lines to 5000# psi. Circulate capacity of D/P. Pump 6.5 bbls @ 9.6# mud spacer. Mix & pump 450 sx & 80 bbls of 17.9# cement @ 461 cuft. WOC & pull 12 stands & reverse out 80 bbls ANN & DP capacity return back to pit 12 bbls of cement. POOH & lay down 39 jts of DP. Jet & clean pits. TIH with bit #6 & tag up @ 4240'. Displaced hole with FH20. WOC.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lisa Hunt TITLE Regulatory Analyst DATE 9/23/05

Type or print name Lisa Hunt Telephone No. 432 848-0214

(This space for State use)

FOR RECORDS ONLY

APPROVED BY [Signature] TITLE [Signature] DATE OCT 04 2005

Conditions of approval, if any: None WOC Time & Casing Pressure Test