

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-015-35346
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name BUCKSHOT STATE COM
8. Well Number 01
9. OGRID Number 258894
10. Pool name or Wildcat MALAGA; MORROW (GAS)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3033

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
LEGEND NATURAL GAS II, LP

3. Address of Operator
15021 KATY FREEWAY, SUITE 200, HOUSTON, TX 77094

4. Well Location
 Unit Letter: I : 1980 feet from the SOUTH line and 1250 feet from the EAST line
 Section 31 Township 24S Range 28E NMPM EDDY County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

BUCKSHOT STATE COM 01-WORKOVER DUE TO POSSIBLE LEAK IN TUBING
 04/30/2013-05/03/2013-PX PLUG IN X-NIPPLE/PACKER @ 12175' VIA SLICKLINE, RELEASE ON/OFF TOOL, TRIP OUT OF HOLE W/ 2 3/8" PRODUCTION TUBING, RIGH UP HYDROTTESTES AND TEST TUBING BACK IN THE HOLE, REPLACED BAD JOINTS; LATH ONTO ON/OFF TOOL, PULL PX PLUG FROM X-NIPPLE/PACKER, SWABBED WELL, RESUMED PRODUCTION VIA NATURAL FLOW.

Tubing depth?

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jennifer Mosley TITLE SR. REGULATORY ANALYST DATE 05/08/2013

Type or print name JENNIFER MOSLEY E-mail address: JMOSLEY@LNG2.COM PHONE: 817-872-7822

APPROVED BY: [Signature] TITLE Dist. Reg. Supervisor DATE 5/10/2013

Conditions of Approval (if any):