Form 3160-5 (April 2004)

Notice of Intent

Subsequent Report

Final Abandonment Notice

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

## BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

Well Integrity

## 5. Lease Serial No.

BHL: NMLC 0069627A

Do not use this form for abandoned well. Use For	6. If Indian, Allottee or Tribe Name  See pg 1 of 8 pt DP for lease info.				
SUBMIT IN TRIPLICATE-	7. If Unit or CA/Agreement, Name and/or No.				
Type of Well		Poker Lake Unit NMNM 71016X			
✓ Oil Well □ () Gas Well □□ Other		8. Well Name and No.			
2. Name of Operator BOPCO, L. P.		Poker Lake Unit 443H			
BOFCO, L. F.		9. API Well-No.			
a Address	3b. Phone No. (include area code)	30-015-41198			
P. O. Box 2760 Midland, TX 79702	432-683-2277	10. Field and Pool, or Exploratory Area			
Location of Well (Footage, Sec., T., R., M., or Surv	ey Description)	Nash Draw (Del, BS, AV)			
		11. County or Parish, State			
At surface SWSE, UL O 791' FSL & 2 At proposed BHL 1495' FSL & 2535' FWL,	Sec 19, T24S-R30E				
12. CHECK APPROPRIATE	BOX(ES) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION				
Acidize	Deepen Production	(Start/Resume) Water Shut-Off			

OCD Artesia

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Fonn 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Fracture Treat

Plug Back

New Construction

Plug and Abandon

Reclamation

Recomplete

Water Disposal

Temporarily Abandon

Accepted for record NMOCD

Alter Casing

Change Plans

Casing Repair

\_\_ Convert to Injection

RECEIVED

MAY 28 2013

BOPCO, L.P. respectfully requests the change of plans as attached.

SEE ATTACHED FORMMOCD ARTESIA CONDITIONS OF APPROVAL

Te / 25/2017

14. Thereby certify that the foregoing is true and correct Name (Printed/Typed) Christopher Völck	Title Drilling Engineer			
Signature Arch Jolet	Date 5/22/2013		APPROVED	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by	Title		Date MAY 2 2 2013	
Conditions of approval, if any, are attached. Approval of this notice does not warrar certify that the applicant holds legal or equitable title to those rights in the subject leads which would entitle the applicant to conduct operations thereon.			WESLEY W. INGRAM PETROLEUM ENGINEER	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to any matter	person knowingly and willfully to r within its jurisdiction.	nake to a	ny department or agency of the United	

BOPCO, L.P. respectfully requests to use a 13-5/8" 5,000 psi Cameron MBS wellhead system for the PLU #443H. Please find wellhead schematic attached. The Cameron MBS wellhead was installed on the 13-3/8", 48 ppf, H-40, surface casing on 5/19/2013. The weld was tested to 500 psi under the supervision of a Cameron wellhead hand. Please find field report attached.

On 5/19/2013 Battle Services tested Latshaw #4's 13-5/8", 5,000 psi WP BOP stack, choke manifold, chokes, kill lines, kelly cocks, kelly safety valves, floor valves, 250 psi low and 3,000 psi high and annular 250 psi low and 2,500 psi high. Test casing to 1,200 psi as per BLM COA. The BOP was tested to the maximum pressures expected at any point in the drilling operation. Please find pressure chart attached. After the 1<sup>st</sup> intermediate hole was drilled and the 9-5/8" casing was run and cemented it was found that cement had clogged and set up in the wellhead mandrel causing the need to nipple down the BOP such that the wellhead could be cleaned out. The BOP will have to be nippled down at the lower 13-5/8" flange, lifted up and the wellhead will be cleaned out by hand. BOPCO, L.P. respectfully requests to test only the 13-5/8" flange fitting that was broken between the BOP and the Cameron MBS wellhead to 3,000 psi high, 250 psi low pressure.




**CUSTOMER: BOPCO** 


PROJECT: Poker Lake Unit #443H

RIG: Latshaw #4

CASING PROGRAM: 13-3/8" x 9-5/8" x 5-1/2"

**DATE: May 6th 2013** 





PLU # 443 BOP Test

Poker Lake Unit 443H 30-015-41198 BOPCO, L.P. May 22, 2013 Conditions of Approval

- 1. Operator has installed and tested a multi-bowl wellhead assembly prior to approval. This assembly was tested when installed on the 13-3/8" surface casing. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 3000 (3M) psi. BLM is granting approval to continue use of the Cameron multi-bowl wellhead assembly by BOPCO abiding by items b. d. listed below.
  - a. Operator submitted documentation that a manufacturer's representative installed the wellhead.
  - b. Operator shall perform the 9-5/8" and 7" casing tests to 70% of the casing burst. This will test the multi-bowl seals. These tests shall be charted and held for 30 minutes. Submit test charts with subsequent report sundry on drilling operations.
  - c. In addition to testing the flange fitting that was disconnected, operator shall also test the manual valve below I-BOP hydraulic valve that was missed in the original test. The rig has already been informed of the need for this test.
  - d. The operator shall monitor the mud system for possible gas kicks until such time that the 7" production casing is cemented as the set point of the 9-5/8" casing restricts when the BOP can be closed without creating the potential for an underground blowout. An underground blowout is considered an undesirable event.

WWI 052213