Form 3160-5 (November 1994)

RECEIVED

MAY 28 2013

UNITED STATES
DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENTMOCD ARTESIA

OMB No. 1004-0135 Expires July 31, 1996

FORM APPROVED

Lease Serial No.

SUNDRY I	NMLC 065478-B					
Do not use this abandoned well.	6. If Indian, Allottee or Tribe Name					
SUBMIT IN TRIPL	ICATE – Other instru	ıctions on reverse	side	7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well X Oil Well Gas Well 2. Name of Operator	8. Well Name and No. FALCON 3 D FEDERAL #30					
LIME ROCK RESOURCES	II-A, L.P. OGRIDA	# : 277558		9. API Well No.		
3a. Address c/o Mike Pippin L	.LC	3b. Phone No. (include	area code)	30-015-39451		
3104 N. Sullivan, Farmington, NM 87401 505-327-4573				10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec.,	Red Lake, Glorieta-Yeso NE (96836)					
250' FNL & 1300' FWL Unit	AND					
Sec. 3, T18S, R27E	Eddy County, New Mexico					
12. CHECK APPROPRIATE BOX	X(ES) TO INDICATE NA	TURE OF NOTICE, REF	PORT, OR OT	HER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize Alter Casing	☐ Deepen ▼ Fracture Treat	Production Reclamatio	(Start/Resume) Water Shut-Off n Well Integrity		
Subsequent Report	Casing Repair	☐ New Construction	Recomplete			
	Change Plans	Plug and Abandon	Temporaril	y Abandon .		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disp	osal		

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BLA. Required subsequent reports shall be filed within 30 days. Following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

LIME ROCK would like to perform a payadd workover on this oil well as follows: MIRUSU. TOH w/all production equipment. Set a 5-1/2" CBP @ ~3185'. (Existing Yeso perfs are @ 3197'-4466'). Perf additional Glorieta/Yeso @ about 2962'-3175' w/~33 holes. Stimulate w/about 1000 gal 7.5% NEFE acid, & frac w/about 86,000# 16/30 sand in X-linked gel. CO after frac, drill out CBP @ 3185', & CO to about 4474'. Re-land 2-7/8" 6.5# J-55 tbg @ ~4340'. Run pump & rods. Release rig. Complete as a single Glorieta/Yeso oil well.

Accepted for record

NMOCO 1895/29/108

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Title	•		
Petroleum Engineer (OAgent) En			
Date		MÆ	79, 2013
E FOR F	EDERAL OR STA	ATE USE	may 9 4 2012
	Title		Vennder Wason
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		BUF	CARLSBAD PIELD OFFICE
	Date E FOR I	Title warrant or Office	Petroleum I Date Man E FOR FEDERAL OR STATE USE Title warrant or Office RIII

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or traudulent statements or representations as to any matter within its jurisdiction.



Proposed Pay Add Workover

Falcon 3D Federal #30 Sec 3-18S-27E (NE D) 250' FNL & 1300' FWL Elevation – 3,585' RKB API # 30-015-39451 Eddy County, NM

8-5/8", 24#, J-55 ST&C Casing @ 379'. Circ 105 sx to Surface. (10/11/2011)

GEOLOGY				
Zone	<u>Top</u>			
Queen	833,			
Grayburg	1,321'			
Premier	1,508'			
San Andres	1,551'			
MSA	1,826'			
LSA	2,427'			
Glorieta	2,892'			
Yeso	3,000'			
Tubb	4,474'			

SURVEYS				
Degrees	Depth			
1	396'			
1	506'			
1/2	1,013			
3/4	1,511'			
1/4	2,019'			
1/2	2,523'			
1/2	3,050'			
1/4	4,029			
1	4 538'			

Proposed Perfs: 2,962' – 3,175' (1 SPF – 33 holes @ 0.41" EHD and 29" penetration)

Set CBP @ 3,185'

PBTD @ 4,475'

Perfs: 3,197' – 3,367' (1 and 2 SPF – 39 holes @ 0.41" EHD and 29" penetration)

Perfs: 3,415' – 3,678' (2 SPF – 38 holes @ 0.41" EHD and 29" penetration)

Perfs: 3,760' – 4,033' (1 SPF - 40 holes @ 0.41" EHD and 29" penetration)

Perfs: 4,100' – 4,466' (1 SPF - 41 holes @ 0.41" EHD and 29" penetration) Proposed Stim: Acidize w/ 1,000 gals 15%. Frac w/ 42,500 gal Viking 2000 x-linked gel, 68,000 lbs 16/30 Brady sand and 18,000 lbs SiberProp

Stim: Acidize w/ 6,888 gals 15% and 60 ball sealers. Frac w/ 37,820 gal Viking 2000 x-linked gel, 48,196 lbs 16/30 Brady sand and 17,927 lbs SiberProp

Stim: Acidize w/ 2,797 gals 15% and 75 ball sealers. Frac w/ 52,991 gal Viking 2000 x-linked gel, 63,786 lbs 16/30 Brady sand and 14,716 lbs SiberProp

Stim: Acidize w/ 2,789 gals 15% and 80 ball sealers. Frac w/ 53,584 gal Viking 2000 x-linked gel, 62,735 lbs 16/30 Brady sand and 16,331 lbs SiberProp

Stim: Acidize w/ 2,705 gals 15% and 80 ball sealers. Frac w/ 82,513 gal Viking 2000 x-linked gel, 83,575 lbs 16/30 Brady sand and 16,795 lbs SiberProp

5-1/2"; 17#; J-55; ST&C Casing @ 4,522'. Circ 172 sx to Surface. (10/16/2011)

TD @ 4,538'

Falcon 3 D Federal 30 30-015-39451 LRE Operating, LLC. May 24, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

- 1. Must conduct a casing integrity test before any perforating or fracturing can be done. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure.
- 2. If MIT does not fail, work is approved as written.
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.

- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 9. Subsequent sundry required detailing work done. Operator to include well bore schematic of current well condition when work is complete.

JAM 052413