

Form 3160-5
(August 2007)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

5. Lease Serial No.

NM-23002

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

7. If Unit of CA/Agreement, Name and/or No.

1. Type of Well

☒ Oil Well☐ Gas Well☐ Other SWD8. Well Name and No.
Hudson Federal # 2

2. Name of Operator

Vanguard Permian, LLC

9. API Well No.

30-015-26804

3a. Address

5847 San Felipe St. Ste. 3000, Houston, TX 77057

3b. Phone No. (include area code)

432-770-9738

10. Field and Pool or Exploratory Area

Shugart Y, SR,Q

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650 FSL and 2180 FEL Sec. 11 T188 R31E

11. Country or Parish, State

Eddy

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☒ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

1. 3/21/13- Notify BLM/OGD on MFRU to P/A

2. 3/25/13 - Set CIBP @ 2500' (Perfs @ 2388')

3. 3/26/13 Tag CIBP @ 2500' circ hole w/mil min 8 lb BW w/25 lbs gel P/bbl spot 25x'a class "c" cm) (perfs 7 - Rivers) woc tag @ 2349', spot 175 sx's class "c" cmt 1/850' surf (top of salt, shoe) woc tag @ surf.

4. 3/27/13 RD P & A equip cut off well head, install ground level DHM clean location.

Accepted as to plugging of the well bore.
Liability under bond is retained until
Surface restoration is completed.RECLAMATION
DUE 9-21-13

Accepted for record

NM/OGD

code 6/7/2013



14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Signature

Title Agent

Date 03/27/2013

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)