

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary-Designate

Brett F. Woods, Ph.D.
Deputy Cabinet Secretary

Jami Bailey, Division Director
Oil Conservation Division



June 10, 2013

Mr. Travis White
Canyon E&P Company
911 Lake Carolyn Pkwy
Suite 104
Irving, TX 75039

Dear Mr. White,

According to Oil Conservation Division (OCD) records, the authority to inject into the attached list of injection wells **has terminated** pursuant to Division Rule 19.15.26.12.C NMAC. Division records show Canyon E&P Company, OGRID # 269864 (Canyon) as the operator of record of the well.

Division Rule 19.15.26.12.C NMAC states:

C. Abandonment of injection operations.

- (1) Whenever there is a continuous one year period of non-injection into all wells in an injection or storage project or into a salt water disposal well or special purpose injection well, the division shall consider the project or well abandoned, and the authority for injection shall automatically terminate ipso facto.

Canyon is out of compliance with ACO-270 and ACOI-250. Once the deadline was reached for ACOI-250, (June 15th 2012) without being fulfilled by the operator, Canyon was instructed to shut-in all of their injection wells. Inspector Inge met Mr. Meyers on location on June 19th to begin testing of their injection wells. Mr. Meyers informed Mr. Inge that the repair of the wells had not been completed. Mr. Inge instructed Mr. Meyers to shut-in and disconnect all injection wells. An LOV was issued on June 27th, 2012 reiterating this directive. As of this date, the OCD has not been contacted by Canyon to indicate that the well repairs have been made. There has been one continuous year period of non-injection.

Therefore, based upon the requirement to cease injection into their injection wells and Canyon not complying with ACOI250, the authority to inject into their wells has terminated pursuant to Division Rule 19.15.26.12.C NMAC.

June 10, 2013

Page 2

Canyon must submit a plugging procedure for these wells by July 15, 2013. The plugging procedure must set forth how the wells are going to be plugged and a timeline for completion of the plugging.

Sincerely,

A handwritten signature in black ink, appearing to read "Daniel Sanchez", with a long horizontal stroke extending to the right.

Daniel Sanchez

New Mexico Underground Injection Control Program Director
Compliance and Enforcement Manager

Encl: Injection well list

CC: Terry Warnell, State Land Office
E.L. Gonzales, District I
Randy Dade, District II

Canyon E&P

6/12/2013

API#	Well Name	#	Comments
30015009410000 ✓	ARTESIA METEX UNIT	006	Lost Authority - must P&A
30015009440000 ✓	ARTESIA METEX UNIT	008	Lost Authority - must P&A
30015019640000 ✓	ARTESIA METEX UNIT	012	Lost Authority - must P&A
30015009420000 ✓	ARTESIA METEX UNIT	016	Lost Authority - must P&A
30015011960000 ✓	ARTESIA METEX UNIT	020	Lost Authority - must P&A
30015021400000 ✓	ARTESIA METEX UNIT	032	Lost Authority - must P&A
30015009630000 ✓	ARTESIA METEX UNIT	035	Lost Authority - must P&A
30015009540000 ✓	ARTESIA METEX UNIT	040	Lost Authority - must P&A
30015021360000 ✓	ARTESIA METEX UNIT	041	Lost Authority - must P&A
30015009590000 ✓	ARTESIA METEX UNIT	045	Lost Authority - must P&A
30015021410000 ✓	ARTESIA METEX UNIT	049	Lost Authority - must P&A
30015009600000 ✓	ARTESIA METEX UNIT	052	Lost Authority - must P&A
30015009560000 ✓	ARTESIA METEX UNIT	054	Lost Authority - must P&A
30015009870000 ✓	ARTESIA METEX UNIT	056	Lost Authority - must P&A
30015009910000 ✓	ARTESIA METEX UNIT	058	Lost Authority - must P&A
30005601610000 ✓	DOUBLE L QUEEN UNIT	003	Lost Authority - must P&A
30005601640000 ✓	DOUBLE L QUEEN UNIT	004	Lost Authority - must P&A
30005601270000 ✓	DOUBLE L QUEEN UNIT	001H	Lost Authority - must P&A
30005203070000 ✓	DOUBLE L QUEEN UNIT	001I	Lost Authority - must P&A
30005600780000 ✓	DOUBLE L QUEEN UNIT	001K	Lost Authority - must P&A
30005601170000 ✓	DOUBLE L QUEEN UNIT	001R	Lost Authority - must P&A
30005600840000 ✓	DOUBLE L QUEEN UNIT	001Y	Lost Authority - must P&A
30005203080000 ✓	DOUBLE L QUEEN UNIT	002H	Lost Authority - must P&A
30005203480000 ✓	DOUBLE L QUEEN UNIT	002I	Lost Authority - must P&A
30005203460000 ✓	DOUBLE L QUEEN UNIT	003L	Lost Authority - must P&A
30005203380000 ✓	DOUBLE L QUEEN UNIT	003Q	Lost Authority - must P&A
30005601530000 ✓	DOUBLE L QUEEN UNIT	003Y	Lost Authority - must P&A
30005600800000 ✓	DOUBLE L QUEEN UNIT	004G	Lost Authority - must P&A
30005203390000 ✓	DOUBLE L QUEEN UNIT	004Q	Lost Authority - must P&A
30005203950000 ✓	DOUBLE L QUEEN UNIT	009Q	Lost Authority - must P&A
30005605800000 ✓	KUCHEMANN	002	Lost Authority - must P&A
30015047940000 ✓	NORTHEAST SQUARE LAKE PREMIER UNIT	003	Lost Authority - must P&A
30015047880000 ✓	NORTHEAST SQUARE LAKE PREMIER UNIT	005	Lost Authority - must P&A

✓	30015047850000	NORTHEAST SQUARE LAKE PREMIER UNIT	008	Lost Authority - must P&A
✓	30015048310000	NORTHEAST SQUARE LAKE PREMIER UNIT	012	Lost Authority - must P&A
✓	30015048370000	NORTHEAST SQUARE LAKE PREMIER UNIT	021	Lost Authority - must P&A
✓	30015048450000	NORTHEAST SQUARE LAKE PREMIER UNIT	025	Lost Authority - must P&A
✓	30005621920000	O'BRIEN P	001	Lost Authority - must P&A
✓	30005620700000	TWIN LAKES SAN ANDRES UNIT	001	Lost Authority - must P&A
✓	30005606480000	TWIN LAKES SAN ANDRES UNIT	002	Lost Authority - must P&A
✓	30005605790000	TWIN LAKES SAN ANDRES UNIT	004	Lost Authority - must P&A
✓	30005605960000	TWIN LAKES SAN ANDRES UNIT	006	Lost Authority - must P&A
✓	30005605980000	TWIN LAKES SAN ANDRES UNIT	009	Lost Authority - must P&A
✓	30005605630000	TWIN LAKES SAN ANDRES UNIT	011	Lost Authority - must P&A
✓	30005605580000	TWIN LAKES SAN ANDRES UNIT	013	Lost Authority - must P&A
✓	30005625650000	TWIN LAKES SAN ANDRES UNIT	015	Lost Authority - must P&A
✓	30005600390000	TWIN LAKES SAN ANDRES UNIT	017	Lost Authority - must P&A
✓	30005605600000	TWIN LAKES SAN ANDRES UNIT	019	Lost Authority - must P&A
✓	30005606580000	TWIN LAKES SAN ANDRES UNIT	021	Lost Authority - must P&A
✓	30005609650000	TWIN LAKES SAN ANDRES UNIT	023	Lost Authority - must P&A
✓	30005603340000	TWIN LAKES SAN ANDRES UNIT	025	Lost Authority - must P&A
✓	30005605210000	TWIN LAKES SAN ANDRES UNIT	027	Lost Authority - must P&A
✓	30005607950000	TWIN LAKES SAN ANDRES UNIT	032	Lost Authority - must P&A
✓	30005600330000	TWIN LAKES SAN ANDRES UNIT	034	Lost Authority - must P&A
✓	30005600260000	TWIN LAKES SAN ANDRES UNIT	035	Lost Authority - must P&A
✓	30005606960000	TWIN LAKES SAN ANDRES UNIT	040	Lost Authority - must P&A
✓	30005608290000	TWIN LAKES SAN ANDRES UNIT	043	Lost Authority - must P&A
✓	30005602910000	TWIN LAKES SAN ANDRES UNIT	046	Lost Authority - must P&A
✓	30005607960000	TWIN LAKES SAN ANDRES UNIT	050	Lost Authority - must P&A
✓	30005609610000	TWIN LAKES SAN ANDRES UNIT	052	Lost Authority - must P&A
✓	30005003490000	TWIN LAKES SAN ANDRES UNIT	054	Lost Authority - must P&A
✓	30005602970000	TWIN LAKES SAN ANDRES UNIT	055	Lost Authority - must P&A
✓	30005611350000	TWIN LAKES SAN ANDRES UNIT	057	Lost Authority - must P&A
✓	30005608070000	TWIN LAKES SAN ANDRES UNIT	059	Lost Authority - must P&A
✓	30005609200000	TWIN LAKES SAN ANDRES UNIT	061	Lost Authority - must P&A
✓	30005625630000	TWIN LAKES SAN ANDRES UNIT	063	Lost Authority - must P&A
✓	30005610070000	TWIN LAKES SAN ANDRES UNIT	068	Lost Authority - must P&A
✓	30005608850000	TWIN LAKES SAN ANDRES UNIT	070	Lost Authority - must P&A

30005602480000	TWIN LAKES SAN ANDRES UNIT	074	Lost Authority - must P&A
30005608090000	TWIN LAKES SAN ANDRES UNIT	076	Lost Authority - must P&A
30005609950000	TWIN LAKES SAN ANDRES UNIT	078	Lost Authority - must P&A
30005609930000	TWIN LAKES SAN ANDRES UNIT	081	Lost Authority - must P&A
30005607940000	TWIN LAKES SAN ANDRES UNIT	086	Lost Authority - must P&A
30005610060000	TWIN LAKES SAN ANDRES UNIT	088	Lost Authority - must P&A
30005607900000	TWIN LAKES SAN ANDRES UNIT	091	Lost Authority - must P&A
30005611070000	TWIN LAKES SAN ANDRES UNIT	095	Lost Authority - must P&A
30005611050000	TWIN LAKES SAN ANDRES UNIT	100	Lost Authority - must P&A
30005610750000	TWIN LAKES SAN ANDRES UNIT	103	Lost Authority - must P&A
30005620680000	TWIN LAKES SAN ANDRES UNIT	105	Lost Authority - must P&A
30005611040000	TWIN LAKES SAN ANDRES UNIT	107	Lost Authority - must P&A
30005617720000	TWIN LAKES SAN ANDRES UNIT	109	Lost Authority - must P&A
30005614530000	TWIN LAKES SAN ANDRES UNIT	111	Lost Authority - must P&A
30005616040000	TWIN LAKES SAN ANDRES UNIT	113	Lost Authority - must P&A
30005617360000	TWIN LAKES SAN ANDRES UNIT	118	Lost Authority - must P&A
30005616230000	TWIN LAKES SAN ANDRES UNIT	119	Lost Authority - must P&A