Submit I Copy To Office	Appropriate District State of New Mexico			co	Form C-103			
District I (575)	393-6161	Energy, Minerals	and Natura	Resources	WELL API NO.	Revised Aug	ust 1, 2011	
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283					30-015-24855			
011 0 21 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			VATION D	IVISION	5. Indicate Type of Lease			
District III – (505)) 334-6178 JUN 2	6 2013 1220 South	h St. Franci	s Dr.	STATE X FEE			
District III – (505) 334-6178					6. State Oil & C	Gas Lease No.		
1220 S. St. Franci 87505	s Dr., Santa Fe, NM	0000		'	11:		,	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					7. Lease Name or Unit Agreement Name Red State			
1. Type of Well: Oil Well X Gas Well Other					8. Well Number 001			
Name of Operator State of New Mexico formerly Marks and Garner					9. OGRID Number 14070			
3. Address of Operator					10. Pool name or Wildcat			
	reet Artesia, NM 883	210			GB Jackson 7R	VS QN GB SA		
4. Well Locat	٠.							
1	_etterB:_3			line and23		m theEast	line	
Section		Township		inge 29E	NMPM	Eddy Count	y Control	
		11. Elevation (Show w	netner DK, K	KB, KI, GK, etc.)				
ALL CONTRACTOR OF THE PARTY OF	10 Marie 12				13003.44	party (A.C.) Day and deliver to the least of the delivership and the delivership and the second of the delivership and the del	County S 490" 20"; 21879 CL465 (645)4	
	12. Check Ap	propriate Box to Ir	ndicate Nat	ure of Notice,	Report or Othe	er Data		
	NOTICE OF INT	ENTION TO:		SUB	SEQUENT RI	EPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CA							SING 🗌	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A						X		
PULL OR ALT		MULTIPLE COMPL		CASING/CEMENT	JOB 🗆			
DOWNHOLE (COMMINGLE	·						
OTHER:	• • • •			OTHER:				
	be proposed or complete							
	ing any proposed work ed completion or recon		.14 NMAC.	For Multiple Cor	npletions: Attach	wellbore diagram	ı ot	
propos	ed completion of recon	ipicuoii.						
4/18/2013	MIRU and lay down rods. Installed BOP and Talley OOH.							
4/19/2013	Made scrapper run and set CIBP at 2524'. Circulated mud and spotted 25 sx cement on top of CIBP. POOH to 1808' and spotted 25 sx cement. POOH with tubing and perforated at 405'. Circulated cement down 5 1/2" casing To perfs at 405' and up annulus to surface. Took 160 sx.							
4/20/2013	Rigged down and cu	t off wellhead. Installe	ed marker and	cut off anchors.			,	
		.: ***						
•								
•								
<u></u>	1:					 1		
Spud Date:		Rig	Release Date	:				
· L	. , ,							
•	• •			•				
I hereby certify	that the information ab	ove is true and comple	te to the best	of my knowledge	e and belief.			
SIGNATURE_		TIT	I F		г	DATE		
JIGIAT ORD_			<u> </u>		Ł		•	
Type or print na		E-m	ail address:		· P	HONE:		
For State Use (Only		-					
APPROVED B	E Stan	oles TITI	E ///2	+ ME	> ~	ATIL 26-	2012	
	pproval (if any):	1111		a . I . Klát	<u> </u>	AIR COE		
	` //							