Submit I Copy To Appropriate District State of New Mexico Form C-103 Office Revised August 1, 2011 Energy, Minerals and Natural Resources District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-015-31650 <u>District II</u> – (575) 748-1283 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 1220 South St. Francis Dr. STATE | FEE \square 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH LITTLE BOX STATE PROPOSALS.) 8. Well Number 5 1. Type of Well: Oil Well ☐ Gas Well ☒ Other 2. Name of Operator 9. OGRID Number NADEL AND GUSSMAN PERMIAN 155615 3. Address of Operator 10. Pool name or Wildcat 601 N. MARIENFELD, SUITE 508, MIDLAND TEXAS 79701 LITTLE BOX CANYON: MORROW 4. Well Location G: 1980_feet from the __NORTH__ line and __1980__feet from the __EAST_line Unit Letter Township 20S Range 21E County EDDY Section 36 **NMPM** 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4 1 4382' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING □ PERFORM REMEDIAL WORK □ PLUG AND ABANDON \boxtimes COMMENCE DRILLING OPNS. P AND A **TEMPORARILY ABANDON CHANGE PLANS** \Box PULL OR ALTER CASING MULTIPLE COMPL \Box CASING/CEMENT JOB \Box DOWNHOLE COMMINGLE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 06/14/2012 RIG UP ON WELL, TUBING STUCK AT PACKER. RECEIVED APPROVAL FROM RANDY DADE TO CUT AND PULL TUBING ABOVE PACKER. PACKER AT 7868'. CUT TUBING AT 7820' AND PULL TUBING. SET CIBP AT 7818' AND DUMP BAIL 35FT OF CEMENT. RIG DOWN, PLAN TO PLUG AND ABANDON. 06/15/2012 RECEIVED JUN 24 2013 NMOCD ARTESIA Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE ENGINEER DATE 06/18/2013 Type or print name_JASON GOSS E-mail address: JGOSS@NAGUSS.COM PHONE: 432-682-4429 For State Use Only APPROVED BY: Conditions of Approval (if any):