Submit I Copy To Appropriate District Office	State of N	√lew Me	SECENTE!	<u> </u>	Form C-103
<u>District I</u> – (575) 393-6161	State of N REGENCED	and Natu	ral Paso Greey E		Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	UH EÐRSERV			WELL API NO. 30-015-03013	
811 S. First St., Artesia, NM 88210	OH CONSERV	ATION	DIVISION	5. Indicate Type	of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	NMOCD ARTES	St. Fran	MOUD ARTE	STATE	
<u>District IV</u> - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM ⁺	- Santa-re	÷1/1/1-87	202	6. State Oil & G E-742	as Lease No.
87505					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name HUMBLE STATE	
1. Type of Well: Oil Well	Gas Well Other			8. Well Number	1
2. Name of Operator				9. OGRID Numl	ber
Alamo Permian Resources. LLC				274841	
3. Address of Operator 415 W. Wall Street, Suite 500, Midland, TX 79701				10. Pool name or Wildcat GRAYBURG JACKSON; SR-Q-G-SA	
4. Well Location				Grati Berre 37	
Unit Letter F : 1980	feet from the N li	ne and	1980 feet fro	om the W I	ine
Section 20	Township 17S	Range	29E	NMPM	County EDDY
	11. Elevation (Show who	ether DR,	RKB, RT, GR, etc.)		August 1997
12. Check	Appropriate Box to Inc	licate N	ature of Notice	Report or Other	· Data
	• • •	areate i v		•	
	NTENTION TO:			SEQUENT RE	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS		REMEDIAL WORK COMMENCE DRI	 -	ALTERING CASING P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	H	CASING/CEMENT		PANDA L
DOWNHOLE COMMINGLE		_			
OTUED			OTHER :		W.O.T.O.N.
OTHER:			OTHER: R	ETURN TO PROD	OUCTION
			, .	. •	* , *
5/13/13	L'A CARLA D'	. 1		C. MIDIL III	
Pull tested and replaced 1 anchor. Wrods. Shop pump. ND wellhead. NU	Tait on CVE to temp. Disco	onnect ele	ctrical service for sational in Tallied out	atety. MIRU. Unna of the hole with to	ang well and POOH with
2285.45' PU 5-1/2 casing scrapper a	and RIH to 1800'. SWISD	ON.	John III. Tumba oat	or the hole with the	
					2 <
5/14/13 Finished running in the hole to 2200)' with casing scranner PC	OH with	hit and scranner PI	12-7/8" MA with	RP 3500' X 2=7/8" slotted
sub, crossover, 2-3/8" seating nipple	e, endurance joint, 3 joints	2-3/8" tu	bing, 5-1/2" X 2-3/3	8" TAC and 68 JT	S of tubing to surface. Set
TAC with 6000 lbs. tension. EOT 2					φ \circ
5/15/13					√. <u> </u>
RIH with pump and rods. Spaced ou	ut rods and HWO: rigged d	own rig. (Cleaned location. Re	estore power to we	Il and pressure pump to 500
PSI. OK	, 33	8			1 1
I be and a service when the information	.1			11 1 6	
I hereby certify that the information	above is true and complete	e to the be	est of my knowledge	e and belief.	
\bigcirc . \bigcirc	` ^ <				
SIGNATURE	TITL Vellat	E Regu	ılatory Affairs Coo	ordinator DATE	E_05/16/2013
Type or print name CARIE STO	OKFR F-mail address:	cstoker	@helmsoil.com	PHONE: 432-6	64_7659
P)	D-man address.	. <u>cstoκer</u>	a C	1110NL. 432-0	" 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
APPROVED BY:	<u>W</u> TITLI	E() 5-2	Capewist?	D/	ATENULY 24,2013
Conditions of Approval (if any):	•		•	The second	— ·
				IMECE	IVED
				JUL 2	1 2010
				1 301 24	± 2013
				NMOCD A	BTESIA