

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-64150
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Ponderosa Petroleum Corporation		6. State Oil & Gas Lease No. VB-1234
3. Address of Operator P.O. Box 132, Roswell, NM 88202		7. Lease Name or Unit Agreement Name Easy State
4. Well Location Unit Letter C : 330 feet from the N line and 1650 feet from the W line Section 22 Township 11S Range 27E NMPM County Chaves		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3727 GR		9. OGRID Number 248481
		10. Pool name or Wildcat Coyote Queen

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) Ran tubing to 975'. Circ. hole & spot 40 sx. cement. Pull tubing.
- 2) WOC 24 hours. Ran tubing & tagged @ 335'. Spot 30 sx. cement from 335' to surface. Pulled tubing. Top off to surface again with 5 sx.
- 3) Install dry hole marker & clean location. Work completed 6/6/13

Spud Date:

Rig Release Date:

Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms: www.cdmr.state.nm.us/oed.

RECEIVED

JUL 31 2013

NM OCD ARTESIA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE President

DATE 6/26/13

Type or print name Fred F. Pool, III

E-mail address: sspool@cableone.net PHONE 575-623-4667

For State Use Only

APPROVED BY:

TITLE District Supervisor

DATE Aug 1, 2013

Conditions of Approval (if any):

* File Subsequent C-103 for final inspection