Office Office	State of N			Form C-103			
<u>District I</u> – (575) 393-6161	Energy, Minerals a	and Natu	iral Resources	Revised July 18, 2013			
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-015-27235						
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERV	<b>ATION</b>	5. Indicate Type of Lease				
<u>District III</u> - (505) 334-6178	1220 South	St. Frat	ncis Dr.	STATE FEE			
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe	6. State Oil & Gas Lease No.					
1220 S. St. Francis Dr., Santa Fe, NM		,		E.10083			
87505							
l .	ES AND REPORTS ON			7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA	Indian Hill=St.Com.						
PROPOSALS.)	Gas Well  Other			8. Well Number			
1. Type of Well: Oil Well 2. Name of Operator		9. OGRID Number					
		192463					
3. Address of Operator	VTP Limited Partnership			10. Pool name or Wildcat			
	250 Midland, TX 7971	0					
4. Well Location				Cemetary Wolfcamp			
I .	1880 feet from the	40.1	<u></u>	660 feet from the west line			
Section 34	Township 20			NMPM County FdLy			
	11. Elevation (Show whe		RKB, RT, GR, etc.				
		634					
12. Check Ap	propriate Box to Ind	licate N	ature of Notice,	Report or Other Data			
· · · · · · · · · · · · · · · · · · ·							
NOTICE OF INT				SEQUENT REPORT OF:			
PERFORM REMEDIAL WORK 🗌	PLUG AND ABANDON		REMEDIAL WOF	<del></del>			
TEMPORARILY ABANDON	TEMPORARILY ABANDON						
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMEN	TJOB 🗌			
DOWNHOLE COMMINGLE							
CLOSED-LOOP SYSTEM							
OTHER:			OTHER:				
13. Describe proposed or comple	ted operations. (Clearly	state all p	pertinent details, an	d give pertinent dates, including estimated date			
- · · · · ·	The state of the s	4 NMAC	C. For Multiple Co	mpletions: Attach wellbore diagram of			
proposed completion or recor	npletion.	·					
TD-9600'	PBTD-6589' Perfs-6	622-6636	6' CIBP-6589'				
9-	5/8" 36# csg @ 1220' w/	1100sx,	12-1/4" hole, TOC-	Surf-Circ .			
7"	23-26# csg @ 7999', DV	T @ 5592	2' w/ 1100sx, 8-3/4	4" hole, <u>TOC-Surf-Circ</u>			
1. RIH &		improved for plugging of well bore only.					
2. M&P 3		<ul> <li>mility under bond is retained pending receipt</li> <li>C 103 (Subsequent Report of Well Plugging)</li> </ul>					
	30sx cmt @ 4360-4260' V			which may be found at OCD Web Page under			
	35sx cmt @ 2370-2225' V	_	چ د	Forms, www.cmnrd.state.nm.us oed.			
	25sx cmt @ 1250-1150' V			TUNIDITIONS OF THE PROPERTY OF			
	70sx @ 300' to surface	100 106		CONDITIONS OF APPROVAL ATTACHED			
	MLF between plugs						
	ound steel tanks will be	utilized	•	Approval Granted providing work is			
Above gi	outiu steet taliks will be	utmzcu.		Completed by g			
				Dept 12, 2014			
Spud Date:	Rig Ro	elease Da	ite:	19 (II terret a variante de la companya de la compa			
			L				
I hereby certify that the information at	ove is true and complete	to the he	est of my knowledg	e and belief			
2 norsely control man and minormation at	ove is true una complete	to the be	or or my knowledg	o una benen			
SIGNATURE .	TITLE	E Sr.	Regulatory Adviso	DATE 82713			
Type or print nameDavid Stewart_	E-mail a	address:	david stewart@	@oxy.com PHONE:432-685-5717			
For State Use Only		٨					
M/I	$\cap$	/\	TPC an	· A alashan			
APPROVED BY / / UU	TITLE	NIN	# Spen 1	DATE 7/88/DOLS			
Conditions of Approval (if any):	/ 40 40 4		•	' /			
# See AHAC	md (1/1)4						
Y JET /TIME							

OXY USA WTP LP - Proposed Indian Hills State Com. #4

API No. 30-015-27235 70sx @ 300'-Surface 12-1/4" hole @ 1220' 9-5/8" csg @ 1220' w/ 1100sx-TOC-Surf-Circ 25sx @ 1250-1150' WOC-Tag 35sx @ 2370-2225' WOC-Tag 30sx @ 4360-4260' WOC-Tag 30sx @ 5642-5542' WOC-Tag 25sx @ 6589' 2010-CIBP @ 6589' Perfs @ 6622-6636' 2004-50sx @ 7602-7178' Perfs @ 7516-7746' sqz w/ 525sx 8-3/4" hole @ 8000' 2004-25sx @ 8050-7850' 7" csg @ 7999' DVT @ 5592' w/ 1100sx-TOC-Surf-Circ 4-3/4" OH @ 8000-9600' 2004-25sx @ 9104-8915'

OXY USA WTP LP - Current Indian Hills State Com. #4 API No. 30-015-27235

TD-9600'

12-1/4" hole @ 1220' 9-5/8" csg @ 1220' w/ 1100sx-TOC-Surf-Circ

2010-CIBP @ 6589'

2004-50sx @ 7602-7178'

2004-25sx @ 8050-7850'

2004-25sx @ 9104-8915'

Perfs @ 6622-6636'

Perfs @ 7516-7746' sqz w/ 525sx

8-3/4" hole @ 8000' 7" csg @ 7999' DVT @ 5592' w/ 1100sx-TOC-Surf-Circ

4-3/4" OH @ 8000-9600'

## NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

## CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operato	r: Oxy	USA	WTP	CP			
Well Na	me & Num	ber: <u>&amp;v</u>	rdian 1	4115	5%	Com	4
API #:	30 - 0/3	V-27	<i>a</i> 35				

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.

11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: Sept 12, 2013

APPROVED BY:

## GUIDELINES FOR PLUGGING AND ABANDONMENT

## DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
  - o Fusselman
  - o Devonian
  - o Morrow
  - o Wolfcamp
  - o Bone Spring
  - o Delaware
  - Any Salt Section (Plug at top and bottom)
  - o Abo
  - o Glorieta
  - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).