Form 3160-5 (August 2007) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS					OMB N	APPROVED O: 1004-0135 July 31, 2010
					5. Lease Serial No. NMNM98122	
Do not use thi abandoned we	s form for proposals to I. Use form 3160-3 (AF	o drill or to re-e PD) for such pr	oposals.	ļ.	5. If Indian, Allottee of	or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or N	
I. Type of Well Oil Well Gas Well Other: INJECTION					8. Well Name and No. SKELLY UNIT 16	
2. Name of Operator	Contact:	TERRY B CAI	LAHAN		. API Well No.	
LINN OPERATING INC	E-Mail: Icallahan((include area code)	· · ·	30-015-05334	Exploratory
600 TRAVIS STREET, SUITE HOUSTON, TX 77002	5100	Ph: 281-840	-4000		GRAYBURG J	ACKSON;SR-1-G
4. Location of Well (Footage, Sec., T					11. County or Parish,	and State
Sec 21 T17S R31E Mer NMP 32.814637 N Lat, 103.876823		VL.	•		EDDY COUNT	Y, NM
12. CHECK APPI	ROPRIATE BOX(ES) T	O INDICATE	NATURE OF 1	NOTICE, REI	PORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
8 Notice of Intent	C Acidize	🗖 Deep		—	n (Start/Resume)	U Water Shut-C
Subsequent Report	Alter Casing Casing Repair	. —	ure Treat Construction	Reclamat Recomple		Well Integrit Other
☐ Final Abandonment Notice	Change Plans		and Abandon		ily Abandon	Workover Oper
	Convert to Injection			U Water Di		
testing has been completed. Final A determined that the site is ready for f Procedure:	inal inspection.) -	filed only after all r	completion or reconcentric completion or reconcentric completion of the second se	ling reclamation,	have been completed	, and the operator has
determined that the site is ready for f Procedure: 1. Test anchors prior to riggin 2. MIRU WO rig and record ca 3. Bleed pressure off of well. 4. NU BOP. 5. Unseat packer and POOH	inal inspection.) g up. asing and tubing pressur w/ tubing and packer.	filed only after all r re.	equirements, inclue	ling reclamation,	Accepted	and the operator has
determined that the site is ready for f Procedure: 1. Test anchors prior to riggin 2. MIRU WO rig and record ca 3. Bleed pressure off of well. 4. NU BOP.	inal inspection.) g up. asing and tubing pressur w/ tubing and packer. and retrievable bridge plu Test backside (tbg/csg a lidn?t hold.	filed only after all r re. ug (Set BP at 2 annulus) to 500	equirements, inclue 120). osi. Contact En	ling reclamation, d gr with results	have been completed ACCONNECTION PORCE	and the operator has or record 10/16/2 enment Sha m is Acco
determined that the site is ready for f Procedure: 1. Test anchors prior to riggin 2. MIRU WO rig and record c 3. Bleed pressure off of well. 4. NU BOP. 5. Unseat packer and POOH 6. RIH w/ workstring, packer a 7. Test against BP to 500psi. and discuss plan if pressure c 8. If csg tests ok. RIH with ar Set PKR at 2120?	inal inspection.) g up. asing and tubing pressur and retrievable bridge plu Test backside (tbg/csg a lidn?t hold. rowset 8 5/8? injection p s true and correct. Electronic Submission	filed only after all r re. annulus) to 500 okr and on off to	120). ot on 2-3/8? IP	ling reclamation, gr with results C tubing.	have been completed Accepted Dave Dave This For For Record	and the operator has or record 10/16/5 enment 54 m is Acc
determined that the site is ready for f Procedure: 1. Test anchors prior to riggin 2. MIRU WO rig and record c 3. Bleed pressure off of well. 4. NU BOP. 5. Unseat packer and POOH 6. RIH w/ workstring, packer a 7. Test against BP to 500psi. and discuss plan if pressure c 8. If csg tests ok. RIH with an Set PKR at 2120? 9. RDMO	inal inspection.) g up. asing and tubing pressur and retrievable bridge plu Test backside (tbg/csg a lidn?t hold. rowset 8 5/8? injection p s true and correct. Electronic Submission. For LINN	filed only after all r re. annulus) to 500 okr and on off to #218530 verifier	equirements, inclue 120). Ssi. Contact En ot on 2-3/8? IP t by the BLM We C, sent to the C	ling reclamation, gr with results C tubing. Il information arlsbad	have been completed Accepted Dave Dave This For For Record	and the operator has CH RECOVIC 10/16/2 RAMMENT SHA M is Accel
determined that the site is ready for f Procedure: 1. Test anchors prior to riggin 2. MIRU WO rig and record ca 3. Bleed pressure off of well. 4. NU BOP. 5. Unseat packer and POOH 6. RIH w/ workstring, packer a 7. Test against BP to 500psi. and discuss plan if pressure of 8. If csg tests ok. RIH with ar Set PKR at 2120? 9. RDMO 14. Thereby certify that the foregoing i Name (Printed/Typed) TERRY B	inal inspection.) g up. asing and tubing pressur and retrievable bridge plu Test backside (tbg/csg a lidn?t hold. rowset 8 5/8? injection p s true and correct. Electronic Submission. For LINN	filed only after all r re. annulus) to 500 okr and on off to #218530 verifier	equirements, inclue 120). Ssi. Contact En ot on 2-3/8? IP t by the BLM We C, sent to the C	ling reclamation, d gr with results C tubing. Il Information arlsbad	have been completed ACCENTER IN PORCE This Four This Four For Record	and the operator has or record 10/16/5 enment 54 m is Acc
determined that the site is ready for f Procedure: 1. Test anchors prior to riggin 2. MIRU WO rig and record ca 3. Bleed pressure off of well. 4. NU BOP. 5. Unseat packer and POOH 6. RIH w/ workstring, packer a 7. Test against BP to 500psi. and discuss plan if pressure of 8. If csg tests ok. RIH with ar Set PKR at 2120? 9. RDMO 14. Thereby certify that the foregoing i Name (Printed/Typed) TERRY B	inal inspection.) g up. asing and tubing pressur w/ tubing and packer. and retrievable bridge plu Test backside (tbg/csg a lidn?t hold. rowset 8 5/8? injection p s true and correct. Electronic Submission For LINN & CALLAHAN	filed only after all r re. annulus) to 500 okr and on off to #218530 verifier OPERATING IN	equirements, inclue (120). Disi. Contact En of on 2-3/87 IP by the BLM We C, sent to the C Title REG C Date 08/29/2	ling reclamation, gr with results C tubing. Il Information arlsbad	have been completed ACCONNECT IN Part of Cover This For For Record System SPECIALIST III	and the operator has or record 10/16/5 enment 54 m is Acc
determined that the site is ready for f Procedure: 1. Test anchors prior to riggin 2. MIRU WO rig and record ca 3. Bleed pressure off of well. 4. NU BOP. 5. Unseat packer and POOH 6. RIH w/ workstring, packer a 7. Test against BP to 500psi. and discuss plan if pressure of 8. If csg tests ok. RIH with an Set PKR at 2120? 9. RDMO 14. Thereby certify that the foregoing i Name (Printed/Typed) TERRY B Signature (Electronic	inal inspection.) g up. asing and tubing pressur and retrievable bridge plu Test backside (tbg/csg a lidn?t hold. rowset 8 5/8? injection p s true and correct. Electronic Submission For LINN & CALLAHAN Submission)	filed only after all r re. annulus) to 500 okr and on off to #218530 verifier OPERATING IN	120). osi. Contact En ot on 2-3/87 IP t by the BLM We C, sent to the C Title REG C Date 08/29/ L OR STATE	ling reclamation, gr with results C tubing. Il Information arlsbad	have been completed ACCONNECT IN Part of Cover This For For Record System SPECIALIST III	and the operator has the cost of the cost
determined that the site is ready for f Procedure: 1. Test anchors prior to riggin 2. MIRU WO rig and record ca 3. Bleed pressure off of well. 4. NU BOP. 5. Unseat packer and POOH 6. RIH w/ workstring, packer a 7. Test against BP to 500psi. and discuss plan if pressure of 8. If csg tests ok. RIH with ar Set PKR at 2120? 9. RDMO 14. Thereby certify that the foregoing i Name (Printed/Typed) TERRY B Signature (Electronic 	inal inspection.) g up. asing and tubing pressur w/ tubing and packer. and retrievable bridge plu Test backside (tbg/csg a lidn?t hold. rowset 8 5/8? injection p s true and correct. Electronic Submission For LINN & CALLAHAN Submission) THIS SPACE F	Filed only after all r re. annulus) to 500 okr and on off to W218530 verifier OPERATING IN	equirements, inclue (120). Disi. Contact En of on 2-3/87 IP by the BLM We C, sent to the C Title REG C Date 08/29/2	ling reclamation, gr with results C tubing. Il Information arlsbad	have been completed ACCONNECT IN Part of Cover This For For Record System SPECIALIST III	and the operator has or record 10/16/3 enment 54 m is Acc
determined that the site is ready for f Procedure: 1. Test anchors prior to riggin 2. MIRU WO rig and record ca 3. Bleed pressure off of well. 4. NU BOP. 5. Unseat packer and POOH 6. RIH w/ workstring, packer a 7. Test against BP to 500psi. and discuss plan if pressure of 8. If csg tests ok. RIH with an Set PKR at 2120? 9. RDMO 14. Thereby certify that the foregoing i Name (Printed/Typed) TERRY B Signature (Electronic	inal inspection.) g up. asing and tubing pressur w/ tubing and packer. and retrievable bridge plu Test backside (tbg/csg a lidn?t hold. rowset 8 5/8? injection p s true and correct. Electronic Submission For LINN I CALLAHAN Submission) THIS SPACE F ed. Approval of this notice do juitable title to those rights in.	Filed only after all r re. annulus) to 500 okr and on off to W218530 verifier OPERATING IN	120). osi. Contact En ot on 2-3/87 IP t by the BLM We C, sent to the C Title REG C Date 08/29/ L OR STATE	ling reclamation, gr with results C tubing. Il Information arlsbad	have been completed ACCONNECT IN Part of Cover This For For Record System SPECIALIST III	and the operator has the cost of the cost
determined that the site is ready for f Procedure: 1. Test anchors prior to riggin 2. MIRU WO rig and record ca 3. Bleed pressure off of well. 4. NU BOP. 5. Unseat packer and POOH 6. RIH w/ workstring, packer a 7. Test against BP to 500psi. and discuss plan if pressure of 8. If csg tests ok. RIH with ar Set PKR at 2120? 9. RDMO 14. Thereby certify that the foregoing i Name (<i>Printed/Typed</i>) TERRY B Signature (Electronic 	inal inspection.) g up. asing and tubing pressur w/ tubing and packer. and retrievable bridge plu Test backside (tbg/csg a lidn?t hold. rowset 8 5/8? injection p s true and correct. Electronic Submission For LINN CALLAHAN Submission) THIS SPACE F ed. Approval of this notice do juitable title to those rights in uct operations thereon.	Filed only after all r re. (Set BP at 2, annulus) to 500 okr and on off to OPERATING IN FOR FEDERA FOR FEDERA	120). 120). 120). 120). 120). 120. 1	ling reclamation, d gr with results C tubing. Il Information arlsbad CMPLIANCE 2013 OFFICE US	have been completed Accepted Development Je to Gover this for For Record System SPECIALIST III	and the operator has Of recOrd Penmout 544 m is Acc Date
determined that the site is ready for f Procedure: 1. Test anchors prior to riggin 2. MIRU WO rig and record ca 3. Bleed pressure off of well. 4. NU BOP. 5. Unseat packer and POOH 6. RIH w/ workstring, packer a 7. Test against BP to 500psi. and discuss plan if pressure of 8. If csg tests ok. RIH with ar Set PKR at 2120? 9. RDMO 14. Thereby certify that the foregoing i Name (Printed/Typed) TERRY E Signature (Electronic 	inal inspection.) g up. asing and tubing pressur w/ tubing and packer. and retrievable bridge plu Test backside (tbg/csg a lidn?t hold. rowset 8 5/8? injection p s true and correct. Electronic Submission. For LINN CALLAHAN Submission) THIS SPACE F ed. Approval of this notice do uitable title to those rights in. uct operations thereon. U.S.C. Section 1212, make in statements or representations	Filed only after all r re. (Set BP at 2, annulus) to 500 okr and on off to (OPERATING IN FOR FEDERA FOR FEDERA (Set BP at 2, annulus) to 500 okr and on off to (Set BP at 2, annulus) to 500 okr and (Set BP at 2, annulus) to 500 okr and (Set BP at 2, annulus) to 500 okr annulus) to 500 okr annulus (Set BP at 2, annulus) to 500 okr annulus (Set BP at 2, annulus) to 500 okr annulus (Set BP at 2, annulus (Set	120). 120). 120). 1 by the BLM We 1 by the BLM We 1 by the BLM We 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 co	ling reclamation, d gr with results C tubing. Ill Information arlsbad COMPLIANCE 2013 OFFICE US OFFICE US	have been completed Accepted Development be to Gover this for for Kecorc System SPECIALIST III EE	and the operator has CH RECORCI ID /16/2 RNMaut 544 M is Acco Date Date
determined that the site is ready for f Procedure: 1. Test anchors prior to riggin 2. MIRU WO rig and record ca 3. Bleed pressure off of well. 4. NU BOP. 5. Unseat packer and POOH 6. RIH w/ workstring, packer a 7. Test against BP to 500psi. and discuss plan if pressure of 8. If csg tests ok. RIH with ar Set PKR at 2120? 9. RDMO 14. Thereby certify that the foregoing i Name (Printed/Typed) TERRY E Signature (Electronic 	inal inspection.) g up. asing and tubing pressur w/ tubing and packer. and retrievable bridge plu Test backside (tbg/csg a lidn?t hold. rowset 8 5/8? injection p s true and correct. Electronic Submission For LINN CALLAHAN Submission) THIS SPACE F ed. Approval of this notice do juitable title to those rights in uct operations thereon.	Filed only after all r re. (Set BP at 2, annulus) to 500 okr and on off to (OPERATING IN FOR FEDERA FOR FEDERA (Set BP at 2, annulus) to 500 okr and on off to (Set BP at 2, annulus) to 500 okr and (Set BP at 2, annulus) to 500 okr and (Set BP at 2, annulus) to 500 okr annulus) to 500 okr annulus (Set BP at 2, annulus) to 500 okr annulus (Set BP at 2, annulus) to 500 okr annulus (Set BP at 2, annulus (Set	120). 120). 120). 1 by the BLM We 1 by the BLM We 1 by the BLM We 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 by the BLM We 2 c, sent to the C 1 con 2-3/87 IPO 1 co	ling reclamation, d gr with results C tubing. Ill Information arlsbad COMPLIANCE 2013 OFFICE US OFFICE US	have been completed Accepted Development be to Gover this for for Kecorc System SPECIALIST III EE	and the operator has or record renmant 544 m is Acc Date Date

Skelly 16

EDDY COUNTY, NM

30-015-05334

8/21/2013

Project Scope: POH w/ Tbg and Pkr, locate and repair problem and RTI.

Procedure:

- 1. Test anchors prior to rigging up.
- 2. MIRU WO rig and record casing and tubing pressure.
- 3. Bleed pressure off of well.
- 4. NU BOP.
- 5. Unseat packer and POOH w/ tubing and packer.
- 6. RIH w/ workstring, packer and retrievable bridge plug (Set BP at 2,120).
- 7. Test against BP to 500psi. Test backside (tbg/csg annulus) to 500psi. Contact Engr with results and discuss plan if pressure didn't hold.
- 8. If csg tests ok. RIH with arrowset 8 5/8" injection pkr and on off tool on 2-3/8" IPC tubing. Set PKR at 2120
- 9. RDMO
- 10. RTI

Contact Information:

Briklynd – Asset Engineer Ceil – 832-723-4867 Office – 281-840-4275

Joe Hernandez - Foreman Cell - 575-942-9492