Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Artesia

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

5. Lease Scrial No. NMLC050797

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well Oil Well □ □ Gas Well □ □ Other					8. Well Name and No. Russell USA #068 9. API Well No.	
2. Name of Operator Apollo Energy, LP						
ia Address 120 W. Pujo St. Suite 300 Lake	3b. Phone No. (include area code) 337-502-5227		30-015-20463 10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					Russell Field	
Section 12, T20S, R28E 10 FSL & 1980 FEL					11. County or Parish, State Eddy County, New Mexico	
12. CHECK AF	PPROPRIATE BOX(ES) T	O INDICATE NATUR	E OF NOTICE, R	EPORT, OR	OTHER DATA	
TYPE OF SUBMISSION						
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (State Reclamation Recomplete Temporarily At Water Disposal		Water Shut-Off Well Integrity Other	

- If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)
 - 1. RIH with 2" pipe to bottom of casing
 - 2. Pump Class "C" Cement until full returns to surface
 - 3. POOH with 1" and wait 15 minutes and monitor well for fall back
 - 4. Top out well with cement
 - 5. Install 4" P & A marker per BLM requirements

RECLAMATION PROCEDURE ATTACHED

Tag Bottom of well bore, circulate cement to surface. At cut-off verify cement to surface on all annulus. If not take remedial action.

10/23/13 cceated for rea

APPROVED

SEP 3 0 2013 /s/ JD Whitlock Jr

BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. Thereby certify that the foregoing is true and correct Name (Printed/Typed)								
Thomas G. Wright	Title	Executive Vice President						
Signature This high	Date	05/31/2013	· .	MECEIVED				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by		Title	Date	NMOCD ARTES				
Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject lewhich would entitle the applicant to conduct operations thereon.		Office						
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to anymatic	person	knowingly and willfully to make to	any departme	ent or agency of the United				

(Instructions on page 2)

