

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMNM0354232

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side.7. If Unit or CA/Agreement, Name and/or No.
SRM1145

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other8. Well Name and No.
ELIZONDO A 3

2. Name of Operator

OXY USA WTP LIMITED PTNRSHIP E-Mail: david_stewart@oxy.com

Contact: DAVID STEWART

9. API Well No.
30-015-21930-00-S1

3a. Address

MIDLAND, TX 79710-0250

3b. Phone No. (include area code)

Ph: 432-685-5717

Fx: 432-685-5717

10. Field and Pool, or Exploratory
UNDESIGNATED

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 20 T21S R27E SESW

11. County or Parish, and State

EDDY COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☒ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

TD-11690' PBTD-11650' Perfs 11025-11424'

OXY USA WTP LP respectfully requests a 2 year temporary abandonment of this well for further evaluation of possible recompletion potential. Oxy has begun implementing a project to evaluate the recompletion potential of the Strawn/Penn and Wolfcamp formations in the Burton Flats area. The project entails recompleting one well and analyzing the results to prove viability in the area. The recompletion program involves inspecting wellbore casing integrity, completing the well with a multiple stage fracture design and testing the formations potential. The completion of the first well is currently planned for the first quarter 2014. From the results of the project, Oxy will evaluate and determine the potential for recompletion of this well. Additional information can be provided upon request.

RECEIVED

DEC 16 2013

NMOCD ARTESIA

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

Accepted for record

NMOCD RF 12/19/13

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #219860 verified by the BLM Well Information System

For OXY USA WTP LIMITED PTNRSHIP, sent to the Carlsbad

Committed to AFMSS for processing by KURT SIMMONS on 09/18/2013 (13KMS7287SE)

Name (Printed/Typed) DAVID STEWART

Title SR. REGULATORY ADVISOR

Signature (Electronic Submission)

Date 09/12/2013

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By JAMES A AMOS

Title SUPERVISOR EPS

Date 12/09/2013

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Carlsbad

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.


** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #219860 that would not fit on the form

32. Additional remarks, continued

1. POOH w/ prod equipment, RIH & set CIBP @ +/-10975'.
2. Notify BLM/NMOCD of casing integrity test 24hrs in advance.
3. RU pump truck, circulate well with treated water, pressure test casing to 500# for 30 min.

OXY USA WTP LP - Proposed
Elizondo A Federal #3
API No. 30-015-21930



17-1/2" hole @ 600'
13-3/8" csg @ 600'
w/ 1075sx-TOC-Surf-Circ

12-1/4" hole @ 3000'
8-5/8" csg @ 3000'
w/ 1500sx-TOC-Surf-Circ

7-7/8" hole @ 11690'
5-1/2" csg @ 11690'
w/ 750sx-TOC-8295'-TS


Perfs @ 11025-11162'
Perfs @ 11265-11424'

CIBP @ 10975'

PB-11650'

TD-11690'

OXY USA WTP LP - Current
Elizondo A Federal #3
API No. 30-015-21930



17-1/2" hole @ 600'
13-3/8" csg @ 600'
w/ 1075sx-TOC-Surf-Circ

12-1/4" hole @ 3000'
8-5/8" csg @ 3000'
w/ 1500sx-TOC-Surf-Circ

7-7/8" hole @ 11690'
5-1/2" csg @ 11690'
w/ 750sx-TOC-8295'-TS

Perfs @ 11025-11162'
Perfs @ 11265-11424'

2-7/8" tbg w/ pkr @ 10940'

PB-11650'

TD-11690'

BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972

Temporary Abandonment of Wells on Federal Lands
Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. The bridge plug is to be capped with 35 feet of cement (if bailed) or 25 sacks (if placed with tubing). If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
3. **Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.**

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
2. Describes the temporary abandonment procedure.
3. Attaches a clear copy or the original of the pressure test chart.
4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

1. A procedure to repair the casing so that a TA approval can be granted.
2. A procedure to plug and abandon the well.

Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 1 year after successful MIT and subsequent report is submitted.