Form 3160-5

INITED STATES

CD Artesia	FORM APPROVE			
	OMB NO. 1004-013			
	Expires: July 31, 20			

	CPARTMENT OF THE INTERIOR				OMB NO. 1004-0135 Expires: July 31, 2010		
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS				5. Lease Serial No. NMNM67980			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well					8. Well Name and No. SANTA FE FEDERAL 4		
2. Name of Operator Contact: JODY NOERDLINGER RKI EXPLORATION & PRODUCTIONE-Mail: jnoerdlinger@rkixp.com					9. API Well No.		
3a. Address	PUCTION E-Mail: jnoerdlinge		. (include area code)	· · · · · ·	30-015-27030	Evalorators	
210 PARK AVENUE, SUITE S OKLAHOMA CITY, OK 7310	Ph: 405-99 Fx: 405-996	6-5774	·	10. Field and Pool, or Exploratory EAST HERRADURA BEND, DELA			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			· · · · · · · · · · · · · · · · · · ·		11. County or Parish, and State		
Sec 35 T22S R28E Mer NMP SENE 1730FNL 910FEL					EDDY COUNTY COUNTY, NM		
12. CHECK APP	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF 1	NOTICE, R	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	☐ Acidize ☐ Alter Casing	☐ Dee	pen ture Treat	☐ Produc	ction (Start/Resume)	☐ Water Shut-Off ☐ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	_	Construction	Recom Recom	-	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☐ Plug ☐ Plug	gand Abandon gBack	☐ Tempo	orarily Abandon Disposal		
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for formation on the approximate A CIBP will be set at 5,900 fee. These intervals will be perfed 3,403 ? 3,408 feet 3,638 ? 3,648 feet 5,621 ? 5,623 feet	ally or recomplete horizontally, rk will be performed or provide of operations. If the operation rebandonment Notices shall be fil inal inspection.) on seeks approval to feed date of February 15, 201. et, with a 35 foot cement pand completed:	give subsurface the Bond No. outside in a multiple donly after all dependent of the Bond No. outside in a multiple donly after all dependent of the Bond No. outside in the Bo	locations and measurable with BLM/BLA e completion or recorded in the block of the	red and true v. Required si mpletion in a ing reclamatio	retrical depths of all pertin absequent reports shall be new interval, a Form 316 on, have been completed, a	ent markers and zones. filed within 30 days 0-4 shall be filed once and the operator has	
5,665 ? 5,685 feet	NMOCD19	MWOCI FEB	0 3 2014 D ARTESIA	<u>/ </u>			
14. I hereby certify that the foregoing is	true and correct. Electronic Submission # For RKI EXPLORA Committed to AFMSS t	231631 verifie ATION & PRO	d by the BLM We DUCTION, sent to by DEBORAH H	ll Informatio the Carlsb AM on 01/27	ad //2014 ()		
Name (Printed/Typed) JODY NO	ERDLINGER		Title REGUL	ATORY AN	IALYST		
Signature (Electronic S	Submission)	<u> </u>	Date 01/09/2	014 F	ALLUAREN		
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	18/E 114 N - 2 2/2014		
_Approved By			Title	b	mula	1000	
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	uitable title to those rights in the	not warrant or subject lease	Office	BUREA CA	NU OF LAWI MANAGE RLSBAD FIELD OFFIC	MENT V	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and winfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Santa Fe Federal 4 30-015-27030 Apache Corporation January 28, 2014 Conditions of Approval

Work to be completed by April 28, 2014.

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

- 1. Must conduct a casing integrity test to max treating pressure before any perforating or fracturing can be done. Submit results to BLM. Contact the BLM if test fails.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a **2000** (**2M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done and completion report for the new formation. Operator to include well bore schematic of current well condition when work is complete.

JAM 012814