SUNDRY	NOTICES AND REPORT	5. Lease Serial No. NMNM111946	s: July 31, 2010				
Do not use the abandoned we	6. If Indian, Allottee or Tribe Name						
SUBMIT IN TR	IPLICATE - Other instruction	ns on reverse side.		7. If Unit or CA/Ag	reement, Name and/or No.		
1. Type of Well	her			8. Well Name and No TOMBSTONE F			
2. Name of Operator COG OPERATING LLC		NICIA CASTILLO choresources.com		9. API Well No. 30-015-33554	9 338960		
3a. Address ONE CONCHO CENTER 600 MIDLAND, TX 79701		 Phone No. (include area co h: 432-685-4332 	de)	10. Field and Pool, c CEMETARY M	or Exploratory		
4. Location of Well (Footage, Sec., 2	T., R., M., or Survey Description)			11. County or Parish	, and State		
Sec 35 T19S R25E Mer NMP	9 660FSL 1650FEL			EDDY COUNT	ΓΥ, NM		
· · · · · · · · · · · · · · · · · · ·							
12. CHECK APP	ROPRIATE BOX(ES) TO IN	DICATE NATURE OF	F NOTICE, R	EPORT, OR OTHI	ER DATA		
TYPE OF SUBMISSION		ТҮРЕ	OF ACTION	·	·····		
🛛 Notice of Intent		Deepen		tion (Start/Resume)	Water Shut-Off		
Subsequent Report	□ Alter Casing	Fracture Treat	🗖 Reclam		U Well Integrity		
Final Abandonment Notice	 Casing Repair Change Plans 	New Construction Plug and Abandon	C Recom	mplete Dorarily Abandon			
	Convert to Injection	Plug Back	U Tempo	-			
 If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for f COG Operating LLC respectfr as an oil well. Please see attached procedur 1.) MIRU CU. Load hole. NI 2.) Rig up wireline. RIH with 2??? 4.) Perforate Bone Spring with following intervals: 6542??, 6562??, 6575??, 658 6746??, 6755?? 14. Thereby certify that the foregoing is Name (Printed/Typed) KANICIA 	d operations. If the operation results bandonment Notices shall be filed of final inspection.) ully requests to recomplete to re. D wellhead, NU BOP. TOH w CIBP and set at 9420??. Dur ? tubing to PBTD. Circulate h n 3???? casing guns, premiur 39??, 6596??, 6603??, 6613?	in a multiple completion or r nly after all requirements, incl the Bone Spring and re ith tubing, laying down. np 35?? of cement on p hole with 3% KCI water. n charges, 120⁰ ?, 6624??, 6710??, 672	ecompletion in a uding reclamatio classify this w TOH. phasing, 3 SF 20??, 6734??,	new interval, a Form 31 n, have been completed ACCE ell FE ATTACH 6540???, n System	60-4 shall be filed once and the operator has option for record NMOCD 194-1 ED FOR ED FOR S OF APPROVAT RECEIVED FEB 03 2014		
Name (Printed/Tuned) KANICIA	Committed to AFMSS for proc	essing by JOHNNY DICK	ERSON on 01/	17/2014 ()			
Hamer Handar Spear MANICIA				ADDRA	VED		
Signature (Electronic S	Submission)	Date 12/18	/2013	AFTINO	VLD		
	THIS SPACE FOR I	FEDERAL OR STATE	E OFFICE U	SE ANN 20	2011212		
Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu Title 18 U.S.C. Section 1001 and Title 43	uitable title to those rights in the subjuct operations thereon.	office	ad willfully to m	//CARLSBADIE			
States any false, fictitious or fraudulent	statements or representations as to ar	by matter within its jurisdictio	n.				

۸

¥

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

CA 1/28/14

Additional data for EC transaction #230014 that would not fit on the form

32. Additional remarks, continued

٠

¥

Rig down wireline.
5.) TIH with tubing and tension packer. Set packer at 6500??. Swab well and report results.
6.) Rig up a pumping service company. Acidize interval with 3000 gallons of 15% HCl and 72 ball sealers at 5 BPM. Over displace 5 bbls.
7.) Swab back load.
8.) If shows warrant, move in pumping service company to frac the Bone Spring
9.) Flow back frac
10.) Install artificial lift.

Tombstone Fed #1

7

1.) MIRU CU. Load hole. ND wellhead, NU BOP. TOH with tubing, laying down.

- 2.) Rig up wireline. RIH with CIBP and set at 9420'. Dump 35' of cement on plug.
- 3.) Pick up and TIH with 2%" tubing to PBTD. Circulate hole with 3% KCl water. TOH.
- 4.) Perforate Bone Spring with 3¹/₄" casing guns, premium charges, 120^o phasing, 3 SPF in the following intervals:

6542', 6562', 6575', 6589', 6596', 6603', 6613', 6624', 6710', 6720', 6734', 6740', 6746', 6755'

Rig down wireline.

- 5.) TIH with tubing and tension packer. Set packer at 6500'. Swab well and report results.
- 6.) Rig up a pumping service company. Acidize interval with 3000 gallons of 15% HCl and 72 ball sealers at 5 BPM. Over displace 5 bbls.
- 7.) Swab back load.
- 8.) If shows warrant, move in pumping service company to frac the Bone Spring
- 9.) Flow back frac
- 10.) Install artificial lift.

Cemetery

Tombstone Federal #1 Current

PBTD 9947'

DV

6860'

No. of Canada


	Location:	
Footage:	660' FSL & 1650' FEL	
Section:	35	
Township	19S	
Range	25E	
County:	Eddy	
Elevations:		
GL:	3456	
KB:	3473	
KB Calc:	17	
BHL		

Field

istory		
4/25/05	completed	
5/3/05	Set CIBP @ 9560'	
7/18/05	Sec cement retainer at 9500', sqzd perfs 9522-24 with 50 sx.	
		1
		المنتخب
	CURRENT	
	Tubing Ostail (Ass to bettern)	

	CURRENT			
	Tubing Detail (top to bottom)			
Joints	Description	Footage	Depth	
	KB			
	2 3/8" tubing at 9373' (open ended)			
	······································			

			<u> </u>
	Rod Detail (top to bottom)		
· · · · ·		1 1	
Rods	Description	Footage	Depth



.

Cemetery

Field

Tombstone Federal #1 PROPOSED

Z


States and the

	Location:	
Footage:	660' FSL & 1650' FEL	
Section:	35	
Township	195	
Range	25E	
County:	Eddy	
Elevations:		
GL:	3456	
KB:	3473	
KB Calc:	17	_
BHL		

story		
4/25/05	completed	
5/3/05	Set CIBP @ 9560'	
7/18/05	Sec cement retainer at 9500', sqzd perfs 9522-24 with 50 sx.	
	···{··································	

	CURRENT		
_	Tubing Detail (top to bottom)		
Joints	Description	Footage	Depth
	КВ		
	2 3/8" tubing at 9373' (open ended)		
			-

	Rod Detail (top to bottom)		
Rods	Description	Footage	Depth



1

TD 10000' PBTD 9947

DV

Circ 1st stg, TOC 2800' on 2nd stg 6860'

District I 1625 N. French Dr., Hobbs, NM 88240 Phone (575) 393-6161 Fax (575) 393-0720 District II 811 S. First St., Artesia, NM 88210 Phone (575) 748-1283 Fax (575) 748-9720 District II 1000 Rio Brazos Road, Aztec, NM 87410 Phone: (505) 334-6178 Fax (505) 334-6170 District IV 1220 S. G. Francis Dr., Santa Fe, NM 87505 Phone (505) 476-3460 Fax (505) 476-3462

State of New Mexico Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-102 Revised August 1, 2011 Submit one copy to appropriate District Office

AMENDED REPORT

		W	ELL LC	CATIO	N AND ACR	EAGE DEDIC	ATION PLA	T			
	API Number 15-33				•	'Pool Name WC; Seven Rivers; Bone Spring					
¹ Property (3081			⁵ Property Name ⁶ Well Number Tombstone Federal 1								
'OGRIDI 2291				C	⁸ Operator COG Opera					Elevation 3456	
					¹⁹ Surface I	Location					
UL or lat no. O	Section 35	Township 195	Range 25E	Lot Idn	Feet from the 660	North/South line South	Feet from the 1650	East/West line Cou East Eddy			County
		<u> </u>	" Bo	ttom Ho	le Location If	Different From	1 Surface				
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/We	st line		County
¹² Dedicated Acres 4 ()	¹³ Joint o	r Infill ¹⁴ C	onsolidation	Code ¹⁵ Oi	rder No.				d		

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

16					"OPERATOR CERTIFICATION
					I hereby certify that the information contained herein is true and complete
			1		to the best of my knowledge and belief, and that this organization either
					owns a working interest or unleased mineral interest in the kand including
					the proposed battom hale location or has a right to drill this well at this
					location pursuant to a contract with an owner of such a mineral or working
					interest, or to a voluntary pooling agreement or a compulsory pooling
					order heretofore entered by the division.
					12/17/13
)					Signature Date
					Kanicia Castillo
					Printed Name
					kcastillo@concho.com
					E-mail Address
					*SURVEYOR CERTIFICATION
					I hereby certify that the well location shown on this
					plat was plotted from field notes of actual surveys
					made by me or under my supervision, and that the
					same is true and correct to the best of my belief.
				-	Date of Survey
			<u> </u>	1	
	1	5	l.	1	Signature and Seal of Professional Surveyor.
			5	1650'	
		6 • •	\leftarrow	2000	4
		fi 🔥	3	le la	
		660'	2	5	Certificate Number
			ĺ		

.*

Tombstone Federal 1 30-015-33860 COG Operating, LLC. January 28, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by April 28, 2014.

- 1. Operator shall place CIBP at 9,420' with 25sx Class H Cement on top to cover the top of the Morrow formation. Tag required at a minimum of 9,220' or shallower.
- 2. Must conduct a casing integrity test to max treating pressure before perforating and fracturing. Submit results to BLM. Notify BLM if test fails.
- 3. Prior to abandoning the Bone Spring formation the operator must submit an NOI to properly plug back the Wolfcamp formation, as it cannot be done at this time due to the proximity of Bone Spring perforations.
- 4. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 5. Surface disturbance beyond the originally approved pad must have prior approval.
- 6. Closed loop system required.
- 7. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. Operator to have H2S monitoring equipment on location.
- 9. A minimum of a **3000** (**3M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

- 10. Subsequent sundry required detailing work done, a C-102 form, and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.
- 11. See attached for general requirements.

JAM 012814

2

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

General Requirements for Plug Backs

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

1

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed</u>.

7. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.