_Approved_By_EDWARD_FERNANDEZ___

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Farm 2160 5		I I I have been I V have	
	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT	FEB 0,6 2014	FORM APPROVED OMB NO. 1004-0135 Expires: July 31. 2010
SUNDRY NOTICES AND REPORTS ON WELLSMOCD A		LISMOCD ARTE	5. Lease Serial No. NMLC029418B
Do not use this form for proposals to drill or to re-e nter an abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No.
Type of Well Gas Well □ Other			8. Well Name and No. LEA C FEDERAL 4
2. Name of Operator Contact: CLINT A BRIAN CAPSTONE NATURAL RESOURCES E-Mail: cbrian@capstonenr.com			9. API Well No. 30-015-05132-00-S1
3a. Address 3b. Phone No. 2250 E 73RD ST SUITE 500 Ph: 918-236 TULSA, OK 74136		(include area code) 6-3800	10. Field and Pool, or Exploratory GRAYBURG
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, and State
Sec 11 T17S R31E NWSE 1980FSL 1980FEL			EDDY COUNTY, NM
12. CHECK AP	PROPRIATE BOX(ES) TO INDICATE	NATURE OF NOTICE, I	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION		
	☐ Acidize ☐ Deep	oen Produ	ction (Start/Resume)
■ Notice of Intent	-	ture Treat	
☐ Subsequent Report	1	Construction Recor	
☐ Final Abandonment Notice	1	-	orarily Abandon
3	☑ Convert to Injection ☐ Plug	- ·	Disposal
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed within 30 days following completion or provided the shall be filed once testing has been completed. Final hapadoment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Converting to injection is expected to start within two weeks of approval of injection permit of the OCD. Current application is under review and expected to have approval within the next 45 days. 1. Move in rig up workover service unit. Pull out of hole with Rods & pump. Rig up & test BOP to 500 psi. Pull out hole with production tubing. 2. Pick up 4-3/4? bit & scraper. RIH to TD @ 3798. Clean out fill if necessary. Pull out of hole with bit & scraper, laying down production tubing coming out of hole. 3. Pick up 2-3/8/? Internally Plastic Coated injection string. Run in hole with injection packer and injection string to advo feet. Set injection packer at 3400 feet. Rebuild well head for injection operations. Test backside to 500 psi. Rig down and move off workover service unit. 4. Move in and rig up pump truck. Pump down injection string to insure injection. Pump 2,000 gal Lead of the force of the pump down injection string to insure injection. Pump 2,000 gal Lead of the force of the pump down injection string to insure injection. Pump 2,000 gal Lead of the force o			
Committed to AFMSS for processing by JOHNNY DICKERSON on 10/23/2 Name(Printed/Typed) CLINT A BRIAN Title VICE PRESIDEN			13 (14JLD1490SE) T OF OPERATIONS
- January - January - Jensey - Octivity		VIOLITIEOIDEN	. C. C. LIMIONO
Signature (Electroni	c Submission)	Date 10/21/2013	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
THIS STACE FOR FEDERAL OR STATE OFFICE USE			
			•

RECEIVED

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office Carlsbad

TitlePETROLEUM ENGINEER

Date 01/31/2014

Additional data for EC transaction #223701 that would not fit on the form

32. Additional remarks, continued

15% NEFE acid treatment if needed. Otherwise rig down pump truck and put well on injection after approval of the sundry notice from the BLM and injection permit approval from the OCD.

Conditions of Approval

Capstone Natural Resources Lea "C" - 04 API 3001505132, T17S-R31E, Sec 11

January 31, 2014

- 1. Subject to like approval by the New Mexico Oil Conservation Division.
- 2. Casing added or replaced requires a prior notice of intent (BLM Form 3160-5) approval of the design.
- 3. Surface disturbance beyond the existing pad shall have prior approval.
- 4. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 5. Functional H₂S monitoring equipment shall be on location.
- 6. 2000 (2M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. A ram system including a blind ram and pipe ram(s) designed to close on all of the work string(s) used is required equipment. Manual BOP closure (hand wheels) equipment shall be available on location. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 7. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from 3300 or below to top of cement. The CBL may be attached to a pswartz@blm.gov email. The CFO BLM on call engineer may be reached at 575-706-2779.
- 9. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry
- 10. Submit the BLM Form 3160-4 **Recompletion Report** within 30 days of the date all BLM approved procedures are complete.
- 11. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.

Well with a Packer - Operations

- 1) Conduct a Mechanical Integrity Test of the tubing/casing annulus after a tubing, packer or casing seal is established. Repair that seal any time more than five barrels of packer fluid is replaced within 30 days.
- 2) The minimum test pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with a minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need to be reduced). An alternate method for a BLM approved MIT is to have the fluid filled system open to atmospheric pressure and have a loss of less than five barrels in 30 days witnessed by a BLM authorized officer.
- 3) Document the pressure test on a one hour full rotation calibrated recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval.
- 4) Make arrangements 24 hours before the test for BLM to witness. In Eddy County email Paul R. Swartz pswartz@blm.gov or phone 575-200-7902, if there is no response, 575-361-2822. If no answer, leave a voice mail or email with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- 5) Submit a subsequent Sundry Form 3160-5 relating the MIT activity. Include a copy of the recorded MIT pressure chart. List the name of the BLM witness, or the notified person and date of notification. NMOCD is to retain the original recorded MIT chart.
- 6) Use of tubing internal protection, tubing on/off equipment just above the packer, a profile nipple, and an in line tubing check valve below the packer or between the on/off tool and packer is a "Best Management Practice". The setting depths and descriptions of each are to be included in the subsequent sundry. List (by date) descriptions of daily activity of any previously unreported wellbore workover.
- 7) Submit the original subsequent sundry with three copies to BLM Carlsbad.
- 8) Compliance with a NMOCD Administrative Order is required, submit documentation of that authorization.
 - a) Approved injection pressure compliance is required.
 - b) If injection pressure exceeds the approved pressure you are required to reduce that pressure and notify the BLM within 24 hours.
 - c) When injection pressure is within 50 psig of the maximum pressure, install automation equipment that will prevent exceeding that maximum. Submit a subsequent report (Sundry Form 3160-5) describing the installed automation equipment within 30 days.
- 9) Unexplained significant variations of rate or pressure to be reported within 5 days of notice.
- 10) The casing/tubing annulus is required to be monitored for communication with injection fluid or loss of casing integrity. A BLM inspector may request verification of a full annular fluid level at any time.

- 11) A "Best Management Practice" is to maintain the annulus full of packer fluid at atmospheric pressure. Equipment that will display on site, continuous open to the air fluid level is necessary to achieve this goal.
- 12) Loss of packer fluid above five barrels per month indicates a developing problem. Notify BLM Carlsbad Field Office, Petroleum Engineering within 5 days.
- 13) A suggested format for monthly records documenting that the casing annulus is fluid filled is available from the BLM Carlsbad Field Office.
- 14) Gain of annular fluid requires notification within 24 hours. Cease injection and maintain a production casing pressure of Opsia. Notify the BLM's authorized officer ("Paul R. Swartz" <<u>pswartz@blm.gov></u>, cell phone 575-200-7902). If there is no response phone 575-361-2822.
- 15) Submit a (Sundry Form 3160-5) subsequent report (daily reports) describing all wellbore activity and Mechanical Integrity Test as per item 1) above. Include the date(s) of the well work, and the setting depths of installed equipment: internally corrosive protected tubing, tubing on/off equipment just above the packer, and an in line tubing check valve below the packer or between the on/off tool and packer. The setting depths and descriptions of each are to be included in the subsequent sundry. List daily descriptions of any previously unreported wellbore workover(s) and reason(s) the well annular fluid was replaced.

EGF/PRS 013114

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.