Form 3160-5 (April 2004)	UNITED STATES DEPARTMENT OF THE I	N.M. ( nterior	DIL CONSERVATI 811 S. FIRST STI	SER VATION DIVERION OM B No. 1004-0137 FIRST STREET Expires: March 31, 2007	
	BUREAU OF LAND MANA	GEMENT	ARTESIA, NM#	82 mal No.	
Do not use	Y NOTICES AND REP( this form for proposals to well. Use Form 3160-3 (Al	drill or to re-enter an	enter an 6. If Indian, Allottee or Tribe		
<b>SUBMIT IN TRIPLICATE</b> - Other instructions on reverse side.				Jnit or CA/Agreement, Name and/or N M-111019	<u>.</u>
1. Type of Well ☐ Oil Well□ □ ✔ Gas Well□□ ☐ Other				ell Name and No.	
2. Name of Operator	Energy Corneration		C	obra Federal Com #1	
2. Name of Operator Armstrong Energy Corporation 3a Address 3b. Phone No. (include area code)				PI Well No. 0-005-63642	
P.O. Box 1973, Roswell, NM 88202-1973 575-625-2222				ield and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				ounty or Parish, State	
990' FNL & 1650' FEL, Sec 19, T11S, R27E				Chaves County, NM	
12 CHECK	APPROPRIATE BOX(ES) TO I		·   ·	, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF A			
	Acidize		oduction (Start/Resur	ne) Water Shut-Off	
Notice of Intent	Alter Casing	- · –	clamation	Well Integrity	
Subsequent Report	Casing Repair		complete	Other	·
Final Abandonment Notice	Change Plans	Change Plans Plug and Abandon Temporarily Abandon Convert to Injection Plug Back Water Disposal			
following completion of the testing has been completed. determined that the site is re Notify BLM 24 hrs prio 1. Move in, RU, ND W 2. RU Wireline, run g 3. TIH w/ tbg @ 5350' 4. ND BOP and WH. 5. Spot 50 sx, POH, W 6. Spot 50 sx @ 2328', 7. POH @ 400', spot 2 release rig, RD and	or to start of operations. 'H, NU BOP, POH with production auge ring to 5350', pull GR, set Cl , circ hole w/ 9.5 ppg mud. Spot RU spear, cut csg @ 3600'. POH 'OC 4 hrs, tag @ 3550', POH. POH, WOC, tag @ 2228'. POH ( 5 sx. POH @ 60', spot 20 sx to So move out. Sove caliche, rip road and location,	iled only after submit be Casing siz shoe Loca on tbg. IBP @ 5350'. 25 sx, pull to 4604', spot 25 sx and LD csg. RIH w/ tbg @ 3 @ 1096', spot 50 sx. POH, Wu urface. Cut off wellhead and reseed.	POH, WOC 4 hrs POH, WOC 4 hrs 550'. OC, tag @ 996'. mast anchors 3' be		E.
Accepted to	* record, D 3/1/2014	MAR 03 2	•	Assistant Field Mar Lands And Mineral	nager, s
14. I hereby certify that the f Name (Printed/Typed)	oregoing is true and correct	MNIOCD AR	TESIA		EB26
Bruce Stubbs	N A A A		ident - Operations		~
Signature 15	Astilly	Date 2/	24/14		
	THIS SPACE FOR F	FEDERAL OR STATE	OFFICE USE		
Approved by		Title		Date	
Conditions of approval, if any, certify that the applicant holds I which would entitle the applica	are attached. Approval of this notice egal or equitable title to those rights in nt to conduct operations thereon.	does not warrant or n the subject lease Office		SWELL FIELD CHRICE	
Title 18 U.S.C. Section 1001 and States any false, fictitious or fra	Title 43 U.S.C. Section 1212, make it a udulent statements or representations	crime for any person knowingly as to any matter within its jurisdi	and willfully to mak	e to any department or agency of the	United
(Instructions on page 2)				· ·	

ţ