Form 3160-5 (August 2507)

UNITED STATES DEPARTMENT OF THE INTERIOR

OCD Artesia	

FORM APPROVED

OMB No. 1004-0137 Expires: July 31, 2010

BUREAU OF LAND MANAGEMENT

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well Oil Well Gas Well Other			8. W	East Shugart Unit 8. Well Name and No. ESU # 72		
2. Name of Operator Americo Energy Resources, LLC			9. A 30-0	9. API Well No. 30-015-28203		
3a. Address 3b. Phone No. (include area code) 7575 San Filpie, Ste. 200 ,Houston, TX 77063 713-984-9700				10. Field and Pool or Exploratory Area Shugart: Yates- 7Rs-Queens- Grayburg		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1650' FSL & 1150' FWL of Sec. L-35 - 18-S, 31-E				11. Country or Parish, State Eddy. NM		
12. CHEC	K THE APPROPRIATE BO	OX(ES) TO INDICATE NATI	JRE OF NOTICE, R	EPORT OR OTHE	R DATA	
TYPE OF SUBMISSION			TYPE OF ACTION			
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production Reclamation	n (Start/Resume) on	Water Shut-Off Well Integrity	
Subsequent Report Final Abandonment Notice	Casing Repair Change Plans Convert to Injection	New Construction Plug and Abandon Plug Back	Recomplet Temporari Water Dis	ly Abandon	Other	
the proposal is to deepen directions. Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready for 1- MIRU workover rig, ND wealhead 2- Pull the well, Scan out and presson 3- Replace the san eeded. 4- Tag bottom to make sure perfs ar 5- RIH w/ SN and the sand put well.	vork will be performed or proced operations. If the operation Abandonment Notices must final inspection.) NU BOP are test tubings. e not covered. pack on pump.	ovide the Bond No. on file wit on results in a multiple compl	th BLM/BIA. Requirection or recompletion or recompletion on the second of the second o	red subsequent repo n in a new interval, a mation, have been c	rts must be filed within 30 days a Form 3160-4 must be filed once completed and the operator has	
Name (Printed/Typed) Mehdi Sadeghi	ue and correct.	Title Petro	leum Engineer			
Signature Mehdi Sadep	wa	Date 01/06	/2014	<u> </u>	POVED	
· ·	THIS SPACE	FOR FEDERAL OR	STATE OFFICE	: ys£\\\	TO V L D	
Approved by		Title		MAR	1 1 2014	
Conditions of approval, if any, are attached hat the applicant holds legal or equitable to conduct operations.	itle to those rights in the subje		e Brains	PANA BURNALI OF LAI	ND MINAGEMENT	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make-to-my-department or gency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

East Shugart Unit 72 30-015-28203 Americo Energy Resources, LLC March 11, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by June 11, 2014.

- 1. Must conduct a casing integrity test to a minimum of 500 psi. Submit results to BLM. The CIT is to be performed on the production casing per Onshore Oil and Gas Order 2.III.B.1.h.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a **2000** (**2M**) **BOP** to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done. Operator to include well bore schematic of current well condition when work is complete.

JAM 031114