Submit I Copy To Appropriate District · State of New Mexico Form C-103 Office Revised August 1, 2011 Energy, Minerals and Natural Resources District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 30-015-03028 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 1220 South St. Francis Dr. STATE X FEE  $\square$ 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505/ 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM B-1266 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH GJ WEST COOP UNIT PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well X Gas Well Other 024 9. OGRID Number 2. Name of Operator COG OPERATING LLC 229137 3. Address of Operator 10. Pool name or Wildcat 600 W. ILLINOIS AVE., MIDLAND, TEXAS 79701 GRAYBURG-JACKSON; QN-GB-SA 4. Well Location Unit Letter: feet from the **SOUTH** line and 330 feet from the **EAST** line ' P ; 330 Section 21 Township 17S Range 29E **NMPM EDDY** County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,547' - GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  $\Box$ COMMENCE DRILLING OPNS.□ **TEMPORARILY ABANDON CHANGE PLANS** P AND A PULL OR ALTER CASING MULTIPLE COMPL  $\Box$ **CASING/CEMENT JOB**  $\Box$ DOWNHOLE COMMINGLE OTHER: WELL PLUGGED AND ABANDONED 05/09/14. OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 05/08/14: SET 4-1/2" CIBP @ 3,950'; CIRC. WELL W/ PXA MUD; PRES. TEST 4-1/2" CSG. TO 600# X HELD FOR 15 MINS.; PUMP 25 SXS. CMT. @ 3,950'-3,750'; PUMP 30 SXS. CMT. @ 3,400'; WOC. 05/09/14: TAG CMT. PLUG @ 3,016'; PUMP 25 SXS. CMT. @ 2,090'-1,970'; MIX X CIRC. 60 SXS. CMT. @ 700'; DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; TOP OFF WELL TO SURF. W/ 30 SXS. CMT.; WELD ON STEEL PLATE TO CSGS. X INSTALL GROUND LEVEL DRY HOLE MARKER. DURING THIS PROCEDURE WE USED THE CLOSED-LOOP SYSTEM W/ A STEEL TANK AND HAULED CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19. 15.17 Approved for plugging of well hore only. Liability under bond is retained pending receipt of Colo3 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. MIRU: 05/07/14 RDMO: 05/09/14 Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. \_TITLE: AGENT **SIGNATURE** DATE: 05/12/14 Type or print name: DAVID A. EYLER E-mail address: DEYLER@MILAGRO-RES.COM PHONE: 432,687,3033 For State Use Only APPROVED BY: Conditions of Approval (if any