UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-	ART	ES	IA
Wan	,		•

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No.

SHNDRY	NOTICES	AND	REPORTS	ON	WELLS
CONDICE	11011000	7110	IVE: OIVIO	\sim 14	

SUNDRY	NMLC029338A	6. If Indian, Allottee or Tribe Name				
Do not use the abandoned we	6. If Indian, Allottee					
SUBMIT IN TRI	7. If Unit or CA/Agre	7. If Unit or CA/Agreement, Name and/or No.				
Type of Well	her			8. Well Name and No GISSLER A 25	8. Well Name and No: GISSLER A 25	
Name of Operator BURNETT OIL CO. INC.	Contact: LESL E-Mail: lgarvis@burnetto			9. API Well No. 30-015-34021		
3a. Address BURNETT PLAZA - SUITE 15 FORT WORTH, TX 76102	3b. F 500 801 CHERRY STREETPHU	Phone No. (include area NBTF-OB2F-5W08RTH	code) , TX 76102	10. Field and Pool, or LOCO HILLS Y	10. Field and Pool, or Exploratory LOCO HILLS YESO	
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)			11. County or Parish,	11. County or Parish, and State	
Sec 14 T17S R30E 330FSL 2	230FWL			EDDY COUNT	EDDY COUNTY COUNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO IND	ICATE NATURE	OF NOTIO	CE, REPORT, OR OTHE	ER DATA	
TYPE OF SUBMISSION		TYI	PE OF ACT	ION		
Notice of Intent	☐ Acidize	☐ Deepen	P	roduction (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	☐ Fracture Treat	□ R	Leclamation	■ Well Integrity	
☐ Subsequent Report	Casing Repair	☐ New Construction	n 🗆 R	lecomplete	☐ Other	
☐ Final Abandonment Notice	Change Plans	☐ Plug and Abando	on 📋 T	emporarily Abandon		
	☐ Convert to Injection	☐ Plug Back	g Back			
testing has been completed. Final At determined that the site is ready for final The Gissler A 25 developed a a frac stimulation in the lower been isolated with a plug belo with clean water. There are to	I operations. If the operation results in pandonment Notices shall be filed only final inspection.) split in the 7? 23# J-55 casing Blinebry (Yeso) the week of Jurw it and an injection rate of 3 B wo other frac stages in the Yeso fill be used to frac down on the stages.	from 3090? ? 3096 ne 12th, 2014. The PM at 470 psi has to to be done at dep	including recl ? (San And casing sp been estab ths of 5200	amation, have been completed, ACC dres) during lit has lished 07 and NM OIL C		
let the formation determine ho the same cement that was use	o have 400 sx cement on location with much to pump. A 500# rolling of for the deepening: 50/50 P/C+0.2%PF65(Dispersant)+0.4#/s water	g squeeze would b c+5%PF44(BWOW	e ideal. We (Salt)+2%	e will use PF20(Bentonite	1 3 0 2014 ECEIVED	
14. I hereby certify that the foregoing is	Electronic Submission #250214	4 verified by the BLN L CO. INC., sent to t				
Name (Printed/Typed) LESLIE GARVIS			GULATOR	Y COORDINATOR	·	
Signature (Electronic S	Submission)	Date 06/	19/2014	APPRO	VFN	
	THIS SPACE FOR FE	DERAL OR STA	TE OFFI	CE USE		
Approved By	SEE ATTACHED FOR CONDITIONS OF APPROV			AUN, 2,3	2014 Date	
onditions of approval, if any, are attached. Approval of this notice does not warrant or trify that the applicant holds legal or equitable title to those rights in the subject lease hich would entitle the applicant to conduct operations thereon.				BUREAU OF LAND A	ANNACEMENT	
itle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulents	U.S.C. Section 1212, make it a crime f	or any person knowingly	y and willful ction.	y to make CARLSBAUFIEL	Defree United	

Additional data for EC transaction #250214 that would not fit on the form

32. Additional remarks, continued

There is a recent CBL from this well and there is good cement behind the 7? casing at the point of the split as well as above and below it. Cory Rogers is the company man on location for this work.

Verbal approval by Paul Swartz on 6/19/14 to begin this work.

Conditions of Approval

Burnett Oil Co., Inc. Gissler A 25 API 3001534021, T17S-R30E, Sec 14

June 20, 2014

- 1. Before casing or a liner is added, replaced, or repaired prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 2. Subject to like approval by the New Mexico Oil Conservation Division.
- 3. After the cement squeeze and frac stimulation, perform a (charted) casing integrity test of 500 psig. Verify all annular casing vents are plumbed to surface and those valves open to the surface during this pressure test. Pressure leakoff may require correction for approval. Include a copy of the chart in the subsequent sundry for this workover.
- 4. Provide BLM with an electronic copy (Adobe Acrobat Document) (post cement squeeze at 3090') cement bond log record (7" and 5 ½" csg) from 5700 or below to top of cement. The CBL may be attached to a pswartz@blm.gov email. The CFO BLM on call engineer may be reached at 575-706-2779.
- 5. Surface disturbance beyond the existing pad shall have prior approval.
- 6. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 7. Functional H₂S monitoring equipment shall be on location.
- 8. 2000 (2M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. A ram system including a blind ram and pipe ram(s) designed to close on all of the work string(s) used is required equipment. Manual BOP closure (hand wheels) equipment shall be installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 9. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 10. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.
- 11. File intermediate **subsequent sundry** Form 3160-5 within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.

12. Submit the BLM Form 3160-4 Recompletion Report within 30 days of the date all BLM approved procedures are complete.

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil and gas.html § 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.