· .				
Form 3160-5 (March 2012)	UNITED STATES DEPARTMENT OF THE IN BUREAU OF LAND MANAG		5. Lease Serial No.	FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014
Do not use	RY NOTICES AND REPOR this form for proposals to vell. Use Form 3160-3 (AP	drill or to re-enter an		e or Tribe Name
	UBMIT IN TRIPLICATE – Other in	structions on page 2.	7. If Unit of CA/Ag	reement, Name and/or No.
I. Type of Well	Gas Well 🚺 Other		8. Well Name and N BOYDS CANYO	No. DN 14 FED COM #1
2. Name of Operator DEVON ENERGY PRODUC	 ΓΙΟΝ CO LP (6137)		9. API Well No. 30-015-35290	
3a. Address	3t	p. Phone No. (include area co	de) 10. Field and Pool of HAPPY VALLE	
PO BOX 250, ARTESIA, NM 88211 4. Location of Well (Footage, S	Sec., T.,R.,M., or Survey Description)	575-748-3371	11. County or Paris	
220' FSL & 760' FEL, SEC 14, T22S, F	225E		EDDY COUNT	Y, NM
12.	CHECK THE APPROPRIATE BOX	(ES) TO INDICATE NATUR	E OF NOTICE, REPORT OR OT	THER DATA
TYPE OF SUBMISSION	4		PE OF ACTION	
Notice of Intent	Acidize	Deepen Fracture Treat	Production (Start/Resume)	Water Shut-Off Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other F.A.N.
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back	Temporarily Abandon Water Disposal	
the proposal is to deepen di Attach the Bond under whi following completion of the	rectionally or recomplete horizontally, ch the work will be performed or provi e involved operations. If the operation Final Abandonment Notices must be	give subsurface locations and de the Bond No. on file with E results in a multiple completion	measured and true vertical depth BLM/BIA. Required subsequent on or recompletion in a new inter	reports must be filed within 30 days val, a Form 3160-4 must be filed once
the proposal is to deepen di Attach the Bond under whi following completion of the testing has been completed determined that the site is r	rectionally or recomplete horizontally, ch the work will be performed or provi e involved operations. If the operation Final Abandonment Notices must be	give subsurface locations and de the Bond No. on file with E results in a multiple completio filed only after all requiremen	measured and true vertical depth BLM/BIA. Required subsequent on or recompletion in a new inter ts, including reclamation, have b	is of all pertinent markers and zones. reports must be filed within 30 days val, a Form 3160-4 must be filed once een completed and the operator has
the proposal is to deepen di Attach the Bond under whi following completion of the testing has been completed determined that the site is r	rectionally or recomplete horizontally, ch the work will be performed or provi e involved operations. If the operation . Final Abandonment Notices must be eady for final inspection.)	give subsurface locations and de the Bond No. on file with E results in a multiple completio filed only after all requiremen	measured and true vertical depth BLM/BIA. Required subsequent on or recompletion in a new inter ts, including reclamation, have b	is of all pertinent markers and zones. reports must be filed within 30 days val, a Form 3160-4 must be filed once een completed and the operator has
the proposal is to deepen di Attach the Bond under whi following completion of the testing has been completed determined that the site is r Devon Energy feels f Thank you.	rectionally or recomplete horizontally, ch the work will be performed or provi e involved operations. If the operation . Final Abandonment Notices must be eady for final inspection.) that all reclamation requirements has D $7-29-14$	give subsurface locations and de the Bond No. on file with E results in a multiple completio filed only after all requiremen	measured and true vertical depth BLM/BIA. Required subsequent on or recompletion in a new inter ts, including reclamation, have b location is ready for a Final At	is of all pertinent markers and zones. reports must be filed within 30 days val, a Form 3160-4 must be filed once een completed and the operator has
the proposal is to deepen di Attach the Bond under whi following completion of the testing has been completed determined that the site is r Devon Energy feels f Thank you.	rectionally or recomplete horizontally, ch the work will be performed or provi e involved operations. If the operation . Final Abandonment Notices must be eady for final inspection.)	give subsurface locations and de the Bond No. on file with E results in a multiple completio filed only after all requiremen	measured and true vertical depth BLM/BIA. Required subsequent on or recompletion in a new inter ts, including reclamation, have b location is ready for a Final At	is of all pertinent markers and zones. reports must be filed within 30 days val, a Form 3160-4 must be filed once een completed and the operator has oandonment Inspection.
the proposal is to deepen di Attach the Bond under whi following completion of the testing has been completed determined that the site is r Devon Energy feels f Thank you.	D 7-29-14 Chief of the control	give subsurface locations and de the Bond No. on file with E results in a multiple completio filed only after all requiremen	measured and true vertical depth BLM/BIA. Required subsequent on or recompletion in a new inter ts, including reclamation, have b location is ready for a Final At	s of all pertinent markers and zones. reports must be filed within 30 days val, a Form 3160-4 must be filed once een completed and the operator has bandonment Inspection.
the proposal is to deepen di Attach the Bond under whi following completion of the testing has been completed determined that the site is r Devon Energy feels f Thank you.	D 7-29-14 Chief of the control	give subsurface locations and de the Bond No. on file with E results in a multiple completio filed only after all requiremen ave been achieved and the	measured and true vertical depth BLM/BIA. Required subsequent on or recompletion in a new inter ts, including reclamation, have b location is ready for a Final At	ss of all pertinent markers and zones. reports must be filed within 30 days val, a Form 3160-4 must be filed once een completed and the operator has bandonment Inspection. DIL CONSERVATION ARTESIA DISTRICT JUL 1 4 2014
the proposal is to deepen di Attach the Bond under whi following completion of the testing has been completed determined that the site is r Devon Energy feels to Thank you.	The contract of the second sec	give subsurface locations and de the Bond No. on file with F results in a multiple completio filed only after all requiremen ave been achieved and the <i>Typed</i>)	measured and true vertical depth BLM/BIA. Required subsequent on or recompletion in a new inter ts, including reclamation, have b location is ready for a Final At	ss of all pertinent markers and zones. reports must be filed within 30 days val, a Form 3160-4 must be filed once een completed and the operator has bandonment Inspection. DIL CONSERVATION ARTESIA DISTRICT JUL 1 4 2014
the proposal is to deepen di Attach the Bond under whi following completion of the testing has been completed determined that the site is r Devon Energy feels to Thank you.	 bit is true and correct. Name (Printed/) 	give subsurface locations and de the Bond No. on file with F results in a multiple completio filed only after all requiremen ave been achieved and the <i>Typed</i>)	measured and true vertical depth BLM/BIA. Required subsequent on or recompletion in a new inter ts, including reclamation, have b location is ready for a Final At NM C	ss of all pertinent markers and zones. reports must be filed within 30 days val, a Form 3160-4 must be filed once een completed and the operator has bandonment Inspection. DIL CONSERVATION ARTESIA DISTRICT JUL 1 4 2014
the proposal is to deepen di Attach the Bond under whi following completion of the testing has been completed determined that the site is r Devon Energy feels to Thank you.	inectionally or recomplete horizontally, ch the work will be performed or provi e involved operations. If the operation Final Abandonment Notices must be eady for final inspection.) that all reclamation requirements have that all reclamation requiremen	give subsurface locations and de the Bond No. on file with E results in a multiple completio filed only after all requiremen ave been achieved and the <i>Typed</i>) Title ADMIN	measured and true vertical depth BLM/BIA. Required subsequent on or recompletion in a new inter ts, including reclamation, have b location is ready for a Final At NM C FIELD SUPPORT 14	ss of all pertinent markers and zones. reports must be filed within 30 days val, a Form 3160-4 must be filed once een completed and the operator has bandonment Inspection. DIL CONSERVATION ARTESIA DISTRICT JUL 1 4 2014
the proposal is to deepen di Attach the Bond under whi following completion of the testing has been completed determined that the site is r Devon Energy feels to Thank you.	inectionally or recomplete horizontally, ch the work will be performed or provi e involved operations. If the operation Final Abandonment Notices must be eady for final inspection.) that all reclamation requirements have that all reclamation requiremen	give subsurface locations and de the Bond No. on file with E results in a multiple completio filed only after all requiremen ave been achieved and the <i>Typed</i>) Title ADMIN Date 5/30/20	measured and true vertical depth BLM/BIA. Required subsequent on or recompletion in a new inter ts, including reclamation, have b location is ready for a Final At NM C FIELD SUPPORT 14	ss of all pertinent markers and zones. reports must be filed within 30 days val, a Form 3160-4 must be filed once een completed and the operator has bandonment Inspection. DIL CONSERVATION ARTESIA DISTRICT JUL 1 4 2014
the proposal is to deepen di Attach the Bond under whi following completion of the testing has been completed determined that the site is r Devon Energy feels to Thank you. () () () () () () () () () () () () ()	rectionally or recomplete horizontally, ch the work will be performed or provie involved operations. If the operation Final Abandonment Notices must be eady for final inspection.) that all reclamation requirements have that all reclamation requirements	give subsurface locations and de the Bond No. on file with F results in a multiple completion filed only after all requirement ave been achieved and the ave been achieved and the Title ADMIN Date 5/30/20 OR FEDERAL OR ST OR FEDERAL OR ST Title Office	measured and true vertical depth BLM/BIA. Required subsequent on or recompletion in a new inter ts, including reclamation, have b location is ready for a Final At NM C FIELD SUPPORT 14 TATE OFFICE USE	so of all pertinent markers and zones. reports must be filed within 30 days val, a Form 3160-4 must be filed once een completed and the operator has bandonment Inspection. DIL CONSERVATION ARTESIA DISTRICT JUL 1 4 2014 RECEIVED Date $7-8-14$
the proposal is to deepen di Attach the Bond under whi following completion of the testing has been completed determined that the site is r Devon Energy feels to Thank you.	rectionally or recomplete horizontally, ch the work will be performed or provie involved operations. If the operation Final Abandonment Notices must be eady for final inspection.) that all reclamation requirements have that all reclamation requirements	give subsurface locations and de the Bond No. on file with F results in a multiple completion filed only after all requirement ave been achieved and the ave been achieved and the Title ADMIN Date 5/30/20 OR FEDERAL OR ST of warrant or certify lease which would Title Office	measured and true vertical depth BLM/BIA. Required subsequent on or recompletion in a new inter ts, including reclamation, have b location is ready for a Final At NM C FIELD SUPPORT 14 TATE OFFICE USE	so of all pertinent markers and zones. reports must be filed within 30 days val, a Form 3160-4 must be filed once een completed and the operator has bandonment Inspection. DIL CONSERVATION ARTESIA DISTRICT JUL 1 4 2014 RECEIVED

Menoud, Denise

From:	Amos, James <jamos@blm.gov></jamos@blm.gov>
Sent:	Friday, May 30, 2014 10:25 AM
То:	Menoud, Denise
Subject:	Boyds Canyon 14 Fed Com 1 (3001535290)

Denise, The above referenced well is ready for a Final Abandonment Notice (Sundry Notice, Form 3160-5), show that requirements have been met and the location is ready for a final inspection. thanks

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

James A. Amos Bureau of Land Management Carlsbad Field Office Supervisory Environmental Protection Specialist 620 East Greene Street Carlsbad, NM. 88220 Office: (575) 234-5909 Fax: (575) 234-5927 Cell: (575) 361-2648 E-mail: jamos@blm.gov

BURE	UNITED STATES ARTMENT OF THE IN EAU OF LAND MANAG	GEMENT		OM	RM APPROVED fB No. 1004-0137 pires: July 31, 2010
Do not use this fo	OTICES AND REPOR for proposals to Jse Form 3160-3 (APL	drill or to re-e	enter an	6. If Indian, Allottee or	Tribe Name
	IN TRIPLICATE – Other ins	structions on page	2.	7. If Unit of CA/Agreen	nent, Name and/or No.
1. Type of Well Gas W	ell 🗍 Other			8. Well Name and No.	
2. Name of Operator DEVON ENERGY PRODUCTION				9. API Well No.	N 14 FED COM #1
3a. Address		. Phone No. (inclu	de area code)	30-015-35290 10. Field and Pool or E	xploratory Area
PO BOX 250, ARTESIA, NM 88211		575-748-3371		HAPPY VALLEY	
4. Location of Well (Footage, Sec., T., F	R.,M., or Survey Description)			11. Country or Parish, S	State
220' FSL & 760' FEL, SEC 14, T22S, R258	E			EDDY COUNTY	r, NM
12. CHEC	K THE APPROPRIATE BOX(ES) TO INDICAT	E NATURE OF NO	OTICE, REPORT OR OTHE	ER DATA
TYPE OF SUBMISSION			TYPE OF	ACTION	
Notice of Intent	Acidize	Deepen		Production (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Tre	at 🔽	Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Constr	uction	Recomplete	Other
	Change Plans	Plug and At	vandon 🔲	Temporarily Abandon	P&A Inspection - 3rd
Final Abandonment Notice 13. Describe Proposed or Completed Op	Convert to Injection	Plug Back		Water Disposal	
determined that the site is ready for This well was plugged and abandon have all been taken care of. Request to release as a Final Aband	ed and the dry hole marker v		After inspection	is from the BLM, more issu	Jes were reported to Devon, which
14. I hereby certify that the foregoing is t	rue and correct. Name (Printed/	Typed)			
DENISE MENOUD (575-746-554	4)	Title	ADMIN FIELD	SUPPORT 4	
Signature D.Mer	roul	Date	1/17/2014		
C	THIS SPACE F	OR FEDERA	L OR STATE	OFFICE USE	
Approved by				·	
Conditions of approval, if any are attache that the applicant holds legal or equitable t entitle the applicant to conduct operations	title to those rights in the subject		Title Office	[]	Date
Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent statements or repre-			knowingly and will	fully to make to any departmen	al or agency of the United States any false,
(Instructions on page 2)					

4

•

·		° 0	perator Copy		
	UNITED STATES ARTMENT OF THE IN EAU OF LAND MANA		q & A	O	DRM APPROVED MB No. 1004-0137 pires: July 31, 2010
Do not use this f	OTICES AND REPOR orm for proposals to Use Form 3160-3 (AP	drill or to re-en	nter an	NMNM-9984 6. If Indian, Allottee of	/
	IN TRIPLICATE - Other in	structions on page	2.	7. If Unit of CA/Agree	ment, Name and/or No.
1. Type of Well	ell 🗍 Other			8. Well Name and No. BOYDS CANYON	14 FED COM #1
2. Name of Operator DEVON ENERGY PRODUCTION	CO LP (6137)			9. API Well No. 30-015-35290	······································
3a. Address PO BOX 250, ARTESIA, NM 88211	3	b. Phone No. (include	e area code)	10. Field and Pool or E HAPPY VALLEY	xploratory Area
4. Location of Well (Footage, Sec., T., I	R.,M., or Survey Description)	575-748-3371		11. Country or Parish,	State
220 FSL & 760 FEL, SEC 14, T225, R25E	······································			EDDY COUNTY,	NM
12. CHEC	K THE APPROPRIATE BOX	(ES) TO INDICATE	NATURE OF NOT	ICE, REPORT OR OTHI	ER DATA
TYPE OF SUBMISSION			TYPE OF AC	TION	
Notice of Intent	Acidize	Deepen Fracture Trea	·	oduction (Start/Resume)	Water Shut-Off
Subsequent Report	Casing Repair	New Constru		complete	Other
Final Abandonment Notice	Change Plans	Plug and Aba	per-trap	mporarily Abandon ater Disposal	
 Describe Proposed or Completed Op the proposal is to deepen directiona Attach the Bond under which the w following completion of the involv testing has been completed. Final determined that the site is ready for THIS LOCATION WAS INSPECTED DEVON HAS LEVELED THE HIGH THANK YOU. 	ally or recomplete horizontally york will be performed or prov ed operations. If the operation Abandonment Notices must be final inspection.)	, give subsurface loca ide the Bond No. on f results in a multiple filed only after all re BERMS WERE LEF	tions and measured ile with BLM/BIA. completion or recon quirements, includin T ON THE LOCA	and true vertical depths o Required subsequent rep npletion in a new interval, ig reclamation, have been TION.	f all pertinent markers and zones. orts must be filed within 30 days a Forn 3160-4 must be filed once completed and the operator has
Poly Line & a AVC on Norr Renove, then 14. Thereby certify that the foregoing is t	the west sid	South Si e AVC Taol Ab	Le, Por , woody	ly line or debis o	n west side, on east side on be released,
DENISE MENOUD			ADMIN FIELD SU	-	
Signature XI. Man	roud	Date	6/24/2013	ACCEP	TED FOR RECORD
	THIS SPACE F	OR FEDERAL	OR STATE O	FFICEUSE	
Approved by					AUG 3 1 2013
Conditions of approval, if any, are attached that the applicant holds legal or equitable t entitle the applicant to conduct operations	itle to those rights in the subject thereon.	not warrant or certify tease which would	Title	Í	ences a. China
Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent statements or repre (Instructions on page 2)			owingly and willfully	y to make to privide puttiment	t NP areness of the Content States any false, LSBAD FIELD OFFICE

۰.

Resenden						
Form 3160-5 (August 2007) BI	UNITED STATES DEPARTMENT OF THE IN	ITERIOR Uperator	Сару	0	ORM APPROVED MB No. 1004-0137 spires: July 31, 2010	
	UREAU OF LAND MANA			5. Lease Serial No. NMNM-9	· · · · · · · · · · · · · · · · · · ·	
Do not use this	Y NOTICES AND REPOR 's form for proposals to I. Use Form 3160-3 (AP	drill or to ro onton	an	6. if Indian, Allottee o		
	MIT IN TRIPLICATE - Other in		<u>ais.</u>	7 If Unit of CA/Amm	ment, Name and/or No.	
1. Type of Well				. a cator of a refice	anent, trante and/or no.	
2. Name of Operator DEVON ENERGY PRODU				8. Well Name and No. BOYDS C	ANYON 14 FED COM #1	
3a. Address		. Phone No. (include area o	andal	9. API Well No. 30-015-35		
PO BOX 250, ARTESIA, NM 88	8211	575-748-3371	couej	10. Field and Pool or E HAPPY		
 Location of Well (Footage, Sec., 220' FSL & 760' FEL, SEC 14, T2 			·····	11. Country or Parish,		
					DUNTY, NM	
TYPE OF SUBMISSION	ECK THE APPROPRIATE BOX((ES) TO INDICATE NATU	RE OF NOTIC	E, REPORT OR OTHE	ER DATA	
			YPE OF ACT	ON		
Notice of Intent	Acidize	Deepen		ction (Start/Resume)	Water Shut-Off	
Subsequent Report	Casing Repair	New Construction		nplete	Other	
Final Abandonment Notice	Change Plans	Plug and Abandon		orarily Abandon Disposal	······	
Attach the Bond under which the following completion of the invo testing has been completed. Fina determined that the site is ready	e work will be performed or provid olved operations. If the operation r al Abandonment Notices must be fi for final inspection.)	give subsurface locations an le the Bond No. on file with results in a multiple complet filed only after all requirement	Id measured an BLM/BIA. R ion or recompl nts, including	I true vertical depths of squired subsequent rep etion in a new interval, eclamation, have been	all pertinent markers and zo outs must be filed within 30 d $= 5 - 2160$ A must be filed within 30 d	ays
Attach the Bond under which the following completion of the invo testing has been completed. Fina determined that the site is ready to THIS WELL WAS PLUGGED A THIS LOCATION IS READY FO This location to neet on	e work will be performed or provid olved operations. If the operation r al Abandonment Notices must be fi for final inspection.)	gree subsurface locations an le the Bond No. on file with results in a multiple complet filed only after all requirement DRY HOLE MARKER WA	d messured an BLM/BIA. R ion or recompl nts, including S SET 3/2/20 (: او م S Sec 2	 I true vertical depths of squired subsequent repetion in a new interval, eclamation, have been 11. I A BUREAU 	Fall pertinent markers and zor orts must be filed within 30 d a Form 3160-4 must be filed completed and the operator b ED FOR RECO PR 2 7 2013 Immode CF LANO MANAGEMEN	nes. ays once as
Attach the Bond under which the following completion of the invo testing has been completed. Find determined that the site is ready to THIS WELL WAS PLUGGED A THIS LOCATION IS READY FO This to cation to neet on Contact Sim &	AND ABANDONED AND THE C FOR INSPECTION. Sf: 11 Loss isse be cation to a solution of the soluti	give subsurface locations an le the Bond No. on file with results in a multiple complet filed only after all requirement DRY HOLE MARKER WA $go o \circ c - \frac{1}{2}$ $go o \circ c - \frac{1}{2}$ $5 \cdot 2 \cdot 3 \cdot 4 - 5 \cdot 4 \cdot 0 \cdot 3$	d messured an BLM/BIA. R ion or recompl nts, including S SET 3/2/20 (: او م S Sec 2	 I true vertical depths of squired subsequent repetion in a new interval, eclamation, have been 11. I A BUREAU 	all pertinent markers and zor orts must be filed within 30 d a Form 3160-4 must be filed completed and the operator b ED FOR RECO PR 2 7 2013 Smool	nes. ays once as
Attach the Bond under which the following completion of the invo testing has been completed. Find determined that the site is ready if THIS WELL WAS PLUGGED A THIS LOCATION IS READY FO THIS LOCATION IS READY FO This location to neet on Contact Jim #	AND ABANDONED AND THE C FOR INSPECTION. Sf: 11 Loss isse be cation to a solution of the soluti	give subsurface locations an te the Bond No. on file with results in a multiple complet filed only after all requirement DRY HOLE MARKER WA DRY HOLE MARKER WA Go OOCC : 5. 2.34-5409 uped)	d mesured an BLM/BIA. R ion or recompl nts, including S SET 3/2/20 (: k e S S c e e S	 I true vertical depths of squired subsequent repetion in a new interval, eclamation, have been 11. I A BUREAU 	Fall pertinent markers and zor orts must be filed within 30 d a Form 3160-4 must be filed completed and the operator b ED FOR RECO PR 2 7 2013 Immode CF LANO MANAGEMEN	nes. ays once as
Attach the Bond under which the following completion of the invo- testing has been completed. Find determined that the site is ready if THIS WELL WAS PLUGGED A THIS LOCATION IS READY FO THIS LOCATION IS READY FO This I be cadion to neet on Contact Jim #	s true and correct. Name (Printed/Ty strue and correct. Name (Printed/Ty -746-5544)	give subsurface locations an le the Bond No. on file with results in a multiple complet filed only after all requirement DRY HOLE MARKER WA DRY HOLE MARKER WA DRY HOLE MARKER WA Sees. Workling 5. 2.34-54.09 Title ADMIN Date 5/8/201	d mesured an BLM/BIA. R ion or recompl nts, including S SET 3/2/20 (: k e S S C E S S S E T 3/2/20 12 S S E T 3/2/20 12	 I true vertical depths of squired subsequent repetion in a new interval, eclanuation, have been 11. 11. ACCEPT A BUREAU CARL COMPLETIONS 	Fall pertinent markers and zor orts must be filed within 30 d a Form 3160-4 must be filed completed and the operator b ED FOR RECO PR 2 7 2013 Immode CF LANO MANAGEMEN	nes. ays once as
Attach the Bond under which the following completion of the invo- testing has been completed. Find determined that the site is ready to THIS WELL WAS PLUGGED A THIS LOCATION IS READY FO THIS LOCATION IS READY FO This to cation to neet on Contact Sim & 4. Thereby certify that the foregoing is DENISE MENOUD (575-	s true and correct. Name (Printed/Ty strue and correct. Name (Printed/Ty -746-5544)	presubsurface locations an le the Bond No. on file with results in a multiple complet filed only after all requirement DRY HOLE MARKER WA DRY HOLE MARKER WA Sec. 2. 2. 2. 2. 2. 2. 2. 5. 2.3. 4 5. 2. 3. Title ADMIN	d mesured an BLM/BIA. R ion or recompl nts, including S SET 3/2/20 (: k e S S C E S S S E T 3/2/20 12 S S E T 3/2/20 12	 I true vertical depths of squired subsequent repetion in a new interval, eclanuation, have been 11. 11. ACCEPT A BUREAU CARL COMPLETIONS 	Fall pertinent markers and zor orts must be filed within 30 d a Form 3160-4 must be filed completed and the operator b ED FOR RECO PR 2 7 2013 Immode CF LANO MANAGEMEN	nes. ays once as
Attach the Bond under which the following completion of the invo- testing has been completed. Fina determined that the site is ready to THIS WELL WAS PLUGGED A THIS LOCATION IS READY FO This location to neet on Contact on Contact Sim & determined that the foregoing is DENISE MENOUD (575- Signature The	s true and correct. Name (Printed/Ty strue and correct. Name (Printed/Ty -746-5544)	groe subsurface locations and let the Bond No. on file with filed only after all requirements in a multiple complete filed only after all requirements. DRY HOLE MARKER WA cxes. Would go our of the second	d mesured an BLM/BIA. R ion or recompl nts, including S SET 3/2/20 (: k e S S C E S S S E T 3/2/20 12 S S E T 3/2/20 12	I true vertical depths of aquired subsequent repetion in a new interval, eclamation, have been 11.	all pertirent markers and zor orts must be filed within 30 d a Form 3160-4 must be filed completed and the operator b FD FOR RECO PR 2 7 2013 Mono- OF LANO MANAGEMEN SBAD FIELD OFFICE	nes. ays once as
Attach the Bond under which the following completion of the invo testing has been completed. Find determined that the site is ready if THIS WELL WAS PLUGGED A THIS LOCATION IS READY FO THIS LOCATION IS READY FO THIS LOCATION IS READY FO THIS & Lo cadion to meet on Contact or Contact or Signature of The Signature of The order of the site is an and the site is performed by	AND ABANDONED AND THE C OR INSPECTION. Sf: 11 Loss issee location to S75 strue and correct. Name (Printed/Ty -746-5544) THIS SPACE FO hed. Approval of this notice does not e tills to be constant to subject let	ave subsurface locations an te the Bond No. on file with results in a multiple complet filed only after all requirement DRY HOLE MARKER WA DRY HOLE MARKER WA DRY HOLE MARKER WA Sees. Workled go ooc 5. 2.3 4 - 54 09 Title ADMIN Date 5/8/201 DR FEDERAL OR S Tide	d mesured an BLM/BIA. R ion or recompl nts, including S SET 3/2/20 (: k e S S C E S S S E T 3/2/20 12 S S E T 3/2/20 12	I true vertical depths of aquired subsequent repetion in a new interval, eclamation, have been 11.	Fall pertinent markers and zor orts must be filed within 30 d a Form 3160-4 must be filed completed and the operator b ED FOR RECO PR 2 7 2013 Immode CF LANO MANAGEMEN	nes. ays once as
Attach the Bond under which the following completion of the invo- testing has been completed. Find determined that the site is ready to THIS WELL WAS PLUGGED A THIS LOCATION IS READY FO THIS LOCATION IS READY FO THIS LOCATION IS READY FO THIS & Location to meet on Contact Jim & 14. Thereby certify that the foregoing is DENISE MENOUD (575-	AND ABANDONED AND THE C OR INSPECTION. Sf: 11 Loss issee location to solve the solve of the s	give subsurface locations an le the Bond No. on file with results in a multiple complet filed only after all requirement DRY HOLE MARKER WA DRY HOLE MARKER WA DRY HOLE MARKER WA Sees. Workley 5. 2.3 4 - 54.07 DR FEDERAL OR S t warrant or certify ase which would Office me for any person knowingly i	id measured an BLM/BIA. R ion or recompl mts, including S SET 3/2/20 (: Ic c S S C C C C	I true vertical depths of aquired subsequent rep etion in a new interval, eclamation, have been 11.	all pertinent markers and zo orts must be filed within 30 d a Form 3160-4 must be filed completed and the operator b ED FOR RECO PR 2 7 2013 CF LANO MANAGEMEN SBAD FIELD OFFICE ate	res. ays otice as

•