Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BURFALLOF LAND MANAGEMENT

OCD	Artesia

FORM APPROVED
Budget Bureau No. 1004-0137
Expires: July 31, 2010

Expires:	July	31,	2010	
Leace Serial N	Jo			

. I	.ea	se	Serial No.	
Th	ZY	\sim	000410D	****

DORE		NMLC-029418B				
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
		7. If Unit or CA, Agreement, Name and/or No.				
1. Type of Well	TRIPLICATE – Other instructi	ions on page 2.		7. If Ome of CA, Agreement, Planto and Office.		
X Oil Gas			ļ	8. Well Name and No. Lea C Federal #4		
2. Name of Operator				Dea C.1 edolal "4		
CAPSTONE NATURAL RESO	URCES LLC			9. API Well No.		
en orong mir plane i deso	Citobo, EEC			30-015-05132		
3a. Address		3b. Phone No. (include area co				
2250 E. 73rd St., Suite 500, Tulsa	a, OK 74136	Debbie McKelvey, Agent	t	10. Field and Pool, or Exploratory Area		
		575-392-3575		GRAYBURG JACKSON; SR-Q-G-SA		
	T.,R,M., or Survey Description)	***************************************				
1980' FSL & 1980' FEL, SEC. 11, T17S, 31E, NMPM				11. County or Parish, State		
				EDDY, NM		
12. CHECK APPROPRI	ATE BOX(es) TO INDIC	CATE NATURE OF NO	OTICE	, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE	OF ACTION				
Notice of Intent	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Recla	action (Start/Resume) Water Shut-Off Well Integrity Other		
X Subsequent Report	Change Plans X Convert to Injection	Plug and Abandon Plug Back		porarily Abandon or Disposal		

Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be Filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Convert to Injector:

(Instruction on page 2)

Final Abandonment Notice

Reinstatement of authorization to inject for waterflood operations authorized by NMOCD Order No. R-4697-B

See attached procedure for conversion.

Fictitious or fraudulent statements or representations as to any matter within its jurisdiction

This information is also being submitted to the OCD on OCD Form C-103.

NM OIL CONSERVATION

ARTESIA DISTRICT

AUG 1 3 2014

RECEIVED

A	cepted for record
	NMOCD RI 8/15/14
	8/15/14

			144	a market of the	Aller Commence	· · · · · · · · · · · · · · · · · · ·	φò
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) DEBBIE MCKELVEY	Title	AGENT	575-3	ACCEPT	FN FAR RFC	'ORD	
Signature Subbic MKel	Date	3/24/14		ACCEPTE	JFOR RECO	Rhi	9
THE SPACE FOR FEDER	AL OR \$	TATE OFFI	CE USI		110 6 2014		- constant
Approved by	AND THE CONTRACT OF THE STATE O	Title			The state of the s		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that holds legal or equitable title to those rights in the subject lease which would entitle the applicant to coperations thereon.		Office	:		DE LAND MANAGEM SBAD FIELD OFFICE		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for an	ıy person kn	owingly and willfi	ully to ma	g. 011113	· · · · · · · · · · · · · · · · · · ·	- 1	•

2/24/14 - MIRU. POOH with rods and pump.

2/25/14 - RU & Install and test 6" 900 BOP to 500 psi. POOH with production tubing.

2/26/14 - RIH and tag top of fill @ 3773'. Clean out fill to TD @ 3798'. POOH.

2/27/14 – TIH with 5 ½" RBP and set @ 3380'. Circulate w/57 bbls. Of fresh water and test 5 ½" casing for 10 minutes and did not loose any pressure. TOH. RU wireline and run CBL log from 3380' to surface. Found good cement from 3380-2800', poor cement from 2800-2740, and scattered good and poor cement from 2740' to TOC @ 1380'. Electronic copy of CBL was emailed to Paul Swartz, BLM. RD wireline. TOH with RBP. TIH with 5 ½" casing scraper to 3411'. Scraper ran smoothly. TOH.

2/28/14 – TIH w/5 1/2" Loc-set pkr. To 3388'. Load w/52 bbls. of fresh water and pressure up to 500 psi leaving pressure on csg. Test lines to 5500 psi and acidize perfs., 3443-3682' and 3700-3798', with 2000 gals. NEFE HCL 15% acid using 2000# of rock salt diverter.

3/3/14 – TOH. At approximately 2:30 p.m., notified Paul Swartz, BLM, and Richard Inge, OCD, that MIT was to be performed on 3/5/14 @ 8 a.m.

3/4/14 – TIH w/5 ½" IPC nickel plated Loc-set pkr., 2 3/8" x 1.78R nickel plated profile nipple, 2 3/8" nickel plated on/off tool and 104 jts. Of 2 3/8" IPC tbg. Circulate 85 bbls. Of pkr. Fluid. Set pkr. @ 3374' with 14000# of tension. See additional detail below for tubing and pkr. Remove BOP and NU wellhead. Ran a test chart to 530 psi and held constant for 35 min. Paul Swartz, BLM, called and could not make MIT; rescheduled test for 3/6/14 @ 8 a.m. Richard Inge, OCD will be on location for test.

3/6/14 RU. Pressured up to 550 psi and chart MIT pressure for 30 min. and lost 55 psi. Test was witnessed by Richard Inge, OCD; original chart given to Mr.Inge. Paul Swartz was unable to witness test due to illness. TUBING/PKR. DETAIL:

	6.00′	KB Correction
104	3361.90'	2 3/8" IPC tbg.
1	2.00'	2 3/8" Nickel Plated On-Off Tool
1	.40'	2 3/8" x 1.78R Nickel Plated Profile Nipple
		5 ½" x 2 3/8" IPC Nickel Plated Loc-Set
1	<u>4.00'</u>	Pkr.
	3374.30'	Pkr. set depth

Injection set to start soon.



