

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <b>30-005-62911</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>VB-427</b>
7. Lease Name or Unit Agreement Name <b>Hanlad AKZ State</b>
8. Well Number #2
9. OGRID Number <b>9974</b>
10. Pool name or Wildcat <b>Palma Mesa Wolfcamp Gas</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator  
**Hanson Operating Company, Inc.**

3. Address of Operator  
**PO Box 1515, Roswell, NM 88202-1515**

4. Well Location

Unit Letter **M** : **330** feet from the **South** line and **1225** feet from the **West** line  
Section **13** Township **8 South** Range **27 East** NMPM County **Chaves**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
**3943' GR**

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

08/21/14 MIRU plugging equipment. POH w/ rods and pump. Dug out cellar. NU BOP. POH w/ rods and tbq.

08/22/14 Finished stripping out rods and tbq. RIH w/ gauge ring to 5500'. RIH and set 5 1/2 CIBP @ 5500'.

Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 5500'-5253'. POH w/ tbq.

08/25/14 RIH and set 5 1/2 CIBP @ 2100'. Spotted 25 sx cement @ 2100'-1853'. POH w/ tbq. Pressured tested csg to 500 psi. Perf'd csg @ 1680'. Sqz'd 25 sx cement @ 1680'.

08/26/14 NO TAG. Re-Sqz'd 40 sx cement @ 1680'. WOC. Tagged plug @ 1500'. Perf'd csg @ 400'. Sqz'd 50 sx cement and circulated to surface. WOC. Verified cement at surface. ND BOP. Rigged down and moved off.

Approved for plugging of well bore only.  
Liability under bond is retained pending receipt  
of C-103 (Subsequent Report of Well Plugging)  
which may be found at OCD Web Page under  
Forms, www.emnrd.state.nm.us/oed.

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 03 2014

RECEIVED

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Carol J. Smith TITLE Production Analyst DATE 08/28/2014

Type or print name Carol J. Smith E-mail address: hanson@dfn.com PHONE: 575-622-7330

For State Use Only

APPROVED BY: [Signature] TITLE Dist # Supervisor DATE 9-3-14

Conditions of Approval (if any):

Submit Subsequent C-103