Submit I Copy To Appropriate District	State of New Me	exico	Form C-1	
Submit 1 Copy 10 Appropriate District Office District 1 (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District II (575) 748-1283 811 S. First St., Artesia, NM 88210 ARTES OF ISTRICT ARTES OF ISTRICT		Revised July 18, 20 WELL API NO.	<u> </u>	
District II – (575) 748-1283		30-015-29438		
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 ARTES OF CONSERVATION DIVISION		5. Indicate Type of Lease		
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 SEP 2 9 12224 South St. Francis Dr.		STATE XX FEE		
District IV – 5005 476-3600 Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505	RECEIVED		B-8096	
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA		UG BACK TO A	7. Lease Name or Unit Agreement Name Conoco 7 State	e
PROPOSALS.) 1. Type of Well: Oil Well (Gas Well Other		8. Well Number 20	
2. Name of Operator	Jas Well Other	_	9. OGRID Number	
QUANTUM RESOURCES MGMT	. LLC		243874	
3. Address of Operator			10. Pool name or Wildcat	
1401 MCKINNEY STE. 2400 HOL	JSTON, TX 77010		San Andres	
4. Well Location				
Unit Letter <u>D</u> : 1310 feet from the <u>North</u> line and <u>1080</u> feet from the <u>West</u> line				
Section 07	Township 19S 11. Elevation (Show whether DR	Range 29E	NMPM EDDY County	
	3378 3378	, KK <i>b</i> , K1, GK, eic.)	ung.	
The state of the s			, R 2	
12. Check A	ppropriate Box to Indicate N	lature of Notice, l	Report or Other Data	
•	· ·		•	
NOTICE OF INT PERFORM REMEDIAL WORK ☐		REMEDIAL WORK	SEQUENT REPORT OF: ALTERING CASING	\Box
TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	COMMENCE DRIL	_	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	<u> </u>	_
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM		OTHER R. A.H.	n Astatos	\Box
OTHER: 13 Describe proposed or comple	eted operations (Clearly state all:	OTHER: Pay Add	& Acidize I give pertinent dates, including estimated	<u>⊠</u> date
			appletions: Attach wellbore diagram of	uute
proposed completion or recompletion.				
04/29/14 - MIRU 04/30/14 - PERFORATED THE CASING FROM 2636' TO 2644' WITH 2SPF(16)HOLES, 2658'TO 2664'(12)HOLES & 2686'TO				
2692'(12)HOLES, TOTAL OF 40 HOLES.				
05/01/14 - ACIDIZE WITH 1000GLS. OF ACID @ 1458PSI.AND PUMP 200LBS. OF SALT. BOF 1509PSI.PUMP 1000GLS. OF ACID				
@1251PSI. PUMP 200LBS. OF SALT. BOF 1347PSI. PUMP 1000GLS. OF ACID @1288PSI.PUMP 300LBS. OF SALT. BOF 1540PSI PUMP 1000GLS. OF ACID @1163PSI.PUMP 500LBS. OF SALT BOF 1654PSI. PUMP 1000GLS. OF ACID @1308PSI.PUMP 500LBS				
OF SALTPUMP 1000GLS.OF ACID. BOF @1612PSI.START FLUSH, PUMP 35 BLS. OF 2%KCL.				
05/02/14 - PUMP 1000GLS. OF 15%HCL NFE ACID @324PSI.,PUMP 500LBS. OF SALT. BOF @283.PUMP 1000GLS. OF A @305PSI. PUMP 500LBS OF SALT. BOF @244PSI. PUMP 1000GLS. OF ACID @500PSI.PUMP 750LBS. OF SALT.BOF@185I				
			DOGLS. OF ACID@716PSI.PUMP 35BL	
2%KCL TO FLUSH	2.2/0" TUDING 4.4/0" V.0.2/0" T		0 0 0 0 0 0 0 0 THE THE OFF TAG AND NO	D05
AND NU WELL HEAD.	2-3/8 TUBING, 4-1/2" X 2-3/8" I	AC, AND 63 JUINTS	S OF 2-3/8" TUBING. SET TAC AND ND	BOF
			(101) 3/4" KD RODS, AND 8' OF PONY	ROD
SUBS, AND 22' 1-1/2" POLISH ROD	NU WELL HEAD AND HANG WE	LL ON. WELL HAS I	BEEN RETURNED TO PRODUCTION.	
Spud Data: 04/29/14		05/06/14		
Spud Date:	Rig Release D	ate: 05/06/14		
		<u> </u>	,	
			11 11 0	
I hereby certify that the information a	bove is true and complete to the b	est of my knowledge	e and belief.	
210 1	2			
SIGNATURE Molanda P.	TITLE Regul	atory Manager	DATE <u>09/25/14</u>	
/	X	3	DHONE. 712 (24 4/0/	
Type or print name <u>Yolanda Perez</u> For State Use Only	E-mail address: _yperez(ayqracq.com	PHONE: <u>713-634-4696</u>	
A)				
APPROVED BY:	TITLE /)い	El Sycusion	DATE 10/8/14	
Conditions of Approval (if any):		•	·· ,	