Form 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCD Artesia SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side.					FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM0467933 6. If Indian. Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or N											
								1. Type of Well 🔲 Gas Well 🔲 Other					8. Well Name and No DALE H. PARKE	8. Well Name and No. DALE H. PARKE B TRACT C 13		
								2. Name of Operator 'PREMIER OIL & GAS, INC. Contact: DANIEL A JONES E-Mail: dan.jones@premieroilgas.com					9. API Well No. 30-015-32380			
								3a. Address PO BOX 1246 ARTESIA, NM 88211-1246	3b. Phone No. (include area code) Ph: 972-470-0228			10. Field and Pool, or Exploratory LOCO HILLS; GLORIETA-YESO				
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description	n) .			11. County or Parish	, and State										
Sec 15 T17S R30E Mer NMP NESE 2310FNL 990FEL					EDDY COUNTY, NM											
12. CHECK API	PROPRIATE BOX(ES) T	O INDICATE	NATURE OF I	NOTICE,	REPORT, OR OTHE	R DATA										
TYPE OF SUBMISSION		TYPE OF ACTION														
□ Notice of Intent	Acidize	🔀 Dee	🔀 Deepen		□ Production (Start/Resume)		UWater Shut-O									
-	Alter Casing		Fracture Treat		Reclamation		Well Integrity									
🛛 Subsequent Report	Casing Repair	·		Recomplete Other												
Final Abandonment Notice	Change Plans Convert to Injection				orarily Abandon Disposal											
Attach the Bond under which the w following completion of the involve testing has been completed. Final / determined that the site is ready for 5/14-15/2014 - POOH with tu cem retainer @ 4440'. Test b	ed operations. If the operation re bandonment Notices shall be fi final inspection.) Jbing and rods. Prep to sq	esults in a multipl led only after all i ueeze Paddoo	e completion or reco equirements, includ	ompletion in ling reclamat	a new interval, a Form 31, ion, have been completed,	50-4 shall be fi and the operat	iled once tor has $\hat{i}/1Y$									
5/16/2014 - Sqz paddock pei	rfs from 4492 - 4824 (20) v		Class C + 2% Ca	aCL2 + 40	0 sks	NMOCE) :eva									
class C Neat. Circ 52 bbls to 5/19/2014 - RU closed loop	weld auto driller to pulling	g unit + rig up	reverse rig. TIH	w/ rock	NM O	L CONSE										
bit + 6 drill collars + 2-7/8" dr 5/30/2014 - TD 4-3/4" hole to	- .	ement retainei	.			DEC 18	2014									
6/3/2014 - Ran 155 its (includ	des 9.6? shoe jt) of 4? (L8	0) 10.46 lb/ft L	TC casing, 6 ce	entralizers,	۰ ۲	RECEI	VED									
14. I hereby certify that the foregoing	is true and correct. Electronic Submission #	265681 verifie	by the BLM We	liInformati	on,Şystem, FOD											
Name(<i>Printed/Typed</i>) DANIEL	Electronic Submission # For PREMIE Committed to AFMSS	R OIL & GAS, for processing		Qanisbati AM GAJ 2/1 FESIDEN		RECOR	Ŭ									
Signature (Electronic	Submission)		Date 09/24/2		DEC 1 5 20											
	THIS SPACE FO	DR FEDERA					-									
				BUE	REAU OF LAND MAN											
Approved By			Title		CARESBAD FIELD O	FICE Date										
Conditions of approval, if any, are attach pertify that the applicant holds legal or ec which would entitle the applicant to cond	uitable title to those rights in the		Office	L												
	USC Section 1212 make it a	crime for any ne	son knowingly and	willfully to r	make to any department or	agency of the	United									
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	statements or representations as	to any matter wi	thin its jurisdiction.	winnung to i		0 9										

.

Additional data for EC transaction #265681 that would not fit on the form

32. Additional remarks, continued

DV Tool, Float shoe and collar to 6233?. DV Tool set @ 4877.94?. 121 jts above DV Tool. CMT casing and circulate @ DV Tool with 100 sx Class ?C?. Circ 45 sx to pit. WOC.

7/11/14 ? Install 10k companion flange, 10k frac valve and 10k goathead. RU and spot 1000 gal 7.5% HCL and load hole with fresh water. RIH w/wireline and perf Yeso 1 5682 ? 6011? (21).RU wireline and run a cement bond log.

7/17/14 ? Acdize w/3000 gal. Frac Yeso 3 (5570 ? 5947?) w/11,900 bbls of slickwater carrying 187,068# of sand.

7/8/2014 ? RIH w/ seating nipple @ 5955?, 44 jts 2-3/8? tubing (1430.01?), change over collar, 2 jts 2-7/8?, TA @ 4553.71?, 139 jts 2-7/8? (4537? w/ TA). RIH w/ 20? Quin pump w/ sandscreen, 4 ? 1-1/4? Kbars, 56 ?? rods, 178 7/8? rods, 1 ? 6? 7/8? rod sub, 26? polished rod. Load hole with 18 bbls of water. Hang well and begin pumping.

7/24/2014 - Clean out to 6220'

7/29/14 ? Pull 121 Jts 4? casing 4879? to liner. Go in hole 2-7/8? seating nipple, 1 jt, TAC, 150 jts 4862?, 20? Quinn frac pump, 12 1-1/2? k-bars, 181 7/8? rods, 1 ? 4? 7/8? rod sub, 26? polish rod, 11 bbls to load. Hang well on and begin pumping.