
	•		1			·		
	A				• *	• •		
35		ARTESIA DI	-	ION				
Form 3160-5 March 2012) DE	UNITED STATES PARTMENT OF THE INTERIOR			FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014				
	REAU OF LAND MANAGEMENT	NAGEMENT		5. Lease Serial No. NMNM 08277				
Do not use this	NOTICES AND REPORTS ON V form for proposals to drill or to Use Form 3160-3 (APD) for su	o re-enter an	/ED 6	. If Indian, Allot	tee or Tribe	Name		
SUBM	IT IN TRIPLICATE – Other instructions o	on nage 2	7	. If Unit of CA/A	greement, N	Jame and/or No.	· · · · · ·	
Type of Well		·····		Well Name and	No			
Oil Well Gas Well Other				Saladár Federal #5				
MNA Energy, LTD Co.,				9. API Well No. 30-015-02444				
a. Address 3b. Phone No. (include area code) 06 W Alabama, Hobbs, NM 88242 575 392 2702				10. Field and Pool or Exploratory Area Saladar: Yates				
Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 50 FSL & 1650 FWL, Sec 33, T20S, R28E				11. County or Parish, State Eddy				
12. CHE	CK THE APPROPRIATE BOX(ES) TO INE	DICATE NATURE O	F NOTICE	, REPORT OR (THER DA	ГА Г		
TYPE OF SUBMISSION		ТҮРЕ	OF ACTIC	Ņ		· · · · · · · · · · · · · · · · · · ·		
Notice of Intent	Acidize Deep	pen	Product	tion (Start/Resum		Water Shut-Off Well Integrity		
Subsequent Report.		Construction	Recom	·		Other		
Final Abandonment Notice	Change Plans Plug Convert to Injection Plug	and Abandon Back		rarily Abandon Disposal			· · · · · · · · · · · · · · · · · · ·	
testing has been completed. Final Abandonment Notices must be filed only after all requirements, in determined that the site is ready for final inspection.) his well was plugged as follows: 2/18/14: POH w/ rods. Pump 20 bbls of water down backside with no pressure. POH w/ tubi			ADD 1/14/2015					
			ng .		Ť	60614		
2/23/14: RIH w/ tubing to 620'. Po 620', lost returns after pumping a	eld on 5 1/2" collar and install swage and ump water down tubing and establish circ upproximately 35 sx. and POH. WOC 3.5 ump 75 sack Class C neat plug, SDFN.	culation around ins						
2/24/14: RIH and tag plug @ 77'. nnulus from 77' to surface.	Pump water and establish circulation ins	side and outside of	5 1/2" cas	ing. Pump 25	sacks of Cl	ass C neat to fill c	casing and	
er this well is plugged, a dry hole r	narker will be installed and the location c	cleared of junk then	remediate			۰		
See wellbore diagram attached			Accepted as to plugging of the well bore. Liability under bond is retained until					
				. Surface re	storation	is completed.		
helps White	rue and correct. Name (Printed/Typed)	Title Consultant		[
Similars		Date 12/24/2014		ACCI	PTED	FOR RE	CORD	
Signature	THIS SPACE FOR FEDE		E OFFI	CEUSE]	
pproved by					TDEC	3 0 2014		
udiina of annoval if any ara attacha	d Approval of this paties does not up rout be:	Title			Date	Into		
	d. Approval of this notice does not warrant or c title to those rights in the subject lease which we thereon.			BUF	READ OF	AND MANAGE	MENT	
	U.S.C. Section 1212, make it a crime for any personnance of the section of the se		villfully to n	nake to any depart	nient or ager	cy of the United Sta	ttes any false	
nstructions on page 2)	semanons as to any matter within its jurisdictio	///. 	·					
						•		
· · · ·								
			1					

. . .

MNA Enterprises, LTD Co.



Well Bore Diagram

 Well:
 Salador Federal #5

 API #
 30-015-02444

Plugged12/24/14: 55 sx Class C neat from 320 to 620' 75 sx Class C neat from 77 to 320' 25 sx Class C neat from Surface to 77'

3 1/2" 9.3# J-55 and packer @ 550', cement circulated

5 1/2" @ 590', cmt circulated Open Hole shot w/ Nitro

TD 668