Form 3160-5 (April 2004)	2004) UNITED STATES ARTESTA				FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENTMAR 0 2 2015				5. Lease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to reference an abandoned well. Use Form 3160-3 (APD) for such proposals.				NMNM105342 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. Travis Bassett Birney	
1. Type of Well Oil Well Gas Well Gas Well Other				8. Weil Nam	
2. Name of Operator NADEL AND GUSSMAN HEYCO, LLC				Travis E	assett-Birney #1
3a. Address 3b. Phone No. (include area code) PO BOX 1936 ~ ROSWELL NM 88202-1936 575.623.6601				9. API Well No. 3001522370	
PO BOX 1936 ~ ROSWELL NVI 88202-1936 5/5.023.0601 4. Location of Well (Footage, Sec., T., R, M, or Survey Description) 5/5.023.0601				10. Field and Pool, or Exploratory Area Empire; Strawn	
1980' FSL & 1980' FEL, Sec. 7 NWSE , T18S, R29E				11. County or Parish, State Eddy, New Mexico	
12 CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATURI	E OF NOTICE.	REPORT. OR	OTHER DATA
TYPE OF SUBMISSION					
If the proposal is to deepen dir Attach the Bond under which following completion of the in testing has been completed. F determined that the site is read This is a notification of C Harvey E. Yates Compan	ectionally or recomplete horizontal the work will be performed or prov volved operations. If the operation inal Abandonment Notices shall be y for final inspection.) hange of Operator on the abov my, as new operator, accept all r portion of lease described. 317	ty, give subsurface location ide the Bond No. on file w results in a multiple compl filed only after all requiren re referenced well.	is and measured and t ith BLM/BIA. Requisition or recompletion nents, including reclain tions, stipulations a SEE	Abandon any proposed wor rue vertical depth irred subsequent re in a new interval mation, have beer and restrictions	, a Form 3160-4 shall be filed once a completed, and the operator has
14. I hereby certify that the for Name (Printed/Typed) Tammy R. Lint Signature	RZik	Date	roduction Tech	APPR 09/10/2014	OVED
	THIS SPACE FOR	FEDERAL OR S	IAIEUFFIC		2 3/2015
Approved by Conditions of approval, if any, are certify that the applicant holds leg which would entitle the applicant of Title 18 U.S.C. Section 1001 and Ti States any false, fictitious or fraudu	al or equitable title to those rights to conduct operations thereon. tle 43 U.S.C. Section 1212, make it	does not warrant or in the subject lease	ffice owingly and willfull	CARLSB	FIELD OFFICE

-

(Instructions on page 2)

٤ `

BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE 620 E. Greene St Carlsbad, NM 88220 Ph: (575) 234-5972

Conditions of Approval for Change of Operator

- 1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.
- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
- 10. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
- 11. If not in place acquire operating rights on this lease within 30 days with BLM office in Santa Fe, NM.