## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

		<b>,</b> .					
Form 3160-5 (August 2007)	UNITED STATE DEPARTMENT OF THE BUREAU OF LAND MANA			FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010			
SUNE		5. Lease Serial No. NMLC066445					
Do not us		6. If Indian, Allottee or Tribe Name					
abandone	d well. Use form 3160-3 (AF	PD) for such proposals.		o. II indian, i iiida	. moorame		
SUBMIT IN		7. If Unit or CA/Agreement, Name and/or No.					
1. Type of Well				8. Well Name and No.			
		CARIE A STOKER		FED J EMPIRE 3	·		
Name of Operator     ALAMO PERMIAN RESC		9. API Well No. 30-015-00169-00-S1					
3a. Address 415 WEST WALL STREI MIDLAND, TX 79701	ET SUITE 500	3b. Phone No. (include area code Ph: 432-897-0673 Fx: 432-686-8454	<b>;</b> )	10. Field and Pool, or RED LAKE	Exploratory		
4. Location of Well (Footage,	ec.; T., R., M., or Survey Description	n)		11. County or Parish, and State			
Sec 1 T18S R26E SENE		EDDY COUNTY, NM					
					·		
12. CHECK	APPROPRIATE BOX(ES) T	O INDICATE NATURE OF	NOTICE, RE	EPORT, OR OTHE	R DATA		
TYPE OF SUBMISSION		TYPE OF ACTION					
☐ Notice of Intent	☐ Acidize	☐ Deepen	☑ Production (Start/Resume)		☐ Water Shut-Off		
_	☐ Alter Casing	☐ Fracture Treat	□ Reclama	ation	■ Well Integrity		
Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete		Other		
☐ Final Abandonment Notice	ce Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon				
	Convert to Injection	☐ Plug Back	□ Water Disposal				
If the proposal is to deepen dire Attach the Bond under which the following completion of the inv	ctionally or recomplete horizontally the work will be performed or provide tolved operations. If the operation re that Abandonment Notices shall be fi	ent details, including estimated starting, give subsurface locations and mease the Bond No. on file with BLM/BL esults in a multiple completion or recled only after all requirements, included	ured and true ve A. Required sub completion in a n	rtical depths of all pertir sequent reports shall be ew interval, a Form 316	nent markers and zones. filed within 30 days 10-4 shall be filed once		
2/10/14 MIRU PU; UNHANG WE 1786'; SWI; SDFN	.L & UNSEAT PUMP; POOH	W/ PUMP; ND WH, NU BOP	; TAG FILL &	POOH W/TBG; FIL	LL AT		
2/12/14 MIRU TUBING TESTERS	; TEST TBG TO 5000 PSI BI	ELOW SLIPS; RD TESTERS;	ND BOP, NU	J WH; RIH W/ PUM	P & .		

2/12/14 MIRU TUBING TESTERS; TEST TBG TO 5000 PSI BELOW SLIPS; RD TESTERS; ND BOP, NU WH; RIH W/ PUMP & RODS; HWO & LOAD TBG W/5BBLS FW; COULD NOT GET WELL TO PUMP; UNSEAT PUMP & FLUSHED TBG; SEAT PUMP & LONG STROKE WELL; NO PUMP ACTION; PUMP 15 BBLS WTR DWN CSG, NO PUMP ACTION; UNHANG WELL; POOH W/ PUMP; SWI; SDFN

NM OIL CONSERVATIO

RIH W/ NEW PUMP; HWO & PRESSURE TBG TO 200 PSI; PUMP QUIT WORKING AFTER 10 MIN; TAG BTM &

ARTESIA DISTRICT

MAR **3 0** 2015

14. I hereby certify that t	he foregoing is true and correct.  Electronic Submission #236  For ALAMO PERMIA  Committed to AFMSS for process	N RESOURCES LL	C. sent to the Ca	arlsbad		ECEIV	ΈD		
Name (Printed/Typed)	CARIE A STOKER	Title	REGULATOR	Y AFFAIRS CO	ORDINATOR				
Signature	(Electronic Submission)	Date	02/20/2014	ACCEPT	ED FOR REC	ORD			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved By		Title	· .	M	AR 25 2015 Chris Walls	<u>.</u>			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				BUREAU CARI	OF LAND MANAGEM SBAD FIELD OFFICE	ENT			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## Additional data for EC transaction #236189 that would not fit on the form

## 32. Additional remarks, continued

RE-PRESSURED TBG; SHOT FLUID LEVEL; FLUID AT 400' ABOVE PERFS; UNSEAT & PUMP 10BBLS FW DWN TBG; RESEAT PUMP & TRY TO PRESSURE TBG; PUMPED 15 BBLS DWN CSG; COULD NOT GET WELL TO PUMP; UNSEAT PUMP & POOH; PUMP FULL OF FRAC SAND & SCALE; R&R PUMP; UNSET TAC & PUH 1 JNT; RESET TAC & NU WH; RIH W/ PUMP; HWO

2/17/14
MIRU PU; UNHANG WELL & POOH W PUMP & RODS; ND WH; RIH TO 1787'; PACKED OFF WH; CIRC 110 BBLS FW W/
15% RETURNS; LAST 5 BBLS WTR STARTED COMING UP AROUND CSG; UNPACKED WH & LAY DWN 2 JNTS; EOT @
1703'; RIH W PUMP & RODS; LOADED TBG W 4 BBLS; PRESSURED PUMP TO 500 PSI; BLED OFF PRESSURE &
PRESSURED PUMP TO 500 PSI; RDMO; WELL PUMPING