Form 3160-5 (August 2007)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

**OCD** Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

	Expires:	July	3
Lease S	Serial No.		

SUNDRY N	OTICES AND	) REPORTS	ON WELLS	3
Do not use this	form for prop	osals to drill	or to re-ente	r an
abandoned well.	Use form 316	60-3 (APD) fo	r such propo	sals

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.  SUBMIT IN TRIPLICATE - Other instructions on reverse side.  1. Type of Well  Gas Well  Gas Well  Other	If Indian, Allottee or Tribe Name     If Unit or CA/Agreement, Name and/or No. 891005247F	
1. Type of Well  Gas Well Cther	891005247F	
☑ Oil Well ☐ Gas Well ☐ Other		
	8. Well Name and No. COTTON DRAW UNIT 153H	
Name of Operator Contact: SARA COOK     DEVON ENERGY PRODUCTION CO EPMail: sara.cook@dvn.com	9. API Well No. 30-015-38535-00-S1	
3a. Address 333 WEST SHERIDAN AVE OKLAHOMA CITY, OK 73102  OKLAHOMA CITY, OK 73102	10. Field and Pool, or Exploratory COTTON DRAW	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish, and State	
Sec 3 T25S R31E NWNE 200FNL 1980FEL	EDDY COUNTY, NM	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, I	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION TYPE OF ACTION		
Notice of Intent ☐ Acidize ☐ Deepen ☐ Produ	action (Start/Resume)	
☐ Alter Casing ☐ Fracture Treat ☐ Reclaim	mation	
☐ Subsequent Report ☐ Casing Repair ☐ New Construction ☐ Recor	mplete 🛭 Other	
☐ Final Abandonment Notice ☐ Change Plans ☐ Plug and Abandon ☐ Temp	orarily Abandon .	
☐ Convert to Injection ☐ Plug Back ☐ Water	r Disposal	
Devon Energy Production Company, LP respectfully requests to flare the Cotton Draw Unit 153 Central Tank Battery. Intermittent flaring due to DCP boosters going down. We are requesting days to start March 2, 2015 through June 1, 2015.  Amount to be flared is: 600 BOPD & 600 MCFPD. The following wells are to be included:	NM OIL CONSERVATIO	
Cotton Draw Unit 153H (30-015-38535)	ARTESIA DISTRICT	
Cotton Draw Unit 117H (30-015-38434)  Cotton Draw Unit 154H (30-015-38952)  Cotton Draw Hort 160H (30-015-38432)	ルル: MAR <b>3 0</b> 2015	
Cotton Draw Unit 211H (30-015-41941) Nm Nm7 2928X	RECEIVED	
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #295351 verified by the BLM Well Informatic  For DEVON ENERGY PRODUCTION CO LP, sent to the Hob  Committed to AFMSS for processing by JENNIFER SANCHEZ on 03/23/201	obs 15 (15JAS0001SE)	
Name (Printed/Typed) SARA COOK Title REGULATORY CO	OMPLIANCE ASSOC	
Signature (Electronic Submission) Date 03/18/20/15	PROVED	
THIS SPACE FOR FEDERAL OR STATE OFFICE	S 3 2015	
	the distance of the second	
Approved By		
Approved By  Orditions of approval, if any, are attached. Approval of this notice does not warrant or riffy that the applicant holds legal or equitable title to those rights in the subject lease hich would entitle the applicant to conduct operations thereon.  Title  BUALAU OF  CARLSB	LANY MAYELEMENT AD ELD OFFICE	

## Cotton Draw Unit 153H 30-015-38535 Devon Energy Production Co. March 23, 2015 Conditions of Approval

- 1. Report all volumes on OGOR B as disposition code 08.
- 2. Comply with NTL-4A requirements
- 3. Subject to like approval from NMOCD
- 4. Flared volumes will still require payment of royalties
- 5. Install gas meter on vent/flare line to measure gas prior to venting/flaring operations if it is not equipped as such at this time. Gas meter to meet all requirements for sale meter as Federal Regulations and Onshore Order #5. Include meter serial number on sundry.
- 6. This approval does not authorize any additional surface disturbance.
- 7. Submit updated facility diagram as per Onshore Order #3.
- 8. Approval not to exceed 90 days for date of approval.
- 9. Submit Subsequent Report to this sundry with actual volumes of gas flared monthly on 3160-5 (sundry notice).
- 10. If flaring is still required past 90 days submit new request for approval.
- 11. If a portable unit is used to flare gas it must be monitored at all times.
- 12. Comply with any restrictions or regulations when on State or Fee surface.

032315 JAM