Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NA OUCCONSERVATION
ARTESIA DISTRICT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

DOIGETO OF BITTE WITH TOBITE			
	1 A D	Λ.	
	LAR		, ////
SUNDRY NOTICES AND REPORTS ON WELLS	1 1411	V A	<i>)</i>

5. Lease Serial No. NMI C061705A

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. RECEIVED	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side.	7. If Unit or CA/Agreement, Name and/or No. 891000303E
	8. Well Name and No.

1. Type of Well POKER LAKE UNIT 078 Oil Well Gas Well Other Name of Operator
 BOPCO LP TRACIE J CHERRY API Well No. Contact: E-Mail: tjcherry@basspet.com 30-015-27536 3b. Phone No. (include area code) 10. Field and Pool, or Exploratory 3a. Address Ph: 432-221-7379 POKER LAKE; DELAWARE SW P O BOX 2760 MIDLAND, TX 79702 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, and State Sec 25 T24S R30E NENE 660FNL 660FEL EDDY COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent ☑ Subsequent Report ☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture Treat ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	☐ Water Shut-Off ☐ Well Integrity ☑ Other Venting and/or Flari ng

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BOPCO, LP respectfully submits this sundry notice to report the volume flared for 90-days on the referenced agreement. Wells contributing to the flaring volume are as follows:

Lease number/well/API

NMLC061705B / POKER LAKE UNIT 100 / 30-015-27961-00-S1 NMLC061705B / POKER LAKE UNIT 103 / 30-015-27919-00-S1 State - E2206 / POKER LAKE UNIT 105 / 30-015-27895-00-S1 NMLC061705B / POKER LAKE UNIT 106 / 30-015-27920-00-S1 NMNM0157779 / POKER LAKE UNIT 108 / 30-015-28086-00-S1 NMNM0157779 / POKER LAKE UNIT 111 / 30-015-28087-00-S1 State - B10685 / POKER LAKE UNIT 114 / 30-015-28102-00-S1

Acepted for record

14. I hereby certify that	the foregoing is true and correct. Electronic Submission #222915 verifie For BOPCO LP, so Committed to AFMSS for processing	nt to th	the Carlsbad		
Name (Printed/Typed)	TRACIE J CHERRY	Title	REGULATORY ANALYST		
Signature	(Electronic Submission)	Date	ACCEPTED FOR RECORD		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By		Title	e // FEB ZO ZUD		
Conditions of approval, if a certify that the applicant ho	ny, are attached. Approval of this notice does not warrant or ids legal or equitable title to those rights in the subject lease plicant to conduct operations thereon.	Office	BUREAU OF LAND MANAGEMENT CARYSBAD FIELD OFFICE		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #222915 that would not fit on the form

32. Additional remarks, continued

STATE - B10685 / POKER LAKE UNIT 115 / 30-015-28180-00-S1 NMLC061705A / POKER LAKE UNIT 118 / 30-015-29213-00-S1 NMLC061705A / POKER LAKE UNIT 78 / 30-015-27536-00-S1 NMLC061705A / POKER LAKE UNIT 80 / 30-015-27537-00-S1 NMNM030453 / POKER LAKE UNIT 82 30-015-27752-00-S1 NMNM0506A / POKER LAKE UNIT 83 / 30-015-27753-00-S1 STATE NMB10685 / POKER LAKE UNIT 84 / 30-015-29103-00-S1 NMLC061705B / POKER LAKE UNIT 85 / 30-015-27911-00-S1 NMLC061705B / POKER LAKE UNIT 86 / 30-015-27911-00-S1 NMLC061705B / POKER LAKE UNIT 87 / 30-015-27986-00-S1 NMLC061705B / POKER LAKE UNIT 89 / 30-015-27787-00-S1 NMNM030453 / POKER LAKE UNIT 92 / 30-015-27797-00-S1 NMNM030453 / POKER LAKE UNIT 93 / 30-015-27798-00-S1 NMNM030453 / POKER LAKE UNIT 93 / 30-015-32823-00-S1 NMNM025533 / POKER LAKE UNIT 99 / 30-015-32823-00-S1

Intermittent flaring was necessary due to restricted pipeline capacity at respective sales points.

4134 MCF was flared for the period Sept-Nov 2012