

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1201 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87400
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form O-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

| | | |
|--|----------------------------|---------------------------------|
| Name of Company Devon Energy | Contact Tracy Kidd | |
| Address P. O. Box 250 Artesia, NM 88211 | Telephone No. 575-513-0628 | |
| Facility Name: Snapping 10 Federal 1H | Facility Type Oil Well | |
| Surface Owner | Mineral Owner | API #: 30-015-37899 2RP-1975 |

LOCATION OF RELEASE

| | | | | | | | | |
|----------------|------------|--------------|-----------|--------------------|------------------------|---------------------|---------------------|-------------|
| Unit: Letter B | Section 10 | Township 26S | Range 31E | Feet from the 330' | North/South Line North | Feet from the 1980' | East/West Line East | County HNDY |
|----------------|------------|--------------|-----------|--------------------|------------------------|---------------------|---------------------|-------------|

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release: Mix Fluids | Volume of Release: 10 bbls | Volume Recovered: 0 bbls |
| Source of Release: Poly line leak | Date and Hour of Occurrence 9/29/13, 3:00 AM | Date and Hour of Discovery 9/29/13, 3:00 AM |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? OCD/Mike Bratcher & BLM/Jeffery Robertson | |
| By Whom? Aaron Kidd | Date and Hour: 10/1/13, 8:45 AM | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*



N/A

Describe Cause of Problem and Remedial Action Taken.* A poly line leaked causing a release of 10 barrels of mixed fluids. No fluids were recovered. The line was isolated, replaced and put back into service.

Describe Area Affected and Cleanup Action Taken.* Teton T. PR was contractor for the correction of this release. The impacted area from this release was excavated to a depth of 2.5 feet deep and analytical testing was completed. The excavation was backfilled to grade using new material, contoured to match the surrounding location and seeded on February 11, 2014 using BLM seed mix #2.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

| | | |
|--|---|-----------------------------------|
| Signature:  | Approved by District Supervisor:  | |
| Printed Name: Veronica Tool | | |
| Title: Admin Field Support | Approval Date: 4/22/15 | Expiration Date: |
| Date: 3/3/2014 Phone: 375-748-9933 | Conditions of Approval: | Attached <input type="checkbox"/> |

* Attach Additional Sheets If Necessary

2RP-1975
Final