Approved By

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

			0	ĈÐ A⊨	Property of the Contract of th					
Form 3160-5 (August 2007)				OCD ARRESTS			FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010			
SUNDRY NOTICES AND REPORTS ON WELLS				•		5. Lease Serial No. NMNM54998				
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.					
1. Type of Well ☑ Oil Well ☐ Gas Well ☐	8. Weil Name and No. STATE LINE FED 1									
2. Name of Operator Contact: JODY NOERDLINGER RKI EXPLORATION & PROD LLC E-Mail: JNOERDLINGER@RKIXP.COM						9. API Well No. 30-015-24479-00-S1				
210 PARK AVE SUITE 900 OKLAHOMA CITY, OK 73102			No. (include area code) 996-0577			10. Field and Pool, or Exploratory BRUSHY DRAW				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						11. County or Parish, and State				
Sec 35 T26S R29E NWNW				EDDY CO	UNTY, N	VM ·				
12. CHECK AF	PROPRIATE BOX(ES) T	O INDICATE	NATURE (OF NO	TICE, RE	EPORT, OR O	THER I	DATA		
TYPE OF SUBMISSION	TYPE OF ACTION							•		
Notice of Intent	☐ Acidize	. Dee	eepen . Produc			tion (Start/Resume)			ff	
☐ Subsequent Report	Alter Casing		-			mation				
	. Casing Repair				Recomp		(Other		
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection				-	orarily Abandon Disposal				
13. Describe Proposed or Completed of If the proposal is to deepen directing Attach the Bond under which the following completion of the involvesting has been completed. Final determined that the site is ready for	onally or recomplete horizontally work will be performed or provide red operations. If the operation re Abandonment Notices shall be fil	give subsurface the Bond No. or sults in a multip	locations and m ifile with BLM e completion or	easured /BIA. F recomp	l and true ver Required sub pletion in a n	tical depths of all sequent reports sl ew interval, a For	l pertinent hall be file rm 3160-4 bleted, and	markers and zones. d within 30 days shall be filed once the operator has		
RKI Exploration and Production seeks authorization to temporarily all evaluating the possibility of recompleting or plugging. The last recor 11/2013.				pandon the subject well while ded oil production was			- 000	OIL CONSI	STRIC	
				•	-cet			APR 27	2015	
Per BLM instructions, a plug cement dump bailed on top.	will be set in the wellbore	50' above the	top perf, with	•				050		
Please see the attached we		details.		SE	EE ATT	ACHED F	-0R	RECEIVE	D	
	month period end		23/2015	5 C(TIDNO	IONS OF	APPF	ROVAL		
, 11.1	BJECT TO LIKE			O.	OIYDII			ed for reco	ord.	
	PROVAL BY STAT	E			·	,	V	IMOCD RI	•	
14. I hereby certify that the foregoing		299186 verifie	by the BLM	Well In	formation	System		4/27	715	
Committed to AFMSS for processing by CHRIS Name(Printed/Typed) JODY NOERDLINGER				LS on (04/23/2015	•	E)			
Name (Frinted/Typed) JODY N	OERDLINGER		Title REG	ULAI	ORY ANA	LYSI				
Signature (Electronic	c Submission)		Date 04/2	3/2015	ΔPF	PROVE)			
	THIS SPACE FO	OR FEDERA	L OR STAT	E OF	FICE US	E				
Approved By			Title		APF	2 3 2015		Date		

MANAGEMENT
BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title

Office

RKI Exploration and Production, LLC

Stateline Federal #1 Section 35 T26S R29E Eddy County, NM API No. 30-015-24479

KB - 2,900'GL - 2,890'4/23/15; JLM 13-3/8" 54.5/61/68# J-55 BTC @ 455' 8 5/8" 24/32# K-55 STC @ 2,901' TOC @ surface by calc Se! CIBP @ 43960' 50' PLUG AND w/ Brushy Canyon 4,935'-5,892' OA sx cmt PBTD 6,708' 5½" 17# J-55 STC @ 6,756' TD 6,750'

RKI Exploration and Production, LLC

Stateline Federal #1 Section 35 T26S R29E Eddy County, NM API No. 30-015-24479

API No. 30-015-24479 **CURRENT** KB - 2,900'·GL - 2,890' 1/27/15; JLM 13-3/8" 54.5/61/68# J-55 BTC @ 455' Tubing Top to Btm: 190 jts 2-7/8" 6.5# J-55 EUE Tbg, SN, 4' PS, 1 jt tbg MA, BP. EOMA est @ 6,036', SN @ 6,006', TAC ?? 8 5/8" 24/32# K-55 STC @ 2,901' Rod string top to btm: PR/liner, 80 ct. (2,000') 7/8" Class C rods, 164 ct. (4,100') ¾" Class C, downhole pump. TOC @ surface by calc Tubing anchor @ 4,900' Brushy Canyon 4,935'-5,892' OA PBTD 6,708' 5½" 17# J-55 STC @ 6,756' TD 6,750'

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 6 months ending 10/23/2015 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Stateline Federal #1

- 1. Well is approved to be TA/SI for a period of 6 months or until 10/23/2015
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 10/23/2015