# **NMOCD**

Form 3160-5 (August 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

### Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

	· Expires: Jui
5.	Lease Serial No.
	NIN AN IN ALCOHOLOGO

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

1 410/11 4101	121000		
If Indian	Allottee o	r Tribe Name	

abandoned wei	· · · · · · · · · · · · · · · · · · ·								
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No.								
Type of Well     Gas Well	er			8. Well Name and No. WATERLOO FEDERAL 4					
Name of Operator     MACK ENERGY CORPORAT	Contact: ION E-Mail: jerrys@me	HERRELL		9. API Well No. 30-005-64228-00-X1					
3a. Address P.O. BOX 960 ARTESIA, NM 88211-0960		. (include are 8-1288	a code)	10. Field and Pool, or Exploratory ROUND TANK-SAN ANDRES					
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description	)			11. County or Parish, and State				
Sec 20 T15S R29E SENW 23	10FNL 1650FWL				CHAVES COUNTY, NM				
12. CHECK APP	ROPRIATE BOX(ES) TO	O INDICATE	NATURE	OF NOTICE, R	EPORT, OR OTHE	ER DA	TA		
TYPE OF SUBMISSION			TY	PE OF ACTION					
Notice of Intent	☐ Acidize ·	☐ Dee	pen	☐ Product	ion (Start/Resume)	· 0	Water Shut-Off		
_	☐ Alter Casing	· Frac	ture Treat	☐ Reclam	ation	<b>"</b>	Well Integrity		
☐ Subsequent Report	☐ Casing Repair		Constructi				Other		
☐ Final Abandonment Notice	☐ Change Plans		and Aband		rarily Abandon	Change to Original A PD			
	☐ Convert to Injection	Plug	Back	☐ Water I	Disposal				
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4:shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  Mack Energy proposes to drill and set surface casing using an Auger Rig. BLM will be notified prior to spud of hole and setting/cementing of casing. A 20" hole will be drilled to competent bedrock at 200-220', based on COA. 8 5/8" 32# J-55 ST&C New casing will be set and cemented w/350sx 6.32gl/sx Class C + PF1, yield 1.33, weight 14.8ppg, 100% excess. Casing will be capped and secured, cellar will be fenced. Mack Energy will move in a drilling rig capable of drilling to TD. Work will be done using a closed loop system.									
This will eliminate the conduct	or pipe.	NM OIL			- COI	CONSERVATION			
		t I	GD 6/11/15		· AF	ARTESIA DISTRIC			
Conductor pipe will be set if w	elibore issues are encoul		record		UN 1.0 2015 RECEIVED				
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #	304133 verifie	d by the BL	M Well Information		<del>\L</del>	·		
Co	For MACK ENE mmitted to AFMSS for pro			nt to the Roswell on 06/05/2015 (15	5DRG0091SE)				
	/ SHERRELL	Title PRODUCTION CLERK				•			
Signature (Electronic S	Submission)		Date 06	6/05/2015					
	THIS SPACE FO	OR FEDERA	L OR ST	ATE OFFICE U	SE				
Ammand Dr. DAVID D. CLASS			77.4 55.71				D		
_Approved By _DAVID_R_GLASS	d Approval of this notice days		11116PET	ROLEUM ENGIN	EEK .		Date 06/05/2015		
Conditions of approval, if any, are attache certify that the applicant holds legal or equal which would entitle the applicant to condu-	nitable title to those rights in the operations thereon.	e subject lease	Office Roswell						
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any pe to any matter w	rson knowing ithin its jurisc	gly and willfully to m liction.	ake to any department o	r agency	of the United		

## ROSWELL FIELD OFFICE CONDITIONS OF APPROVAL

OPERATOR'S NAME: Mack Energy Corporation - Sherrell, Jerry

LEASE NO.: NMNM121950

WELL NAME & NO.: WATERLOO FEDERAL - 4

SURFACE HOLE FOOTAGE: [2310] 'F [N] L [1650] 'F [W] L

BOTTOM HOLE FOOTAGE: [2310] 'F [N] L [1650] 'F [W] L

LOCATION: Section 020, T015. S., R 028 E., NMPM

COUNTY: Chaves County, New Mexico

### 1. DRILLING:

#### DRILLING OPERATIONS REQUIREMENTS:

- A. The BLM is to be notified a minimum of 24 hours in advance for a representative to witness:
  - Spudding well,
  - Setting and/or Cementing of all casing strings,
  - BOPE tests.

The Roswell Field Office Engineer on-call phone number is: (575) 627-0205.

- B. A Hydrogen Sulfide (H2S) Drilling Operation Contingency Plan shall be activated prior to drilling into the Queen formation. A copy of the plan shall be posted at the drilling site.
- C. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
- D. Include the API Number assigned to well by NMOCD on the subsequent report of setting the first casing string.
- E. The operator will accurately measure the drilling rate in feet/min to set the base of the usable water protection casing string(s) opposite competent rock. The record of the drilling rate along with the caliper-gamma ray-neutron well log run to surface will be submitted to this office as well as all other logs run on the borehole 30 days from completion.

F. Air, air-mist or fresh water and nontoxic drilling mud shall be used to drill to the base of the usable water protection casing string(s). Any polymers used will be water based and non-toxic.

#### CASING:

- A. Deepest depth of usable water occurs at an approximate depth of 83 feet. The 8-5/8 inch usable water protection casing string(s) shall be set in competent bedrock above the top of the salt between 200 feet and 220 feet.
  - If cement does not circulate to the surface, the Roswell Field Office shall be notified and a temperature survey utilizing an electronic type temperature survey with a surface log readout will be used or a cement bond log shall be run to verify the top of the cement.
  - Wait on cement (WOC) time for a primary cement job will be a minimum 18 hours or 500 pounds compression strength, whichever is greater. (This is to include the lead cement).
  - Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compression strength, whichever is greater.
  - If cement falls back, remedial action will be done prior to drilling out that string.
- B. The minimum required fill of cement behind the 5-1/2 inch production casing is sufficient to circulate to the surface. If cement does not circulate, a temperature survey utilizing an electronic type temperature survey with a surface log readout will be used or a cement bond log shall be run to verify the top of the cement.
- C. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.
- D. All casing shall be new or reconditioned and tested casing and meet API standards for new casing. The use of reconditioned and tested casing shall be subject to approval by the Authorized Officer. Approval will be contingent upon the wall thickness of any casing being verified to be at least 87-1/2 per cent of the nominal wall thickness of new casing.

#### PRESSURE CONTROL:

A. Prior to drilling below the 8-5/8 inch surface casing shoe, the blowout preventer assembly (BOP/BOPE) shall be installed. The BOP/BOPE shall consist of a minimum of One Annular Preventer or Two Ram-Type Preventers and a Kelly Cock/Stabbing Valve.

- B. Before drilling below the 8-5/8 inch surface casing shoe, minimum working pressure of the blowout preventer and related equipment (BOPE) shall be 2000 psi. If operator chooses to use a control device greater than the minimum stand they will have to follow all guidelines as stated within Bureau of Land Management 43 CFR part 3160 and Onshore Oil and Gas Order No. 2 Drilling Operations.
- C. The BOPE shall be installed before drilling below the 8-5/8 inch surface casing shoe and shall be tested as described in Onshore Oil and Gas Order No. 2. Any equipment failing to test satisfactorily shall be repaired or replaced.
  - The BLM Roswell Field Office shall be notified a minimum of 24 hours in advance for a representative to witness the tests.
  - The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug.
  - All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test will be submitted to the BLM Roswell Field Office at 2909 West Second Street, Roswell, New Mexico 88201.
  - Testing fluid must be water or an appropriate clear liquid suitable for sub-freezing temperatures. Use of drilling mud for testing is not permitted since it can mask small leaks.
  - Testing must be done in a safe workman like manner. Hard line connections shall be required.

The requested variance to test the BOPE prior to drilling below the 8-5/8 inch surface casing to the reduced pressure of 2000 psi by a third party is approved.

#### 2. CLOSED LOOP SYSTEMS:

No reserve pit will be used. Steel tanks are required for drilling operations. The operator shall properly dispose of drilling contents at an authorized disposal facility. No open top tanks are permitted.